

AD-A156 748


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
SITE NUMBER 1 DEAD RI (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV JUL 79


1/3

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A156 748

ANDROSCOGGIN RIVER BASIN
BERLIN, NEW HAMPSHIRE

SITE NO.1, DEAD RIVER DAM
NH 00473

STATE NO 24.14

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

DTIC
ELECTE
S JUL 17 1985 D

G



DISTRIBUTION STATEMENT A

Approved for public release
Distribution Unlimited

DTIC FILE COPY

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

JULY 1979

85 06 26 045

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NH 00473	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Site No. 1 Dead River Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE July 1979
		13. NUMBER OF PAGES 103
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Androscoggin River Basin Berlin, New Hampshire Jericho Brook		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam has a hydraulic height of 46.5 ft and is 3035 ft. long. The dam is good condition with a few minor concerns which need attention. It is intermediate in size with a high hazard potential. A major breach at normal or recreation pool level could result in the loss of 10 or more lives and excessive property damage.		

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED

JAN 16 1980

Honorable Hugh J. Gallen
Governor of the State of New Hampshire
State House
Concord, New Hampshire 03301

Dear Governor Gallen:

Inclosed is a copy of the Site No. 1, Dead River Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Water Resources Board, the cooperating agency for the State of New Hampshire. In addition, a copy of the report has also been furnished the owner, City of Berlin, Berlin, New Hampshire 03570.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Water Resources Board for your cooperation in carrying out this program.

Sincerely,

Max B. Scheider

MAX B. SCHEIDER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT

Identification No.: NH00473
Name of Dam: Site No. 1, Dead River
City: Berlin
County and State: Coos County, New Hampshire
Stream: Jericho Brook
Date of Inspection: June 7, 1979

BRIEF ASSESSMENT

Site No. 1, Dead River Dam (the Project) has a hydraulic height of 46.5 feet, is 16 feet wide at its crest, and is 3,035 feet long. It is a zoned compacted earth embankment with a 100-foot wide grass covered earthen emergency spillway. The dam spans a reach of Jericho Brook, and is located in northeastern New Hampshire approximately 4 miles northwest to the City of Berlin. Maximum storage capacity is about 4,720 acre-feet. The Project is a dual-purpose structure, providing recreation and flood control. The pond (Jericho Lake) is approximately 3,700 feet in length with a normal surface area of about 132 acres.

The dam is in good condition. Minor concerns are: extensive vehicular trespassing on the crest, the upstream slope, the downstream slope, and the area immediately downstream of the toe of the dam is destroying the grassy ground cover and leaving ruts in the ground surface. Two minor seepages near the outlet of the principal spillway discharge pipe and the two corrugated metal underdrain pipes; and one seepage approximately 300 feet south of the bend in the dam and 100 feet downstream from the toe of the dam.

Based on an intermediate size and a high hazard classification in accordance with Corps guidelines, the test flood is the Probable Maximum Flood (PMF). A test flood inflow of 16,870 cfs was routed, resulting in a test flood outflow of 7,975 cfs (1,231 csm) would not overtop the dam although the reservoir would rise to elevation 1,370.9 feet MSL, which is 0.1 feet below the top of the dam. The spillway will pass 8,102 cfs or about 102 percent of the test flood. A major breach at normal or recreation pool level could result in the loss of 10 or more lives and excessive property damage.

The owner, City of Berlin, should implement the results of the recommendations and remedial measures given in Sections 7.2 and 7.3 within 2 years after receipt of this Phase I Inspection Report.

Warren A. Guinan
Warren A. Guinan
Project Manager
N.H. P.E. 2339

This Phase I Inspection Report on Site No. 1, Dead River Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Joseph A. McElroy

JOSEPH A. MCELROY, MEMBER
Foundation & Materials Branch
Engineering Division

Carney M. Terzian

CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division

Joseph W. Finegan, Jr.

JOSEPH W. FINEGAN, JR., CHAIRMAN
Chief, Reservoir Control Center
Water Control Branch
Engineering Division

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A/1	24 C/W

APPROVAL RECOMMENDED:

Joe B. Fryar

JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

Title	Page
LETTER OF TRANSMITTAL.....	
BRIEF ASSESSMENT.....	
REVIEW BOARD PAGE.....	
PREFACE.....	iv
TABLE OF CONTENTS.....	v
OVERVIEW PHOTO.....	vi
LOCATION MAP.....	vii

REPORT

Section


1	PROJECT INFORMATION.....	1-1
	1.1 General.....	1-1
	1.2 Description of Project.....	1-1
	1.3 Pertinent Data.....	1-3
2	ENGINEERING DATA.....	2-1
	2.1 Design.....	2-1
	2.2 Construction.....	2-1
	2.3 Operation.....	2-1
	2.4 Evaluation.....	2-2
3	VISUAL INSPECTION.....	3-1
	3.1 Findings.....	3-1
	3.2 Evaluation.....	3-2
4	OPERATIONAL PROCEDURES.....	4-1
	4.1 Procedures.....	4-1
	4.2 Maintenance of Dam.....	4-1
	4.3 Maintenance of Operating Facilities.....	4-1
	4.4 Description of Any Warning System in Effect.....	4-1
	4.5 Evaluation.....	4-1
5	HYDROLOGIC/HYDRAULIC.....	5-1
	5.1 Evaluation of Features.....	5-1
6	STRUCTURAL STABILITY.....	6-1
	6.1 Evaluation of Structural Stability.....	6-1
7	ASSESSMENT, RECOMMENDATIONS & REMEDIAL MEASURES.....	7-1
	7.1 Dam Assessment.....	7-1
	7.2 Recommendations.....	7-1
	7.3 Remedial Measures.....	7-1
	7.4 Alternatives.....	7-2

APPENDICES

	Designation
VISUAL INSPECTION CHECKLIST.....	A
ENGINEERING DATA.....	B
PHOTO-RAPHS.....	C
HYDROLOGIC AND HYDRAULIC COMPUTATIONS.....	D
INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS..	E



Figure 1 - Overview of Site No. 1, Dead River Dam.



Reprinted by permission of the Department of Resources and Economic Development, Concord, N.H. 03301, and the copyright owners, The National Survey, Chester, VT. 0-17-78.

SCALE IN MILES



MAP BASED ON STATE OF NEW HAMPSHIRE
OFFICIAL HIGHWAY MAP.

Anderson-Nichols & Co, Inc.		U.S. ARMY ENGINEER DIV. NEW ENGLAND	
CONCORD		CORPS OF ENGINEERS	
NEW HAMPSHIRE		WALTHAM, MASS.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
SITE NO. 1 DEAD RIVER DAM			
LOCATION MAP			
DEAD RIVER		NEW HAMPSHIRE	
		SCALE: SEE BAR SCALE	
		DATE: JULY 1979	

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT
SITE NO. 1, DEAD RIVER DAM

SECTION 1
PROJECT INFORMATION

1.1 General

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Anderson-Nichols & Company, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire. Authorization and notice to proceed were issued to Anderson-Nichols under a letter of March 22, 1979 from John P. Chandler, Colonel, Corps of Engineers. Contract No. DACW33-79-C-0050 has been assigned by the Corps of Engineers for this work.

b. Purpose

(1) To perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.

(2) To encourage and prepare the States to initiate quickly effective dam safety programs for non-Federal dams.

(3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location. Site No. 1, Dead River Dam, (the Project) is the primary structure in the Soil Conservation Service Dead River Watershed project and is located in the City of Berlin, Coos County, New Hampshire. The project consists of a multiple-purpose dam and an earthen dike. The dike is located on the watershed divide approximately 4,150 feet to the northwest of the dam. The dam, constructed for flood protection and recreation, spans Jericho Brook and creates Jericho Lake. After discharging through the dam, Jericho Brook flows easterly for a distance of approximately 1.75 miles before turning sharply to the southeast. Here, approximately 0.25 miles downstream of its crossing by Route 110, Jericho Brook becomes known as the Dead River, although both names refer to the same watercourse. The Dead River continues to the southeast approximately 3.0 miles to its confluence with the Androscoggin River; for the last 0.5 miles of its course, the Dead River flows through an urbanized area of

Berlin, including the Central Business District. The dam is located on the U.S.G.S. Quadrangle, Mt. Washington, N.H. with coordinates at N 44° 29' 47", W 71° 15' 18". (See Location Map, page vii.)

b. Description of the Dam and Appurtenances. The Project consists of an earthen dam and an earthen dike. The latter is located approximately 4,150 feet to the northwest of the dam. The dam, the primary structure at Site No. 1 is oriented in a north-south direction and has a 60° 30' bend to the southeast located 525 feet south along the dam from the principal outlet structure. The dam, about 3,035 feet long, 46.5 feet high (hydraulic height) and 16 feet wide at its crest consists of: a 2,935-foot long earthen dam embankment, a 100-foot wide grass-covered emergency spillway, which is located between the north end of the dam and the north abutment, a 3.5' x 10.5' two-stage drop-inlet riser, discharging into a 42-inch diameter reinforced concrete conduit extending through the dam and a 30-inch diameter low-level reservoir drain pipe extending into the pond (Jericho Lake) behind the dam.

The dam is a zoned and compacted earthen structure with a cutoff through alluvium, glacial till, and decomposed rock to firm bedrock. The upstream slope of the embankment is inclined at 3H:1V and downstream face has a 2.5H:1V slope. Design plans indicate that two 12-inch diameter perforated corrugated metal pipes are located near the downstream toe of the dam to collect seepage. These pipes drain into the downstream outlet channel in the vicinity of the principal spillway discharge pipe.

The two-stage riser is the principal outlet structure or spillway, consisting of two 2'H x 2.7' W inlets at the lower level and two 1.9'H x 10.5'W inlets at the second level discharging into a 3.5' x 10.5' shaft connected to a 42-inch diameter reinforced concrete pipe. Trash racks prevent debris from entering the inlets causing blockage of the riser shaft or the 42-inch reinforced concrete discharge conduit. The low-level 30-inch reservoir drain pipe from the upstream reservoir pool is connected to the riser shaft at the invert of the 42-inch diameter reinforced concrete conduit, which discharges into a riprapped plunge pool at the downstream toe of the dam. Invert data on all outlets is provided in Section 1.3. The reservoir drain is sealed by a regular sluice-type gate (cast iron disk) which is controlled by a geared hand-crank gate lift mechanism located on the concrete platform on top of the riser. A manhole located on the platform nearby permits entrance into the structure for servicing the principal outlet works and the reservoir drain gate lift mechanism.

The dike is a zoned earthen structure with a cutoff along the centerline of the structure through alluvium, glacial till, and decomposed rock to firm bedrock. The dike embankment is approximately 1,665 feet long, 14 feet high (structural and hydraulic height), 10 feet wide at its crest, and the upstream and downstream slopes are inclined at 3H:1V. Its crest elevation is equal to that of the main dam embankment.

Breach of the dam at normal pool would result in a flood stage of 20.0 feet, 7.0 feet over the roadway, at the Route 110 bridge, 1.4 miles downstream of the dam. It was determined that the breach would result in a stage of about 13.2 feet at the Converse Building (currently closed) on the north side of Route 110, 0.4 miles southeast of the Route 110 crossing of Jericho Brook and approximately 1.8 miles downstream of the dam. At this stage, the Converse Building would be inundated by 3 to 5 feet of water causing extensive property damage. However, the reach further downstream where the Dead River flows through a heavily urbanized area of the City of Berlin, is a far greater hazard area. Previous floods in 1927, 1936, and 1953 caused great property damage in this area. An estimated 70 residential and commercial structures in this area are subject to flood damage. The SCS manuscript Work Plan for Watershed Protection, Flood Prevention, and Recreation, Dead River Watershed (June 1965) discusses at length the Dead River major flooding events. The most devastating flood (1936), with a discharge estimated to have been 2,000 cfs, has a return period (recurrence interval) of approximately 100 years. It was determined that breach of the dam, generating a discharge of approximately 18,200 cfs, would result in a stage of about 21.1 feet at the Main Street bridge which could cause excessive damages and considerable loss of life (10 or more) in the most heavily urbanized area of Berlin. This downstream hazard reach begins approximately 4.0 miles downstream of the dam and 0.75 miles above the confluence of the Dead River with the Androscoggin River.

Breach of the dam at emergency spillway elevation would result in a flood stage of 21.5 feet, about 8.5 feet over the roadway at the Route 114 bridge. The resulting stage at the Converse Building downstream of the bridge was determined to be 17.0 feet, causing a 7 foot inundation of the building. At the Main Street bridge, the breach discharge of 31,700 cfs would result in a stage of about 23 feet.

As a result of this analysis and due to major historical flooding events on the Dead River in the City of Berlin, the dam is considered to be of High Hazard potential. For more detailed information regarding the breach analysis and the SCS Watershed Work Plan see Appendix D.

e. Test Flood Analysis. The dam is classified as being intermediate in size, having a hydraulic height of 46.5 feet and a maximum (top of dam) storage of approximately 4,720 acre-feet. Using the Recommended Guidelines for Safety Inspection of Dams, the test flood was determined to be the Probable Maximum Flood (PMF). The watershed above the dam, determined by the SCS to have an average slope of 685 feet/mile, is classified as being mountainous. From the PMF Peak Flow Rates graph the discharge for a mountainous watershed of 6.48 square miles is 2,130 cubic feet per second per square mile (csm) of drainage area. Thus, the peak inflow into the site is 13,800 cubic feet per second (cfs). However, SCS developed a freeboard hydrograph which generated a higher peak inflow (16,870 cfs or 2,600 csm) which has been considered to be the PMF because of the greater detail employed in the SCS analysis. An outflow of 7,975 cfs or 1,230 csm was determined by the SCS from a routing and has been employed as the test flood. Analysis of the elevation versus discharge curves indicates that the principal and emergency spillways combined are capable of passing the test flood without dam overtopping. A discharge of the test flood magnitude would result in a reservoir pool elevation of 1,370.9 feet MSL, which is 0.1 feet below the top of the dam. The total project capacity is 8,102 cfs which is 102 percent of the test flood discharge.

f. Dam Failure Analysis. The impact of the failure of the dam with the reservoir at recreation or normal pool elevation (principal spillway crest) was assessed using the Guidance for Estimating Downstream Dam Failure Hydrographs issued by the Corps of Engineers. Owing to the capacity of the dam project, it was assumed that assessing the impact of dam failure at top of dam (elevation 1,371.0 feet MSL) would be an unrealistic analysis. Therefore the dam failure analysis with Jericho Lake at normal pool level (1,352.0 feet MSL) and at the crest of the emergency spillway (1,362.0 feet MSL) was assessed. Though analysis of dam failure at normal flow conditions was sufficient to identify the hazard potential, computations for failure at emergency spillway crest were also completed.

It was also unrealistic to assume that the dam's breach width would be 640 feet (0.4 times the dam's length at mid-height) as is suggested in the "Rule of Thumb" Guidance for Estimating Downstream Dam Failure Hydrographs. A breach width of 100 feet has been assumed to be a more realistic value. The analysis covered the downstream reach extending from the dam to the urbanized area of the City of Berlin, approximately 4.0 miles below on the Dead River. Although the dam spans Jericho Brook and creates Jericho Lake, it has been determined from field inspection that the Dead River and Jericho Brook are the same watercourse. Approximately 1.75 miles east of the dam, Jericho Brook turns sharply to the southeast and is renamed the Dead River. The watercourse is known as the Dead River from this point to its confluence with the Androscoggin River 3.0 miles downstream.

SECTION 5
HYDROLOGIC/HYDRAULIC

5.1 Evaluation of Features

a. General. The Project consists of an intermediate height earthen dam and an earthen dike which impounds a reservoir (Jericho Lake) of intermediate size. The total length of the dam embankment is 3,035 feet which includes 100 feet of grass-covered earthen emergency spillway. The top of the dam (1,371.0 feet MSL) is 9.0 feet above the emergency spillway crest and 19.0 feet above the low-stage of the principal spillway. The dike, approximately 4,150 feet west of the dam, on the watershed divide, is an earthen structure 1,665 feet long with a crest elevation of 1,371.0 feet MSL. The normally maintained recreation pool (1,352.0 feet MSL) extends approximately 3,700 feet upstream of the dam; the flood control pool (1,362.0 feet MSL) extends approximately 4,150 feet upstream of the dam to the dike embankment.

SCS has calculated the time required to draw down Jericho Lake, first, from the flood-control pool elevation to the principal spillway crest and, secondly, from the principal spillway crest to the level of the reservoir drain (see Appendix B). A drawdown estimate was calculated assuming no inflow, the two-stage riser was the only discharging outlet, and reservoir pool level initially at the crest of the emergency spillway (1,362.0 feet MSL). An analysis of the drawdown capacity under falling-head conditions determined that it would take 10.1 days to draw down the lake to the level of the principal spillway crest (1,352.0 feet MSL). The second drawdown estimate was calculated assuming an average inflow rate of 10.5 cfs (1.62 csm) into the reservoir, the 30-inch diameter reinforced concrete low-level reservoir drain pipe was open and flowing full, and the reservoir pool level was initially at the crest of the principal spillway. It was determined that it would take 10.8 days to drain Jericho Lake under these condition.

b. Design Data. Detailed hydrologic and hydraulic data for the Project were disclosed (Appendix B). SCS design details give a principal spillway capacity of 302 cfs and an emergency spillway capacity of 7,800 cfs. The as-built plans indicate that the design capacities are representative of as-built conditions.

c. Experience Data. The owner of the dam has indicated that the maximum stage at the damsite occurred when the reservoir pool elevation reached the second-stage outlet of the principal spillway. Flow was estimated to have been 90 cfs.

d. Visual Observation. No evidence of damage to the dam as the result of flood flow was visible at the time of this inspection. The reservoir pool has never reached the dike embankment.

SECTION 4 OPERATIONAL PROCEDURES

4.1 Procedures

Formal operating procedures (see Appendix B, pages B-1 to B-5) have been agreed upon by the Soil Conservation Service, the designer of the Project, and the City of Berlin, the current owner and sponsor of the project. The City is required to inspect all structural works of improvement annually and after every major storm or occurrence of any unusual adverse conditions that affect their operation. However, the only operable outlet structure at the Project, is the 30" low-level reservoir control which allows the pool to be drawn down for cleaning or repairs at the site. The principal and emergency spillways function automatically as the reservoir pool elevation changes. The SCS provides consultative assistance to the City of Berlin for the operation of the structures.

4.2 Maintenance of the Structures

The City of Berlin has been responsible for the maintenance of Site No. 1, Dead River Dam since 1973. As set forth in the Operation and Maintenance Agreement between the City and the SCS, the City must obtain SCS approval of all plans, designs, and specifications for maintenance work involving major repairs "... which include: (1) repairing separated joints, cracks, or breaks in the principal spillway, (2) correcting seepage, (3) replacing significant backfill around structures resulting from major erosion damage, (4) major vegetation due to failure to obtain an adequate vegetative cover, and (5) restoring areas with significant erosion caused by unusual flow in emergency spillways." The City is required to undertake all maintenance that the SCS has determined to be necessary. The SCS will provide the City with consultative assistance in the preparation of plans, designs, and specifications for needed repairs of the structures.

4.3 Maintenance of Operating Facilities

The City of Berlin is required to inspect all structural works annually and after every major storm or occurrences of any unusual adverse conditions that affect their operation.

4.4 Description of Any Warning System in Effect

No written warning system for the Project was disclosed.

4.5 Evaluation

Minor maintenance is good; however, extensive trespassing by vehicles on the crest, upstream and downstream slopes, and the area immediately downstream of the toe requires attention. The dike is not as well maintained as the main dam.

Extensive trespassing by vehicles on the crest, the upstream slope, the downstream slope, and the area immediately downstream of the toe of the dam is destroying the grassy ground cover and leaving ruts in the ground surface. If the trespassing is not controlled, it may lead to serious erosion and seepage problems.

Two minor seepages near the outlets of the spillway pipe and the corrugated metal pipe underdrains may be indicative of a problem. The seepage that is located more than 100 feet downstream of the toe of the dam may or may not be associated with flow from reservoir, and therefore may not be indicative of a problem and presents no problem to discharge.

The saplings growing on the slopes of the dike could pose a long-term problem if allowed to grow into trees.

to the top of the concrete slab. Inside dimensions of the box are 10.5 feet long by 3.5 feet wide. Two 2.7-foot wide by 2-foot high lower inlets are cast into the ends of the riser section 6.4 feet below the top slab and the two higher-level spillway inlets have a crest 4.0 feet above the crest of the lower inlets. The higher-level inlets are 10.5 feet long and are 1.9 feet high. All spillway openings in the riser are protected with steel trash gate openings to contain floating debris. All visible portions of the concrete riser appear to be in very good condition with no signs of deterioration or corrosion. The outlet end of the 42-inch diameter outlet pipe (see Appendix C - Figures 8 and 9) is reinforced concrete also observed to be in very good condition. The outlet ends of the corrugated metal toe drains discharging to the spillway outlet pipe from downstream face are in good condition.

The emergency spillway (see Appendix C - Figure 15) is an open channel about 100 feet wide at the bottom and with a 1H:1V side slope of exposed rock and 4H:1V side slope of earth embankment to the north and a 4H:1V side slope of earth embankment to the south. The channel bottom appears to be mostly glacial till. Several of the rock exposures in the channel appear to be bedrock, while others are large boulders.

d. Dike. The dike (see Appendix C - Figures 16 and 17) is located on the drainage divide along the west side of the reservoir. The dike is about 1,665 feet long, 14 feet high, and 10 feet wide at the crest. The reservoir elevation at the time of the inspection was well below the upstream toe of the dike. The crest of the dike is covered with grass and has an elevation equal to that of the dam embankment crest. The upstream and downstream slopes of the dike are inclined at 3H:1V. Both slopes are covered with grass and some brush and saplings are beginning to grow on the slopes. Some swampy areas near the downstream toe of the dike are obviously the result of a high natural water table and are not the result of seepage from the reservoir.

e. Reservoir Area. The watershed (see Appendix C - Figure 18) above the reservoir is rolling and heavily wooded. A bathing beach, bathhouse, and boat ramp are located on the north shore of the reservoir; no other structures exist on the shores of the lake. No evidence of significant sedimentation was observed.

f. Downstream Channel. The spillway outlet conduit (see Appendix C - Figure 19) discharges into a riprap-lined plunge pool. Riprap extends in the downstream channel for a distance of about 75 feet from the outlet conduit. Beyond that point are trees and brush growing adjacent to the channel. Downstream from the emergency spillway are trees and brush growing in that channel and presents no problem to discharge.

3.2 Evaluation

Based on the visual inspection, the Project is in good condition.

SECTION 3 VISUAL INSPECTION

3.1 Findings

a. General. The Project consists of a dam of intermediate height which impounds a reservoir of intermediate size and a dike 4,150 feet to the northwest of the dam. The watershed above the reservoir is rolling and heavily wooded. The downstream area is rolling and partially wooded.

b. Dam. The Project is an earthen embankment about 46.5 feet high (hydraulic and structural height), 2,935 feet long, and 16 feet wide at the crest. (See Appendix C - Figures 2, 3, and 4.) A sand-and-gravel roadway, completely bare of vegetation, runs along the crest of the dam. The upstream slope of the embankment is inclined at 3H:1V and is covered with grass which is kept mowed. Riprap extends from an elevation about 3 feet above the reservoir level at the time of the inspection to an elevation about 15' below dam embankment crest. The riprap was in good condition. Near the south abutment there are some ruts (see Appendix C - Figures 5 and 6) where a vehicle was apparently driven on the upstream slope during wet weather. The downstream slope is also covered with grass which is kept mowed. Ruts are at many locations on the downstream slope where vehicles have apparently been driven during wet weather. There are also many ruts (see Appendix C - Figure 7) in the relatively flat grassy area immediately downstream of the dam. Two corrugated metal drain pipes (see Appendix C - Figures 8 and 9) discharge at the downstream toe, one on either side of the spillway outlet pipe. Water was flowing from both drain pipes at the time of the inspection. Two minor seepage areas are located on the south side of the spillway outlet pipe. One seepage (see Appendix C - Figure 10) was observed approximately 300 feet south of the bend in the dam and 100 feet downstream from the toe of the dam. It is not known whether this seepage is coming from the reservoir or whether it is natural spring. The north end of the dam is an earthen slope (see Appendix C - Figures 11, 12, and 13) which serves as part of the south bank of the emergency spillway channel. Vehicles have been driven up two paths on this slope, destroying the vegetation and leaving the end of the embankment susceptible to erosion.

c. Appurtenant Structures. A concrete outlet structure (see Appendix C - Figure 14) is located near the center of the dam. This structure serves as a low-level outlet, and two-stage principal spillway, all constructed in one vertical riser. The reservoir drain outlet is a gated 30-inch diameter pipe located at the base of the riser. The mechanical gate operating mechanism mounted on the top of the riser appeared to be well maintained and in good condition. The concrete riser section is 20 feet high from base to the crest of the higher-level spillway and an additional 2.4 feet

The City is required to inspect all structural works of improvement annually and after every major storm or occurrence of any unusual adverse conditions that affect their operation. However, the only manually operated structure at Site No. 1, Dead River Dam, is the low-level reservoir outlet which allows the pool to be drawn down for cleaning or repairs at the site. The principal and emergency spillways function automatically as the reservoir pool elevation changes. The SCS provides consultative assistance to the City of Berlin for the operation of the structures.

2.4 Evaluation

a. Availability. Complete SCS engineering plans and sketches, hydrologic and hydraulic calculations, construction field notes, and detailed geologic data are on file at the SCS Durham office.

b. Adequacy. Field inspection of Site No. 1, Dead River Dam, indicated that the SCS plans and sketches were adequate. Final assessments and recommendations are based upon the SCS plans, sketches, and hydrologic and hydraulic calculations in conjunction with the visual inspection of the dam and dike sites.

c. Validity. The visual inspection disclosed that the present conditions are consistent with the SCS as-built plans and sketches.

SECTION 2 ENGINEERING DATA

2.1 Design

Site No. 1, Dead River Dam, was designed by the U.S. Department of Agriculture, Soil Conservation Service (SCS) in 1968. Design data were found in the SCS Durham, New Hampshire, office. These data consisted of:

- (1) Complete design report with all hydrologic and hydraulic calculations (see Appendix B).
- (2) Detailed geologic investigations of the dam and dike sites (see Appendix B).
- (3) Dam, dike, and emergency spillway design data on 39 sheets and other data include (selected 9 of 39 sheets in Appendix B):
 - (a) Plans of dike, dam, principal spillway, and emergency spillway, toe drains, and pool.
 - (b) Sketches of typical sections of dam and dike embankment and emergency spillway.
 - (c) Profiles along centerline of dike, dike cutoff trench, dam, dam cutoff trench, and emergency spillway.
 - (d) Detailed listing of quantities of construction materials.
 - (e) Sketches of fill placement in dam and dike embankments.
 - (f) Logs of test holes (not readily reproducible).

2.2 Construction

The design plans were revised in 1971 to reflect as-built conditions. Field notes and revisions made to the design plans are available in the SCS Durham office.

2.3 Operation

The City of Berlin is responsible for operation of the dam for structural measures as set forth by an agreement (see Appendix B, pages B-1 to B-5) between the SCS, the project's designer, the New Hampshire Water Resources Board (NHWRB), and the City of Berlin, the sponsor of the Dead River Watershed project.

(6) U/S Channel - The dam spans Jericho Brook and creates Jericho Lake. The watershed above the reservoir is steep and heavily wooded. A bathing beach, bathhouse, and boat ramp are located on the northshore of the reservoir and comprise Jericho Lake Park. No other development exists on the shores of Jericho Lake. The dike is not clearly visible from the dam.

(7) D/S Channel - The channel immediately downstream is about 20 feet in width. The channel bottom is a mixture of sand, gravel, and boulders. Trees and heavy brush cover the valley sides. In the immediate vicinity of the principal spillway outlet erosion of the channel walls is apparent.

k. Emergency Spillway

(1) Type - a grass covered earthen channel having side slopes 1H:1V of exposed rock and 4H:1V of earth embankment to the north and 4H:1V side slope of earth embankment to the south.

(2) Width - 100'

(3) Crest elevation - 1,362.0' MSL

(4) Length of level section - 60' (approximate)

(5) U/S Channel - The approach channel originates at the northeast bank of the reservoir north of the dam and is grass covered.

(6) D/S Channel - The downstream channel is not well defined with standing trees and brush noted. It joins the downstream channel of the principal spillway several hundred yards downstream of the principal spillway outlet.

1. Regulating Outlet. A 60-foot long, 30-inch diameter reinforced concrete pipe serves as reservoir drain, originating at upstream pool bottom with invert at 1,329.3 feet (MSL) and discharges into 42-inch diameter concrete. The crank-operated gate lift mechanism is located on top of the cover of the two-stage drop-inlet riser.

(8) Cutoff - core trench excavated through alluvium, glacial till and decomposed rock to firm bedrock as shown on SCS design plans

(9) Grout curtain - none

(10) Toe drain - two 12" diameter perforated corrugated metal pipes

h. Dike

(1) Type - earthen embankment on unconsolidated glacial deposits along the watershed divide

(2) Length - 1,665'

(3) Height - 14'

(4) Topwidth - 10'

(5) Side Slopes - 3H:1V upstream and downstream

(6) Zoning - 2 zones in dike embankment indicated on SCS design plans (see Appendix B)

(7) Impervious core - none indicated on SCS design plans

(8) Cutoff - core trench excavated through alluvium, glacial till, and decomposed rock to firm bedrock along centerline shown on SCS design plans

(9) Grout curtain - none

(10) Toe drain - none

i. Diversion and Regulating Tunnel - not applicable

j. Principal Spillway

(1) Type - a vertical reinforced concrete two-stage drop-inlet riser having a covered top with two 2'H x 2.7'W rectangular inlets at the lower level and two 1.9'H x 10.5'W inlets at the higher level which ultimately discharge into a 42-inch horizontal conduit.

(2) Size - 3.5' x 10.5' drop-inlet riser discharging into a 42-inch diameter horizontal conduit with a length of 204 feet through dam embankment

(3) Crest Elevation - 1,352.0' MSL for first level inlets and 1,356.0' MSL for second level inlets

(4) Gates - none

(5) Low-level - 30-inch diameter reinforced concrete pipe which originates in pool bottom and discharges into the 42-inch conduit.

(4) Length of flood control pool - 4,150

e. Storage (acre-feet)

(1) Recreation pool - 1,240

(2) Flood control pool - 2,800

(3) Principal spillway crest pool - 1,240

(4) Emergency spillway crest pool - 2,800

(5) Top of dam - 4,720

(6) Test flood pool - 4,695

f. Reservoir Surface (acres)

(1) Recreation pool - 132

(2) Flood control pool - 177

(3) Principal spillway crest - 132

(4) Emergency spillway crest - 177

(5) Test flood pool - 208

(6) Top of dam - 215

g. Dam

(1) Type - earthen embankment on unconsolidated glacial deposits with drop-inlet spillway (principal) and grassed emergency spillway; consists of 333,700 cubic yards of fill.

(2) Length - 3,035' (includes 100-foot wide emergency spillway)

(3) Height - 46.5' (hydraulic and structural height)

(4) Topwidth - 16'

(5) Side slopes - 3H:1V upstream and 2.5H:1V downstream

(6) Zoning - 3 zones in dam embankment and riprap on the upstream slope as indicated on SCS design plans.

(7) Core - trapezoidal section consisting of silty sands with a 40' width at base, 10' topwidth, and height of 30'; elevation at top of impervious core is 1,352.0' MSL as shown on SCS design plans.

(1) Low-level outlet (reservoir drain) 30" RCP capacity @ principal spillway elevation - 112 cfs @ 1,352' MSL

(2) Principal (drop-inlet) spillway capacity @ test flood elevation - 302 cfs @ 1,370.9' MSL (low stage: 113 cfs; high stage: 189 cfs)

(3) Emergency spillway discharge @ test flood elevation - 7,673 cfs @ 1,370.9' MSL

(4) Total project discharge @ test flood elevation - 7,975 cfs @ 1,370.9' MSL

(5) Principal (drop-inlet) spillway capacity @ top of dam - 302 cfs @ 1,371.0' MSL (low stage: 113 cfs; high stage: 189 cfs)

(6) Emergency spillway capacity @ top of dam - 7,800 cfs @ 1,371.0' MSL

(7) Total spillway capacity @ top of dam - 8,102 cfs @ 1,371.0' MSL

c. Elevation (feet above MSL as shown on available "as built" SCS plans in Appendix B)

(1) Streambed @ centerline of dam - 1,324.5 (approximate, at downstream toe)

(2) Bottom of cutoff trench - 1,317.0

(3) Maximum tailwater - unknown

(4) Upstream invert low-level outlet - 1,329.3

(5) Recreation pool - 1,352.0 (principal spillway)

(6) Full flood control pool - 1,362.0

(7) Drop-inlet spillway crest - lower level - 1,352.0,
higher level - 1,356.0
Emergency spillway crest - 1,362.0

(8) Design surcharge (original design) - 1,371.0

(9) Top of dam - 1,371.0

(10) Test flood pool - 1,370.9

d. Reservoir (feet)

(1) Length of maximum pool - 4,150

(2) Length of pool at principal spillway crest - 3,700 (approximate)

(3) Length of pool at emergency spillway crest - 4,150 (approximate)

c. Size Classification. Intermediate (hydraulic height - 46.5 feet; storage - 4,720 acre-feet) based on criteria (intermediate size corresponds to dam with height \geq 40 feet and $<$ 100 feet and storage \geq 1,000 and $<$ 50,000 acre-feet) in Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification. High Hazard. A major breach could result in extensive property damage and considerable loss of life (10 or more) downstream in the urbanized area of the City of Berlin. Major floods in 1927, 1936, and 1953 on the Dead River, with significantly smaller discharges than the breach discharge used in this report, support this contention (See Section 5.1 f.).

e. Ownership. The Project is owned by the City of Berlin, New Hampshire.

f. Operator. The dam is operated by the City of Berlin Recreation and Parks Department, First Avenue, Berlin, New Hampshire, 03570. Telephone (603) 752-2010.

g. Purpose of the Project. The Project was constructed for the purposes of storing floodwaters and providing recreational opportunities.

h. Design and Construction History. The Project was designed by the Soil Conservation Service (SCS), Durham, New Hampshire office. Construction was begun in May 1969 by Rogers Construction Co., Inc. of Brattleboro, Vermont and the project was 99 percent complete by December 1969. All remaining construction work was completed by September 1970 by the same firm.

i. Normal Operating Procedures. The City of Berlin, as is set forth in the Operation and Maintenance Agreement for Structural Measures (between the City and SCS), is required to inspect all structural works of improvement annually and after every major storm or occurrence of any unusual adverse conditions that affect their operation. The only operable outlet at the Project is the low-level reservoir drain which allows the reservoir pool level to be drawn down for cleaning or repairs at the site. The principal spillway (two-stage riser) and the emergency spillway function automatically as the reservoir pool elevation changes.

1.3 Pertinent Data

a. Drainage Area. The watershed above the dam consists of 6.48 square miles (4,147 acres) of steep forested terrain. No storage areas exist in the watershed above the upstream limit of Jericho Lake. The normal surface area (recreation pool) is 132 acres which constitutes 3.2 percent of the total watershed area.

b. Discharge at Damsite. According to the director of the City of Berlin Park and Recreation Department, the maximum known stage at the damsite occurred at an unknown date when the reservoir pool elevation approximately reached the second stage inlet of the principal spillway. Using the rating curve calculated for the dam, the project discharge was estimated to have been 90 cfs.

SECTION 6
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations. The visual examination indicates the following evidence of potential problems:

(1) Extensive vehicular trespassing on the crest, the upstream slope, the downstream slope, and the area immediately downstream of the toe of the dam is destroying the grassy ground cover and leaving ruts in the ground surface.

(2) Two minor seepages near the outlet of spillway discharge pipe and the two underdrain pipes.

(3) One seepage more than 100 feet downstream from the toe of the dam.

b. Design and Construction Data. Site No. 1, Dead River Dam, was designed by the U.S. Department of Agriculture, Soil Conservation Service (SCS) in 1968. Design data were found in the SCS Durham, New Hampshire, office. These data consisted of:

(1) Complete design report with all hydrologic and hydraulic calculations (see Appendix B).

(2) Detailed geologic investigations of the dam and dike sites (see Appendix B).

(3) Dam, dike, and emergency spillway design data on 39 sheets; include (selected 9 of 39 sheets in Appendix B):

(a) Plans of dike, dam, principal spillway, and emergency spillway, toe drains, and pool.

(b) Sketches of typical sections of dam and dike embankments and emergency spillway.

(c) Profiles along centerline of dike, dike cutoff trench, dam, dam cutoff trench, and emergency spillway.

(d) Detailed listing of quantities of construction materials.

(e) Sketches of fill placement in dam and dike embankments.

(f) Logs of test holes (not readily reproducible).

The design plans were revised in 1971 to reflect as-built conditions. Field notes and revisions made to the design plans are available in the SCS Durham office.

c. Operating Records. Detailed inspections records obtained from the SCS Durham office are in Appendix B.

d. Post-Construction Changes. There is no record of post-construction changes.

e. Seismic Stability. This dam is located in Seismic Zone 2 and in accordance with the Phase I guidelines does not warrant seismic analysis.

SECTION 7
ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. The visual examination indicates that Dead River Dam is in good condition. The only concerns with respect to the long-term stability of the dam are:

(1) Extensive vehicular trespassing on the crest, the upstream slope, the downstream slope, and the area immediately downstream of the toe of the dam is destroying the grass ground cover and leaving ruts in the ground surface.

(2) Two minor seepages near the outlet of spillway discharge pipe and the two corrugated metal underdrain pipes.

(3) One seepage approximately 300 feet south of the bend in the dam and 100 feet downstream from the toe of the dam may or may not be associated with flow from the reservoir and, therefore, may not be indicative of a problem.

b. Adequacy of Information. The visual examination and the complete design data available are adequate for the purposes of the Phase I inspection.

c. Urgency. The recommendations and remedial measures made in 7.2 and 7.3 below should be implemented by the owner within two years after receipt of this Phase I inspection.

d. Need for Additional Investigation. There is no need for additional investigation for the purposes of this Phase I report.

7.2 Recommendations

The owner should engage a registered professional engineer to investigate the two minor seepages near the spillway outlet and the one seepage which is more than 100 feet downstream from the dam.

7.3 Remedial Measures

a. Operating and Maintenance Procedures. The owner should:

(1) Repair ruts and control trespassing on the dam and the area immediately downstream of the dam.

(2) Visually inspect the dam and appurtenant structures and monitor seepage once a month.

(3) Engage a registered professional engineer to make a comprehensive technical inspection of the dam once every two years.

(4) Establish an around-the-clock surveillance program

for use during and immediately after heavy rainfall and also a warning program to follow in case of emergency conditions or imminent dam failure.

(5) Mow and cut saplings on dike embankment seasonally.

(6) Observations at the dam should be made after significant events, but while substantial storage is still being utilized to determine if seepage exists which could not be detected when the reservoir pool is at normal elevation.

7.4 Alternatives

None.

APPENDIX A
VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST
PARTY ORGANIZATION

PROJECT Site No. 1, Dead River Dam DATE June 7, 1979
(Berlin, NH)

TIME 1400

WEATHER Sunny, warm

W.S. ELEV. U.S. DN.S.
1353.1 1321.0

PARTY:

- | | |
|-----------------------------|-----------|
| 1. <u>Warren Guinan</u> | 6. _____ |
| 2. <u>Stephen Gilman</u> | 7. _____ |
| 3. <u>Katherine Hivley</u> | 8. _____ |
| 4. <u>Pattu Keshevan</u> | 9. _____ |
| 5. <u>Ronald Hirschfeld</u> | 10. _____ |

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>Hydrology/Hydraulics</u>	<u>W. Guinan</u>	
2. <u>Structural Stability</u>	<u>S. Gilman</u>	
3. <u>Soils & Geology</u>	<u>R. Hirschfeld</u>	
4. _____		
5. _____		
6. _____		
7. _____		
8. _____		
9. _____		
10. _____		

PERIODIC INSPECTION CHECKLIST

PROJECT Site No. 1, Dead River (Berlin, NH) DATE June 7, 1979

PROJECT FEATURE Dam Embankment NAME _____

DISCIPLINE _____ NAME _____

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	1371.0 MSL
Current Pool Elevation	1353.1 MSL
Maximum Impoundment to Date	1356.0 MSL (approximate)
Surface Cracks	None observed
Pavement Condition	Not paved
Movement or Settlement of Crest	None observed
Lateral Movement	None observed
Vertical Alignment	Good
Horizontal Alignment	Good
Condition at Abutment and at Concrete Structures	Good
Indications of Movement of Structural Items on Slopes	None observed
Trespassing on Slopes	Extensive vehicle tracks on downstream face of dam at and beyond toe.
Sloughing or Erosion of Slopes or Abutments	None observed
Rock Slope Protection - Riprap Failures	Riprap on upstream face - no failures observed.
Unusual Movement or Cracking at or Near Toe	None observed
Unusual Embankment or Downstream Seepage	Two minor seepage areas right of spillway outlet pipe
Piping or Boils	None observed
Foundation Drainage Features	
Toe Drains	Two CMP toe drains discharging water on either side of spillway discharge.
Instrumentation System	None observed
Vegetation	Grass on both upstream and downstream slopes. Some grass on crest, but vehicle tracks on crest are bare soil.

PERIODIC INSPECTION CHECKLIST

PROJECT Site No. 1, Dead River (Berlin, NH) DATE June 7, 1979
 PROJECT FEATURE Dike Embankment NAME _____
 DISCIPLINE _____ NAME _____

AREA EVALUATED	CONDITION
<u>DIKE EMBANKMENT</u>	
Crest Elevation	1371.0 MSL
Current Pool Elevation	1353.1 MSL
Maximum Impoundment to Date	1356.0 MSL (approximate)
Surface Cracks	None observed
Pavement Condition	Not paved
Movement or Settlement of Crest	None observed
Lateral Movement	None observed
Vertical Alignment	Good
Horizontal Alignment	Good
Condition at Abutment and at Concrete Structures	Good
Indications of Movement of Structural Items on Slopes	None
Trespassing on Slopes	None observed
Sloughing or Erosion of Slopes or Abutments	None observed
Rock Slope Protection - Riprap Failures	No riprap
Unusual Movement or Cracking at or Near Toes	None observed
Unusual Embankment or Downstream Seepage	No water against upstream side of dike
Piping or Boils	None
Foundation Drainage Features	None observed
Toe Drains	None observed
Instrumentation System	None observed
Vegetation	Grass on crest; grass, brush, and small trees on upstream slope and downstream slopes.

PERIODIC INSPECTION CHECKLIST

PROJECT Site No. 1, Dead River (Berlin, NH) DATE June 7, 1979

PROJECT FEATURE Principal Spillway NAME _____
(Two-stage riser)

DISCIPLINE _____ NAME _____

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - CONTROL TOWER</u>	
a. Concrete and Structural	
General Condition	Good
Condition of Joints	Good - no indications of movement.
Spalling	None visible
Visible Reinforcing	None
Rusting or Staining of Concrete	None visible
Any Seepage or Efflorescence	None visible
Joint Alignment	Good - no apparent movement.
Unusual Seepage or Leaks in Gate Chamber	Not visible
Cracks	None visible
Rusting or Corrosion of Steel	None visible - galvanized steel in good condition.
b. Mechanical and Electrical	
Air Vents	Hand-operated crank serves as a gate lift mechanism for low-level reservoir drain; located on concrete platform on top of two-stage riser. Appears to be in good condition.
Float Wells	
Crane Hoist	
Elevator	
Hydraulic System	
Service Gates	
Emergency Gates	
Lightning Protection System	
Emergency Power System	
Wiring and Lighting System	

PERIODIC INSPECTION CHECKLIST

PROJECT Site No. 1, Dead River (Berlin, NH) DATE June 7, 1979
 PROJECT FEATURE Emergency Spillway NAME _____
 DISCIPLINE _____ NAME _____

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
a. Approach Channel	
General Condition	Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Approach Channel	Glacial till
b. Weir and Training Walls	None - earth spillway
General Condition of Concrete	None
Rust or Staining	None
Spalling	None
Any Visible Reinforcing	None
Any Seepage or Efflorescence	None
Drain Holes	None
c. Discharge Channel	
General Condition	Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	Some trees in channel
Floor of Channel	Glacial till
Other Obstructions	None

PROJECT Site No. 1, Dead River
(Berlin, NH)

DATE June 7, 1979

PROJECT FEATURE Reservoir

NAME W. Guinan

AREA EVALUATED	REMARKS
Stability of Shoreline	Good
Sedimentation	None visible
Changes in Watershed Runoff Potential	None visible
Upstream Hazards	None visible
Downstream Hazards	Urbanized area of City of Berlin Converse Building
Alert Facilities	None visible
Hydrometeorological Gages	None visible
Operational & Maintenance Regulations	None visible

APPENDIX B
ENGINEERING DATA

Jericho Brook
Berlin, New Hampshire
June 24, 1977

1977

Dead River - Topdressing

Dam only.

Recommendations for this season.

Use 500#/acre of "Sul-po-mag". This is sulfate of potash magnesia.

This may be purchased at Merrimack Farmers' Exchange in 80# bags. The ton price is \$125. There may be other local sources.

There are 6½ acres involved in the dam. Of these, 2½ acres are on the upstream face of the dam and 4½ on the downstream face.

Basis for recommendations.

The dam is covered with a good population of birdsfoot trefoil. The vigor of these plants is very poor on the upstream face and fairly good but deteriorating on the downstream face.

Soil tests taken on 5/27/77 revealed a deficiency of magnesium and potassium in relation to the needs of birdsfoot trefoil.

The objective of the recommendation is to try and increase the plant cover of birdsfoot trefoil in order to prevent erosion and to prevent encroachment of woody plant species that would require annual eradication.

Recommendations for next spring and early summer.

A topdressing of 300#/acre of muriate of potash next spring is very desirable. If this can be accomplished, further topdressing should be based on soil tests taken every other year.

One ton of muriate of potash would cover the entire dam. It costs approximately \$170/ton and is readily available through local grain companies.

Attachment

MAINTENANCE CHECKLIST FOR PL 566 FLOOD CONTROL STRUCTURES

This maintenance checklist is a guide for determining the maintenance required for Public Law 566 flood control structures in New Hampshire. It doesn't take the place of experience and judgment and is not inclusive. Items of a difficult nature to check, such as principal spillway conduit condition, are not included. Intensive checks of these items are necessary at proper intervals. Review of As Built drawings, the design folder, structure history, and previous maintenance reports should be part of the inspection. Prompt maintenance is a vital part of safe and effective operation.

Except where otherwise indicated, completion of this form may be facilitated by ranking maintenance items on a 1 to 4 basis where

- 1 = satisfactory
- 2 = satisfactory, but check carefully at next inspection
- 3 = requires maintenance this season
- 4 = requires immediate attention.

WATERSHED DEAD RIVER SITE 1 DATE 6/12/78
 INSPECTED BY Keith MacPherson, Richard Haldeman, Mitchell Berkowitz, M. L. Glidden

1. GENERAL ITEMS

Access Road.	3
Site Fencing.	2
Traffic Conditions.	3
Vandalism Control.	1
Trash Control.	3

COMMENTS Gate is being installed across left end of dam.

2. RESERVOIR

Timber stand at reservoir.	2
Debris and slash.	3
Sediment level in relation to low stage inlet	2

COMMENTS Brush in the inlet and outlet channel of the Emergency Spillway should be removed. Debris and slash on the upstream embankment.

Piche Building, 99 Main St., Lancaster, NH 03574

June 19, 1975

Mr. James Smith
City Manager
City Hall
Berlin, NH 03570

Dear Mr. Smith:

Attached is the annual Operations and Maintenance Inspection Report for the Dead River Watershed conducted on June 17, 1975.

The report lists items that require attention by the City as their obligation under the Operation and Maintenance Agreement of August 26, 1968.

I trust that you will see that these actions are carried out and following completion will send me a letter to that effect.

Sincerely,

Calvin J. Perkins
District Conservationist

cc: ✓ Wheeler, Acting City Engineer
✓ C. Pingle, Assistant State Conservationist (NR)

OPERATIONS AND MAINTENANCE INSPECTION REPORT
Site 1 (Jericho Lake)
Dead River Watershed Project
May 28, 1976

An operation and maintenance inspection of Site 1 (Jericho Lake) in the Dead River Watershed, Berlin, NH was conducted on May 28, 1976. The inspection was made by representatives from the local sponsoring organization, the Coos County Conservation District, and the Soil Conservation Service. Those present were:

Mitchell Berkowitz, Berlin Recreation Director
Randell Sargent, Coos County Conservation District
Richard Haldeman, District Conservationist, USDA, SCS
Eddie Wood, USDA, SCS
Tillman Marshall, USDA, SCS
Nick Luhtala, USDA, SCS

Following is a list of items discussed and the necessary action needed:

1. Remove debris from the principle spillway trash rack.
2. Close off, repair erosion and revegetate old access road below dam.
3. Close off and vegetate present road running across the top of the dam.
4. Improve vegetative cover on the dam slopes by:
 - A. Removing woody vegetation which is starting to develop in several areas.
 - B. Lime and fertilize slopes, especially the upstream slope. Lime and fertilizer should be applied according to soil test recommendations which can be obtained through the County Agent's office, Coos County Extension Service, Lancaster, NH. However, if this information can not be obtained a general recommendation of 2 tons per acre (or 100 lbs. per 1,000 sq. ft.) of ground limestone and 400 lbs. per acre (or 10 lbs. per 1000 sq. ft.) of 10-10-10 or equivalent fertilizer may be used.
5. Remove alders and other woody vegetation that is starting to grow in the stream overflow area, between the upstream slope of the dam and the inlet stream.

ding, 99 Main St., Lancaster, NH 03584

File
June 3, 1976

Mr. James Smith
City Manager
City Hall
Berlin, NH 03570

Dear Mr. Smith:

Attached is the annual Operations and Maintenance Inspection Report for the Dead River Watershed conducted on May 23, 1976.

The report lists those items which require maintenance by the City. I trust that these items will be carried out as soon as possible under the City's obligation in the Operation and Maintenance Agreement, for this project, of August 26, 1968.

When the items listed are completed please send me a letter so indicating.

If additional technical assistance is needed to carry out any of these maintenance items please feel free to call on us.

Very truly yours,

Richard S. Haldeman
District Conservationist

BERLIN RECREATION AND PARKS DEPARTMENT

FIRST AVENUE BERLIN, NEW HAMPSHIRE 03570 TELEPHONE 752-2010

MITCHELL A. BERKOWITZ, DIRECTOR


-2-

all of the undesirable vegetation along the dam and the over-flow areas. Much of our new operations and maintenance program included the 1968 project agreement. In future years we hope to improve this type of maintenance based on the changes in the park's areas.

Our summer workers also controlled the erosion along the new access road with the introduction of bark. This has already started new vegetation which should enhance the roadway next year. Two important areas of erosion were also brought to a control. The first was the entrance way which has been carefully cribbed and seeded. The second area was along the steep slope of the parking lot. Again, cribbing and seeding along with a drainage ditch has halted any erosion. During the 1977 summer we will complete the parking lot erosion control, re-landscape the roadway and develop 12 special tent campsites in the upper field.

As always, I look forward to another year at Jericho Lake Park and the needed improvements we hope to fulfill. Your inspection in May 1977 should also provide us with additional recommendations.

Cordially,



Mitchell A. Berkowitz,
Director

CC: Mayor Laurier Lamontagne
City Manager James C. Smith

BERLIN RECREATION AND PARKS DEPARTMENT

FIRST AVENUE BERLIN, NEW HAMPSHIRE 03570 TELEPHONE 752-2010

MITCHELL A. BERKOWITZ, DIRECTOR

17 December 1976

Mr. Richard S. Halderman
District Conservationist
U.S.C.S.
Piche Building
99 Main Street
Lancaster, N.H.

Dear Mr. Halderman,

The Recreation Department Summer Staff has worked very diligently to complete many of the Inspector recommendations. To date we have removed debris from the principle spillway trash rack and consider this as part of our weekly operation once the park is open each year. In the Early spring this would be checked once the access road is clear of ice. The Old access road has been partially closed off and we intend to completely close this road as well as the road on top of the dam. All erosion in these areas has been initially halted and further repairs and vegetation will commence in the late spring and early summer. One of the major difficulties in this area is accessibility by G.V.'s. During the 1977 summer we feel that we will be better able to control their use through some additional concrete development and barrier improvements.

During the summer we were able to apply lime to the slopes and in many cases we scarified, lined, added loam and re-seeded bare spots along the dam. This will continue during the 1977 summer.

In the area of woody vegetation control I feel we went beyond the recommendations and will continue to control

6. IMPACT BASIN, SAF. BOX INLET, & MISCELLANEOUS CONCRETE STRUCTURES

(specify) Diversion channel structures

Concrete: Cracking 1; Spalling 1; Other deterioration 1; Excessive movement (check joints) 1; Waterstops 1; Joint sealant 1; Other 1.
 inside and out

Trashracks: Condition of protective coatings 1; Corrosion 1; Damaged parts 1; Condition of fastenings 1; Need of gratings due to beaver 1; Safety condition (protruding fastenings, sharp edges, etc.) 1; Other 1.
 low and high stage

Gates: Condition of protective coating ; Corrosion ; Damaged parts ; Condition of fastenings ; Stem alignment ; Operation ; Lubrication ; Wood decay ; Other .
 including lifting device, stem, guides, disc, flap

Structure Drainage: Report under "Embankment and Other Drains"

Structure, Railing, Condition of protective coating ; Corrosion ; Damaged parts ; Condition of Fastenings ; Wood decay ; Safety condition (protruding fastenings, sharp edges, etc.) ; Other .
 Grates, Barriers, etc.

Safety Items: Condition of warning signs ; Condition of safety equipment ; Other .

COMMENTS 1 stop log in stream below structure-
channels for stop logs rusty - paint

9. CHANNEL

Stream obstructions.	<u>1</u>
Debris in stream.	<u>1</u>
Sediment bars controlled.	<u>1</u>
Plunge pool stability.	<u>1</u>
Fish habitat appurtenances	<u>0</u>
Riprap -- Report under "Riprap" (item 4)										

COMMENTS _____

7. RISER

Caution Be extremely careful when using ladders. Check condition before using. Ladders are sometimes broken, loose, corroded, and or slippery. Use safety harness.

Ladders:
inside and out

Condition of protective coating ?;
Corrosion ?; Damaged parts ?; Loose ?;
Other ?.

Concrete:
inside and out

Cracking 1; Spalling 1; Other deterioration
 ; Excessive movement (check joint at riser
and conduit) ; Other .

Trashracks:
low and high stage

Condition of protective coatings 1; Corrosion
1; Damaged parts 1; Condition of fastenings
1; Need of gratings due to beaver 1; Safety
condition (protruding fastenings, sharp edges,
etc.) 1; Other .

Manhole:

Condition of protective coatings 3; Corrosion
 ; Damage 1; Lock operable ?; Other .

Gate:
including lifting
device, stem, guides,
disc

Condition of protective coating 2; Corrosion
1; Damaged parts 1; Condition of fasten-
ings 1; Stem alignment 1; Lubrication 1;
Operation ; Other .

Safety Items:

Condition of warning signs ; Condition of
safety equipment ; Other .

COMMENTS Trash in racks need cleaning. Didn't check
Ladder - No wrench to get M.H. cover off. Man hole
cover rusty. Gate lift should be painted & checked
for operation. Grease & oil if necessary.

5. VEGETATION

	Dam	Emergency Spillways ^{1/}		Dike	Outlet Channel	flood water way	Other (Parking) lot
		left	right				
Condition of stand (including need for lime and fertilizer)	3	3	—	—	1	2	3
Undesirable vegetation	3	3	—	—	1	3	1
Drainage (surface)	1	1	—	—	1	1	1
Erosion ^{2/}	1	1	—	—	1	1	1
Sedimentation	1	1	—	—	1	1	1
Condition of planting	—	—	—	—	—	—	—
Pest control	1	1	—	—	1	1	1
Fire control	1	1	—	—	1	1	1

COMMENTS Entire dam should be fertilized based on soil test results.
Entire dam may need to be limed based on soil test results.
Shrub growth on dam should be eradicated.
Spillway should be limed and fertilized based on soil test results.
Shrub growth in waterway should be controlled.
Shrub growth in spillway should be controlled.
Bank above parking lot should be limed & fertilized based on soil test.

6. EMBANKMENT, STRUCTURAL, & OTHER DRAINS

		Dam ^{1/}		Other	
		left	right	()	()
Depth of Flow (in inches above invert)	With any obstruction	—	—	—	—
	Without any obstruction	1/2	1/2	—	—
Turbidity of Discharge (yes, no)	With any obstruction	No	No	—	—
	Without any obstruction	No	No	—	—
Condition of Protective Coating	Outside	2	2	—	—
	Inside	1	1	—	—
Obstruction in Flow (yes, no)		No	No	—	—
Animal Guard Condition		1	1	—	—
Outlet Condition		—	—	—	—
Retarding Pool Elevation (ft. msl) _____ or _____ (ft.) above _____ below _____					
Other _____					

COMMENTS Seepage around riser.

^{1/}Looking downstream.

^{2/}Including wave, surface, stream, manmade, and livestock erosion.

3. EMBANKMENT AND EXCAVATED SLOPES

(Report riprap and vegetation and erosion condition under Items 4 and 5.)

	Dam	Dike	Emergency Spillways ^{1/}		Other	
			left	right	()	()
Sliding or sloughing	2	—	—	—	—	—
Holes (rodent and other) (check especially at embankments)	2	—	—	—	—	—
Excessive settlement (embankments)	1	—	—	—	—	—
Cracks						
Traverse	1	—	—	—	—	—
Longitudinal	1	—	—	—	—	—
Seepage ^{2/}	1	—	—	—	—	—
Piping ^{2/}	1	—	—	—	—	—

COMMENTS could be gouging by ice

200' rt of riser to 40' long - top about half way
up fill. 2nd area 170' LT of PI of curve. 2 holes &
burrowing downstream face (rt side) opposite rock rib outcrop.
Vehicle tracks should be filled in - particularly those
running up & down slope

4. RIPRAP

	Displ. of Rock	Loss of Spalls	Loss of Bedding	Erosion of Found.	Break- down of Rock
Dam					
Upstream berm	2	2	1	1	1
Principal Spillway Outlet	—	—	—	—	—
Embankment Gutters					
left	—	—	—	—	—
right	—	—	—	—	—
Emergency Spillway					
location	—	—	—	—	—
location	—	—	—	—	—
Waterways					
location <u>floodway</u>	2	2	1	1	1
location <u>Division channel</u>	1	1	1	1	1
Outlet Channel	1	1	1	—	—
Other	—	—	—	—	—

COMMENTS Riprap around riser displaced. Some minor
displacement in riprap on upstream face along
floodway.

^{1/}Looking downstream.

^{2/}Check especially at downstream face of embankments.

MAINTENANCE CHECKLIST FOR 1956 FLOOD CONTROL STRUCTURES

This maintenance checklist is a guide for determining the maintenance required for Public Law 566 flood control structures in New Hampshire. It doesn't take the place of experience and judgment and is not inclusive. Items of a difficult nature to check, such as principal spillway conduit condition, are not included. Intensive checks of these items are necessary at proper intervals. Review of As Built drawings, the design folder, structure history, and previous maintenance reports should be part of the inspection. Prompt maintenance is a vital part of safe and effective operation.

Except where otherwise indicated, completion of this form may be facilitated by ranking maintenance items on a 1 to 4 basis where

- 1 = satisfactory
- 2 = satisfactory, but check carefully at next inspection
- 3 = requires maintenance this season
- 4 = requires immediate attention.

WATERSHED DEAD RIVER SITE 1 DATE 1977
 INSPECTED BY _____

1. GENERAL ITEMS

Access Road.	<u>4</u>
Site Fencing.	<u>4</u>
Traffic Conditions.	<u>4</u>
Vandalism Control.	<u>4</u>
Trash Control.	<u>4</u>

COMMENTS UPSTREAM FACE OF DAM EMER. SPIRY FLOODWAY
DOWNSTREAM FACE - Hole under cradle 4" wide 3"
depth flowing full, travel across top of dam, old
road to dam not fenced as required in access
road construction

2. RESERVOIR

Timber stand at reservoir.	<u>2</u>
Debris and slash.	<u>2</u>
Sediment level in relation to low stage inlet	<u>2</u>

COMMENTS water along beach look clearer this
year.

8. IMPACT BASIN, SAF, BOX INLET, & MISCELLANEOUS CONCRETE STRUCTURES(specify) Recirculating System - Inlet and damConcrete:
inside and outCracking 1; Spalling 1; Other deterioration
1; Excessive movement (check joints) 1;
Waterstops 1; Joint sealant 1; Other 1.Trashracks:
low and high stageCondition of protective coatings 1; Corrosion
1; Damaged parts 1; Condition of fasten-
ings 1; Need of gratings due to beaver 1;
Safety condition (protruding fastenings, sharp
edges, etc.) 1; Other 1.Gates:
including lifting
device, stem, guides,
disc, flapCondition of protective coating 2; Corrosion
2; Damaged parts 2; Condition of fasten-
ings 2; Stem alignment 2; Operation 3;
Lubrication 2; Wood decay 2; Other 2.

Structure Drainage:

Report under "Embankment and Other Drains"

Structure, Railing,
Grates, Barriers,
etc.Condition of protective coating --; Corrosion
--; Damaged parts --; Condition of Fasten-
ings --; Wood decay --; Safety condition
(protruding fastenings, sharp edges, etc.)
--; Other --.

Safety Items:

Condition of warning signs --; Condition of
safety equipment --; Other --.

COMMENTS

9. CHANNEL

Stream obstructions.	<u>1</u>
Debris in stream.	<u>1</u>
Sediment bars controlled.	<u>1</u>
Plunge pool stability.	<u>1</u>
Fish habitat appurtenances	<u>---</u>
Riprap -- Report under "Riprap" (item 4)											

COMMENTS

Caution Be extremely careful when using ladders. Check condition before using. Ladders are sometimes broken, loose, corroded, and or slippery.
Use safety harness.

Ladders: None
inside and out

Condition of protective coating___;
Corrosion___; Damaged parts___; Loose___;
Other___.

Concrete:
inside and out

Cracking 0; Spalling 0; Other deterioration
0; Excessive movement (check joint at riser
and conduit) 0; Other 0.

Trashracks:
low and high stage

Condition of protective coatings 1; Corrosion
0; Damaged parts 1; Condition of fastenings
1; Need of gratings due to beaver 0; Safety
condition (protruding fastenings, sharp edges,
etc.) 1; Other 0.

Manhole:

Condition of protective coatings 3; Corrosion
___; Damage___; Lock operable___; Other___.

Gate:
including lifting
device, stem, guides,
disc

Condition of protective coating___; Corrosion
___; Damaged parts___; Condition of fasten-
ings___; Stem alignment___; Lubrication___;
Operation___; Other___.

Safety Items:

Condition of warning signs___; Condition of
safety equipment___; Other___.

COMMENTS Paint manhole cover.

INLET TO RECIRCULATING PIPE SYSTEM - Remove debris from trash rack. (3)

5. VEGETATION

	Dam	Emergency Spillways ^{1/}		Dike	Outlet Channel	Water way	Other ()
		left	right				
Condition of stand (including need for lime and fertilizer)	3	—	—	—	—	—	—
Undesirable vegetation	3	3	—	4	—	—	—
Drainage (surface)	—	3	—	—	—	—	—
Erosion ^{2/}	3	3	—	—	—	—	—
Sedimentation	3	3	—	—	—	—	—
Condition of planting	—	—	—	—	—	—	—
Pest control	—	—	—	—	—	—	—
Fire control	—	—	—	—	—	—	—

COMMENTS Pockets need to be drained and revegetated. Remove woody plants from the dam. Bare spots should be topdressed and reseeded. There is erosion from damage to vegetation by ATV's. Remove the woody vegetation from the dike.

6. EMBANKMENT, STRUCTURAL, & OTHER DRAINS

		Dam ^{1/}		Other	
		left	right	()	()
Depth of Flow (in inches above invert)	With any obstruction	None		—	—
	Without any obstruction	1/4"	1/2"	—	—
Turbidity of Discharge (yes, no)	With any obstruction	No	No	—	—
	Without any obstruction	No	No	—	—
Condition of Protective Coating	Outside	2	2	—	—
	Inside	2	2	—	—
Obstruction in Flow (yes, no)		No	No	—	—
Animal Guard Condition		1	1	—	—
Outlet Condition		1	1	—	—
Retarding Pool Elevation (ft. msl) _____ or _____ (ft.)				above	below
Other _____					

COMMENTS _____

1/Looking downstream.

2/Including wave surface, stream, manmade, and livestock crossings

3. EMBANKMENT AND EXCAVATED SLOPES

(Report riprap and vegetation and erosion condition under Items 4 and 5.)

	Dam	Dike	Emergency Spillways ^{1/}		Other	
			left	right	()	()
Sliding or sloughing	<u>2</u>	—	<u>2</u>	—	—	—
Holes (rodent and other) (check especially at embankments)	<u>3</u>	—	<u>1</u>	—	—	—
Excessive settlement (embankments)	<u>3*</u>	—	—	—	—	—
Cracks						
Traverse	<u>1</u>	—	<u>2</u>	—	—	—
Longitudinal	<u>1</u>	—	<u>2</u>	—	—	—
Seepage ^{2/}	<u>1</u>	—	<u>3</u>	—	—	—
Piping ^{2/}	<u>1</u>	—	<u>2/</u>	—	—	—

COMMENTS Ruts in the spillway should be filled. If the spillway operates, ruts in the outlet channel will accelerate erosion. The city should consider fencing

or erecting barriers to keep ATV's out of the spillway and off the dam.

*Fill in low areas on top of the dam.

4. RIPRAP

	Displ. of Rock	Loss of Spalls	Loss of Bedding	Erosion of Found.	Break- down of Rock
Dam					
Upstream berm	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>
Principal Spillway Outlet	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>
Embankment Gutters					
left	—	—	—	—	—
right	—	—	—	—	—
Emergency Spillway					
location	—	—	—	—	—
location	—	—	—	—	—
Waterways					
location Floodway	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>
location Jericho Br.	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>
Outlet Channel	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>	<u>2</u>
Other	—	—	—	—	—

COMMENTS

^{1/}Looking downstream.

^{2/}Check especially at downstream face of embankments.

Operations and Maintenance Inspection Report
Site 1 (Jericho Lake)
DEAD RIVER WATERSHED PROJECT

JUNE 17, 1975

An operation and maintenance inspection of Site 1 (Jericho Lake) in the Dead River Watershed, Berlin, N. H. was conducted on June 17, 1975. The inspection was made by representatives from the local sponsoring organization and the Soil Conservation Service. Included were:

James Smith, City Manager
Maurice Wheeler, Acting City Engineer
Mitchell Berkowitz, Berlin Recreation Director
Calvin Perkins, District Conservationist, USDA, SCS
Charles Dingo, USDA, SCS
Wallace Jolly, USDA, SCS
Thomas Rogers, USDA, SCS
Nick Luhtala, USDA, SCS

Following is a list of items discussed and the necessary action needed:

1. Remove the small amount of debris from the principal spillway trash rack and along the rip-rap material of the dam.
2. Cut the alders and other woody plant growth that is encroaching the emergency spillway and in a few spots along the dam.
3. All roadways through the emergency spillway, along the downstream side of the dam, and across the top of the dam should be seeded and mulched to provide these areas with a vegetative cover.
4. The upstream slope of the dam should be fertilized to encourage a more dense vegetative cover. Apply 10 lbs. per 1000 square feet of 15-10-10 commercial fertilizer. Application should be made as soon as possible to obtain maximum benefit this growing season.
5. The borrow area where the new access road is being constructed is also void of desirable vegetative cover. This area should also be fertilized, but the slope of the dam is the most critical at this time.
6. It was noted the repairs to the spalling on top of the concrete riser have been made.

UNITED STATES DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

Picke Building, 99 Main St., Lancaster, NH 03584

SUBJECT: Operations and Maintenance Inspection -
Dead River Watershed

DATE: May 21, 1974

TO:

Mr., James Smith
City Manager
City Hall
Berlin, New Hampshire 03570

Dear Mr. Smith:

Attached is the annual Operations and Maintenance Inspection Report for the Dead River Watershed conducted on May 17, 1974.

The report lists items that require attention by the City as their obligation under the Operation and Maintenance Agreement of August 26, 1968.

I trust that you will see that these actions are carried out and following completion will send me a letter to that effect.

Sincerely,

Calvin J. Perkins
District Conservationist

cc: M. Wheeler
C. Dirgle
W. Nelson
✓ K. MacPherson

Operations and Maintenance Inspection Report
Site 1 (Jericho Lake)
DEAD RIVER WATERSHED PROJECT
May 17, 1974

An operation and maintenance inspection of Site 1 (Jericho Lake) in the Dead River Watershed, Berlin, NH, was conducted on May 17, 1974. The inspection was made by representatives from the local sponsoring organization and the Soil Conservation Service. Included were:

Maurice Wheeler, Assistant City Engineer
Mitchell Berkowitz, Berlin Recreation Department
Gus Rooney, Member, Berlin Recreation Commission
Keith MacPherson, Design Engineer, USDA, Soil Conservation Service
Calvin J. Perkins, District Conservationist, USDA, Soil Conservation Service

Following is a list of items discussed and the necessary action needed.

1. Remove the accumulation of debris from the principal spillway trash rack and along the rip-rap material of the dam and in the approach to the emergency spillway.
2. Remove the accumulation of bottles and litter at the trash barrels near the top of the dam.
3. Repair the two areas of concrete spalling on top of the principal spillway. Directions for making this repair are contained in a letter from Mr. Dingle of SCS to Mr. Brungot, City Engineer, dated June 26, 1973. (Copy attached)
4. Remove sediment from the entrance to the water circulation pipe at the water control structure.
5. Repair and vegetate wheel track ruts on the downstream slope of the dam to prevent further erosion.
6. Keep vehicles off dam by placing large boulders close together at the pipeline end of dam. Once vehicle traffic across top of dam has stopped then vegetate the top of dam.
7. The most serious item is to develop better vegetative cover in the emergency spillway area and borrow areas adjacent to the spillway. This would be Area II as shown on the original Plan of Vegetation. This area is approximately 20 acres in size and should be fertilized to promote grass growth. Apply 250 lbs./acre of 15-10-10 or closest equivalent. This application should take place immediately to be effective in this growing season. If this is not done erosion will begin to occur and should the emergency spillway function severe problems could occur without the presence of good vegetative cover.
8. A visit to the dike indicated that no maintenance was required at this time.

Ficks Building, 99 Main St., Lancaster, P. H. 03584

October 30, 1973

Mr. Silvio Croteau, Mayor
City of Berlin
City Hall
Berlin, P. H. 03570

Dear Mr. Croteau:

On October 4, 1973 Soil Conservation Service personnel and Maurice Wheeler representing Clarence Brunot visited the Ford River Site # 1, Jericho Lake. During the visit several operational observations were made that require the immediate attention of the city. They are as follows:

1. A stenguide bracket is missing on the inside of the concrete riser. This needs repair or replacement to assure proper functioning of the sluice gate. This equipment was made by:

Coldwell - Wilcox Division
W. S. Rockwell Co.
200 Elliot Street
Fairfield, Conn. 06430

The spare part is a cast iron stenguide bracket, Part # A-307, Drawing No. SM-13b2, (QQ-I-652, Class 30). Refer to Drawing No. C-SF-904 of the original specifications. Please have repaired as soon as possible.

2. There are two areas of spalling on top of the concrete riser. These should be repaired and a letter of June 26, 1973 to Clarence Brunot explains the details of making the repairs. (Copy attached.)

3. The stop logs should be removed from the diversion channel during the winter months. The sections of old metal pipe that have floated into the diversion channel should be removed.

4. The water storage at the site should be sufficient to cover the recreation circulation pipe with at least 4 feet of water before winter to prevent freezing of this pipe system.

I trust that you will see that this work is performed promptly to assure proper functioning of the flood control structure. If I can be of any assistance please contact me.

Sincerely,

Calvin J. Perkins

Calvin J. Perkins
District Conservationist

1 Incl
as

CJP:ir

cc: Clarence Brunget, City Engineer, Berlin
✓ Charles Bingle, SCS, Durham
Walt Nelson, SCS, Durham

Post Office Building, 99 Main St., Lancaster, N. H. 03584

May 24, 1973

Mr. Clarence Brungot
City Engineer
Public Works Department
City Hall
Berlin, N. H. 03570

Dear Mr. Brungot:

Since the City of Berlin will soon be having a change in the City Manager position I am sending the attached annual Operations and Maintenance Inspection Report for the Dead River Watershed to you.

The report list items # 1, 2, 3, 4, 5, 6, that require action by the City of Berlin.

I trust that you will see that these actions are carried out and following completion will send me a letter to that effect.

Sincerely,

Calvin J. Perkins
District Conservationist

CJP:r

cc: C. Dingle, Asst. State Conservationist (W), SCS, Durham, N. H. ✓
W. Jolly, State Conservation Engineer, SCS, Durham, N. H.
W. Nelson, Soil Conservationist, SCS, Durham, N. H.

OPERATIONS AND MAINTENANCE INSPECTION REPORT
of Site 1 (Jericho Lake)
Dead River Watershed Project
May 22, 1973

An operation and maintenance inspection of Site 1 (Jericho Lake) in the Dead River Watershed was conducted on May 22, 1973. The inspection was made by representatives from the local sponsoring organization and the Soil Conservation Service. Included were:

Clarence Brungot, Berlin City Engineer
Maurice Wheeler, Assistant to City Engineer
Walter Nelson, USDA, Soil Conservation Service
Calvin J. Perkins, USDA, Soil Conservation Service

Following is a list of items discussed and the necessary action needed.

1. Remove heavy debris accumulation from principal spillway trash rack and on the rip-rap material along the dam and in the approach to the emergency spillway.
2. Two areas on top of the concrete riser (each about 2 square feet in area) were showing evidence of spalling. These areas were from $\frac{1}{4}$ to $\frac{1}{2}$ inch deep and had water within. Cause of this action is unknown and correction procedure was not decided upon.
3. In general the vegetation looked better than last year. However, it is apparent that legumes will not grow on the exposed upstream slope of dam. Grasses in this area and other flat areas is present but appeared to need fertilization. Suggested fertilizing a total of 11 acres with 20-10-10 at a rate of 200 lbs./acre. Downstream slope of dam has good legume and grass cover.
4. Clean debris from water control structure, retrieve stop logs that are in downstream channel, and remove sections of old steel pipe in upstream and downstream channel.
5. Slight bank erosion at end of rip-rap on left side of channel below water control structure. This should be watched closely and if conditions increase the rip-rap should be extended.
6. Old road along base of dam should be seeded to prevent erosion and discourage use of this area by unauthorized vehicles.
7. No vegetation on top of dam, however, it appeared that this was causing no problem.
8. Impossible to control vehicle traffic to the site. Cable at gate on Route 110 is destroyed as fast as it is installed.

9. Although records indicate that a plaque was ordered by Water Resources Board in 1971 there is no evidence of installation. The question of who is responsible for installation was brought up but could not be answered.

10. Inclement weather prohibited a visit to the dike area. Mr. Brangot stated that the dike was in good vegetative cover and that brush was not encroaching on same.

Piche Building, 99 Main St., Lancaster, N. H. 03584

June 26, 1972

Mr. Joseph Burke
City Manager
City Hall
Berlin, N. H. 03570

Dear Mr. Burke:

Attached is the annual Operations and Maintenance Inspection Report for the Lead River Watershed conducted on June 20, 1972.

The report lists items # 1 and 2 that require maintenance work by the local sponsors.

Following completion of the work please forward me a letter to that effect.

Sincerely,

Enclosure

Calvin J. Perkins
District Conservationist

cc: C. Brungot, Public Works Superintendent, Berlin, N. H. 03570
C. Dingle, Asst. State Conservationist (W), SCS, Durham, N. H. 03824

Operations and Maintenance Inspection Report

of Site 1 (Jericho Lake)

Dead River Watershed Project

JULIE 20, 1972

An operation and maintenance inspection of Site 1 (Jericho Lake) in the Dead River Watershed was conducted on June 20, 1972. The inspection was made by representatives from the local sponsoring organization and the Soil Conservation Service. Included were:

Mayor Sylvio Croteau, Berlin
Joseph F. Burke, Berlin City Manager
Maurice Wheeler, Berlin
Calvin J. Perkins, USDA, Soil Conservation Service

Following is a list of items discussed and the necessary action needed.

1. Remove debris from principal spillway and on the rip-rap material along the dam.

2. Remove stones under planks at the water control structure in the Jericho Brook channel plus the section of metal pipe that floated downstream and lodged at the structure.

3. Vegetation is not good on upstream slope of dam but may improve during summer growth period. Good vegetation on downstream slope of dam. Winter kill of vegetation is apparent on the downstream flat areas and in the emergency spillway and adjacent borrow area. There is no present damage being done by the lack of vegetation cover but this bears a close watch.

4. The top of the dam is being used extensively by vehicular traffic of various types. They enter onto the dam via the City pipeline and this type of traffic is almost impossible to control. All traffic at the main entrance to the site has been stopped except for ATV and similar two-wheeled transportation. With so much traffic on the top of the dam it is void of vegetation but this is not causing any problems at the present time.

OPERATIONS & MAINTENANCE INSPECTION REPORT
OF SITE 1 (JERICHO LAKE)
DEAD RIVER WATERSHED PROJECT

June 9, 1971

An operation and maintenance inspection of Site 1 (Jericho Lake) in the Dead River Watershed was conducted on June 9, 1971. The inspection was made by representatives from the local sponsoring organizations and the Soil Conservation Service. Included were:

Clarence Brungot, City of Berlin
Forrest Hodgdon, N. H. Water Resources Board
Peter Merkes, N. H. Water Resources Board
Henry Stamatel, USDA, Soil Conservation Service
Charles Brown, USDA, Soil Conservation Service
Ray Wenninger, USDA, Soil Conservation Service
Edward Hutchinson, USDA, Soil Conservation Service
Charles Holden, USDA, Soil Conservation Service
Walter Zwearcan, USDA, Soil Conservation Service

Following is a list of items discussed and the necessary action needed.

1. The dike was in good repair with an excellent vegetative cover established. Woody plant growth should be controlled in the future by either mowing or use of spray.
2. Trash to be cleaned away from the principal spillway and along the dam at the water edge. The N. H. Water Resources Board agreed to take care of this item.
3. Two washouts on the back side of the dam above the principal spillway pipe need repair. The City of Berlin agreed to make this repair by filling and seeding the washout holes. Also to remove stones and smooth out material down slope from the washouts.
4. Inspection of dam, floodway, emergency spillway and borrow area indicated no need for maintenance at this time.

Being early in the growing season, it was difficult to determine the quality of the grass cover. It is possible that there will be a need for fertilizing some of these areas another year.

5. There was no vegetative cover in wheel tracks over the entire length of the dam. This condition will continue to exist until vehicle traffic can be controlled. The condition, however, was not considered harmful to the dam.

Piche Building, 99 Main Street, Lancaster, New Hampshire 03584

June 30, 1971

Mr. Clarence Brungot
Public Works Superintendent
City Hall
Berlin, New Hampshire 03570


Dear Mr. Brungot:

Attached is the annual Operations and Maintenance Inspection Report for the Dead River Watershed conducted on June 9, 1971.

The report lists two items on Site 1 that require maintenance work by the local sponsors.

Following completion of the work, please forward me a Letter of Certification and the approximate cost for doing the work. The cost information will be helpful to us in estimating operation and maintenance in future projects.

Sincerely,



Edward F. Hutchinson
District Conservationist

Enclosure - O&M Inspection Report
Site 1, Dead River Watershed Project

cc: Coos Conservation District, Lancaster, N. H.
C. Dingle, Asst. State Conservationist (W), Soil
Conservation Service, Durham, New Hampshire

✓USDA:SCS: E. F. Hutchinson:hs

*5/11/77 Inspection
Report*

Piche Building, 99 Main Street, Lancaster, New Hampshire 03584

June 30, 1971

Mr. Peter Merkes
New Hampshire Water Resources Board
Concord, New Hampshire 03301

Dear Mr. Merkes:

Attached is the annual Operations and Maintenance Inspection Report for the Dead River Watershed conducted on June 9, 1971.

The report lists two items on Site 1 that require maintenance work by the local sponsors.

Following completion of the work, please forward me a Letter of Certification and the approximate cost for doing the work. The cost information will be helpful to us in estimating operation and maintenance in future projects.

Sincerely,

Edward F. Hutchinson
District Conservationist

Enclosure - O&M Inspection Report
Site 1, Dead River Watershed Project

cc: ☒ Coos Conservation District, Lancaster, N. H.
C. Dingle, Asst. State Conservationist (W), Soil
Conservation Service, Durham, New Hampshire

☒ USDA:SCS: E. F. Hutchinson:hs

B-30

U.S. DEPARTMENT OF AGRICULTURE - SOIL CONSERVATION SERVICE

DESIGN REPORT SUMMARY

I. Watershed Data

A. Structure Class C
 B. Drainage Area 41.47 Ac.
 C. Time of Concentration - T_c 2.4 Hrs.*
 D. Hydrologic Curve Number - C_n
 1. Moisture Condition II* 68
 2. Moisture Condition III* 85

II. Principal Spillway

A. Conduit
 1. Inside Dia. 42 In.
 2. Length 204.33 Ft.
 B. Riser
 1. Inside Dimensions 3.5 X 10.5 Ft.
 2. Height (Floor to Crest) 29.0 Ft.
 C. Weir Length 31.0 Ft.
 D. Orifice Dimensions 2-24 X 32 In.
 E. Reservoir Drain Size 30 In.
 F. Type of Energy Dissipater PLUNGE POOL

III. Emergency Spillway

A. Width 100 Ft.
 B. Side Slopes 4:1 EARTH 11:1 ROCK
 C. Length of Level Section 60 Ft.
 D. Exit Slope 1:4 Ft./Ft.
 E. Max. Velocity in Exit Section @ D.H.W. 2.23 Ft./Sec.
 F. Duration of Flow thru Emer. Spillway @ D.H.W. 4.2 Hrs.
 G. Frequency of Use LESS THAN ONCE IN 100 YRS

IV. Earth Fill

A. Height 46 Ft.
 B. Volume C.Y.
 C. Compaction ZONES 2, 3, 4, 5 - CLASS V
 ZONES 1 - CLASS A

FILL PLACEMENT

* AS PER WORK PLAN

BY

This multiple-purpose dam is located in Coos County, New Hampshire, on the Jerico Brook tributary of the Dead River. The site is approximately four miles northwest of Berlin, New Hampshire.

Sheet 4 of this report, together with the Mt. Washington, New Hampshire, 15-minute quadrangle published by the U. S. Geological Survey, may be used to locate the structure more definitely.

A summary of pertinent design information is given on sheet 2 of this report.

This is the only proposed floodwater retarding dam in the Dead River Watershed. This will be a multiple-purpose structure designed to retard a 100-year frequency storm without discharge occurring in the emergency spillway.

The results of the hydrologic and hydraulic computations are given on sheet 3 of this report.

The primary structure consists of a zoned compacted earthfill with a cutoff through alluvium, glacial till, and decomposed rock to firm bed-rock. A drainage system is located under the downstream portion of the earthfill to control the phreatic surface and to collect seepage.

The principal spillway is a drop inlet, closed conduit structure consisting of a two-stage, reinforced, concrete riser, 42-inch diameter reinforced concrete water pipe, and a riprapped plunge pool.

The emergency spillway is designed as an earth and rock cut in the left abutment. An engineering cost analysis was performed which resulted in the least combined cost of fill and emergency spillway rock excavation.

V I

DESIGN REPORT

DEAD RIVER
WATERSHED PROJECT
SITE 1
COOS COUNTY
NEW HAMPSHIRE
U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

INDEX

GENERAL
LAYOUT
HYDRAULICS
GEOLOGY
SOIL TESTING
E. & F. DESIGN
STRUCTURAL
QUANTITIES
SPECIFICATIONS

Henry S. Stamatel
January 26, 1971
Page 6

Modification No. 4 was issued to provide for over-runs in common excavation, rock excavation, and floodway rock excavation.

Modification No. 5 was issued to provide for over-runs in concrete for the circulation pipe and rock excavation for the circulation pipe.

Modification No. 6 was issued to provide for the construction of a concrete cut-off wall adjacent to the left pier of the drop structure. This was deemed necessary to minimize abutment leakage around the drop structure.

Modification No. 7 was issued to provide for an over-run in riprap for the diversion channel.

Modification No. 8 was issued to allow compensation for a claim submitted by the contractor on Bid Item 8 and Bid Item 16. The contractor based his claim on changed conditions on both items. Bid Item 8 was excavation for the circulation pipe. Backfilling of this item was subsidiary to the excavation item. It was designated that the excavation be backfilled with selected granular material around the pipe. The material contained a great deal of cobbles and boulders making it extremely difficult to provide suitable granular backfill. Granular backfill was obtained from another source with Modification No. 8 providing compensation for additional cost incurred by increased haul distance.

Bid Item 16 was earthfill. Bedrock was exposed above grades shown on the plans creating a shortage of fill. The borrow area had to be expanded in order to obtain the necessary material. The contractor claimed a changed condition due to the presence of the ledge and filed for compensation due to lost efficiency and extra wear on equipment, etc., due to working on bedrock and the confined area of the expanded borrow area. Compensation was granted for approximately one half of the amount claimed. Presently the Contracting Officer's final decision is pending. It appears as though the contractor will have to go to the courts in order to obtain any further compensation.

The contractor completed the job well within the allotted time. He actually worked during a 206 calendar day period out of 341 calendar days.

Arthur N. Luhtala
Project Engineer

ANLUHTALA:pak

Henry S. Stamatel
January 26, 1971
Page 5

At first the contractor attempted to place the drain fill around a form constructed out of sheet steel and angle iron that was to be dragged along the trench by a bulldozer. This method did not prove to work. It was extremely difficult to keep the form moving along the centerline of the trench and when there was drain pipe in the form the friction of drain fill particles tended to keep the entire unit moving as one solid mass. This approach was then abandoned and plywood panels were used to complete the job.

The drain fill was supplied by Lessard Sand and Gravel from Gorham, New Hampshire, although the fine drain fill was trucked from Guildhall, Vermont.

The principal spillway pipe was furnished by Interpace Corporation, Wharton, New Jersey. The pipe was a 42" pre-stressed cylinder pipe (SP-5) double wrap.

Northeastern Culvert Corporation of Westminster, Vermont, supplied the bituminous coated corrugated metal pipe and the trash racks.

Bancroft and Martin, Inc., of South Portland, Maine, supplied the reinforcing steel, cast iron and asbestos cement pipe along with the appurtenances for the circulation system.

Coldwell-Wilcox Company, a division of W. S. Rockwell Company, Fairfield, Connecticut, supplied the back pressure gate.

The E. L. LeBaron Foundry Company of Brockton, Massachusetts, supplied the manhole assembly.

The quality of furnished materials was very good.

The contractor's overall performance was excellent. The experience, equipment, organization and supervision provided was of high quality. The relations between SCS and the contractor were excellent. The Service should not hesitate in awarding future contracts to this contractor.

Eight (8) modifications were issued on this job. Modification No. 1 resulted due to an over-run in the quantity of reinforcing steel and a change in drain trench dimensions. The width of the drain trench had to be increased in order that the flow area required by design be maintained.

Modification No. 2 was issued to apply vegetative treatment on the dike and related areas.

Modification No. 3 was issued to provide plugs for the access tees of the circulation pipe. These were apparently overlooked in quantity summaries.

Henry S. Stamatel
January 26, 1971
Page 4

Available land rights forced the borrow pit extension into an area where excavation was very difficult. This area was located on the northwest border of Borrow Area A. Numerous boulders and the presence of bedrock caused the extreme difficulty. If it had been possible to extend the pit in a northerly direction, I believe that this would have been a more favorable source. This area was not as confined and it appeared as though there was less oversize material present.

In future contracts that require considerable quantities of fill, I suggest that borrow areas be designed to supply at a minimum one and one half times the estimated fill requirement. It is easier to make a borrow area smaller during construction operations than it is to make it larger.

Shrinkage factors, excess amounts of unsuitable material from borrow pits, and other unforeseen factors warrant the need for adequate quantities of available borrow on any particular job.

The concrete was supplied by Brideau Ready Mix of Berlin, New Hampshire.

Six (6) concrete cylinders were broken after seven (7) days with an average strength of 3,400 psi. The minimum seven day break was 2,860 psi and the maximum was 3,750 psi.

Eighteen (18) concrete cylinders were broken after twenty-eight (28) days with an average strength of 4,310 psi. The minimum twenty-eight day break was 3,600 psi and the maximum break was 5,340 psi.

The drainage system for this job consisted of a four (4) foot wide trench drain with a double drain filter. The coarse drain fill was encased by an eight (8) inch layer of fine drain fill. It was extremely difficult to maintain this eight-inch layer with any uniformity due to the nature of the existing foundation soils. Numerous boulders and cobbles are typical of many New Hampshire soils. In the future I suggest that designers allow a minimum of one (1) foot for fine drain fill in a double filter design. This would be much easier to control in the field, allowing placement with less chance of contamination. Contamination appeared to be the most difficult thing to control in placement of the fine drain fill.

Plywood forms were utilized in placement of the drain fill. As drain fill was placed around the plywood sections, the forms would be raised and back filled again. A grad-all proved to be an extremely versatile machine for this operation because of the ability to tilt the bucket in all directions.

Henry S. Stamatel
January 26, 1971
Page 3

Borrow sources on the job were infested with boulders and oversize material. Specifications allowed the use of material up to eighteen (18) inches in size. A large vibratory roller, as specified by construction specifications, attained required compaction with reasonable efficiency.

The material in borrow areas was very dense. Double pushing of scrapers and on occasions triple pushing was utilized in loading operations. Along with ripping this provided for an efficient earth moving operation. It is estimated that ten thousand (10,000) cubic yards per day was moved on occasion. The average production was in the range of thirty-five hundred (3500) cubic yards per day.

A total of seventy-six (76) compaction tests were made. Eleven (11) tests showed compaction below an acceptable density. Most of the unsatisfactory tests resulted with material being on the dry side of optimum. This necessitated adding water to the fill to obtain satisfactory densities.

Zone 1 required a minimum density of 95% of Standard Proctor. Eighteen (18) tests were taken with only two (2) failing. The average of all acceptable densities was 101.2% of Standard Proctor.

Zones 2, 3, 4 and 5 required class V compaction as defined by construction specification 5. In the field this was evaluated by Standard Proctor control due to the nature of the material. The soil had enough silt so that a definite sharp crested Proctor curve could be established. Ninety-five (95) percent of Standard Proctor was considered as acceptable.

In Zones 2 and 3, fifty-two (52) tests were taken with only eight (8) failing to meet 95%. The average of all acceptable densities was 100.5% of Standard Proctor.

In Zones 4 and 5, of the dike, six (6) tests were taken with only one (1) test failing. The average of all acceptable densities was 105.3% of Standard Proctor.

A shortage of earth fill developed on the job. Bedrock appeared at elevations above the grades shown in the plans in Borrow Area A, the major borrow source, thus decreasing the amount of available fill. Another factor was that approximately seventeen thousand (17,000) cubic yards of muck had to be removed from the foundation instead of an anticipated two thousand (2,000) cubic yards. This resulted in excavating Borrow Area A deeper than expected along with having to extend the pit beyond the limits indicated on the plans.

Henry S. Stamatel
January 26, 1971
Page 2

The contract provided for two hundred and eighty (280) calendar days of performance time to complete the work. Work commenced on May 26, 1969. A winter shutdown was issued on December 11, 1969, with approximately ninety-nine (99) percent of the work complete. The contractor used just over sixty-eight (68) percent to perform this amount of work. Performance time again commenced on June 15, 1970, with all remaining construction being completed between August 17, 1970, and August 28, 1970. The final value of the contract was \$651,100.59.

In addition to winter shutdowns, the contractor's work was suspended because of weather for a total of five (5) days, all occurring during November 1969. The contractor was also granted sixty-one (61) additional days of performance time due to contract modifications.

Personnel directly concerned with the work were as follows:

Vernon A. Knowlton, Contracting Officer, New Hampshire Water Resources Board, Concord, New Hampshire
Norman A. McDermott, Project Manager, Rogers Construction Co., Inc., Brattleboro, Vermont
Glenm Gibbs, General Superintendent, Rogers Construction Co., Inc., Brattleboro, Vermont
Walter J. Zwearcan, Government Inspector, Soil Conservation Service, Berlin, New Hampshire
Daniel P. Preece, Alternate Government Inspector, Soil Conservation Service, Plymouth, New Hampshire
Arthur N. Luhtala, Government Representative and Project Engineer, Soil Conservation Service, Berlin, New Hampshire

Other personnel were assigned to the job from time to time as required for assistance in inspection and layout work.

The contractor furnished good equipment for the job. The major items of equipment include:

- a. Crawler tractors: Two D-8H's with ripper attachments, 82-40, D-7, D-5, JD-450, and other tractors as needed.
- b. Rubber-tired dozers, Cat. 334-B and 324-B.
- c. Front end loader, Cat. 988.
- d. Backhoes, Reehring 1 yd³, Drott 40, Dynahoe 160, and Grad-all backhoes.
- e. SPV-7 vibratory roller.
- f. Cat. 147 road grader.
- g. 4-Terex TS-24 double barreled scrapers.
- h. Gardner Denver 900 cfm wagon drill.
- i. 6 large dump trucks (10-15 cu.yd. capacity).
- j. Miscellaneous equipment such as a water wagon, pumps, small compressor, vibrating and tamping hand compactors, chain saws, sand blasting equipment, and other necessary equipment as required.

Plymouth, N.H..

ENG - Construction Report, Site No. 1, Dead
River Watershed

January 26, 1971

Henry S. Stamatal
State Conservation Engineer
Soil Conservation Service
Durham, New Hampshire 03824

The location of this site is in northern New Hampshire in the city of Berlin, Coos County. This dam is a multiple purpose dam with recreation being the secondary purpose. The job was contracted by the New Hampshire Water Resources Board under Project Agreement No. 12-10-270-75. The City of Berlin and the Coos County Soil Conservation District were sponsors of the work.

The City of Berlin cost shared 23.46% of the costs incurred by construction of the dam and dike, with the Soil Conservation Service paying the remaining 76.54% of the costs. The City of Berlin and SCS cost shared on a 50-50 basis on construction of the circulation system which is considered as a basic recreation facility. The floodway was constructed with SCS paying 100% of the costs because the intended nature is specifically for flood control purposes.

A public viewing of the site was conducted on January 21, 1969. The unique thing about this viewing was that snow machines were required for access to this remote site. Snow depths of seven feet or more on the level were reported at the time of the site showing.

Bids for this job were opened on February 7, 1969. The following shows the bidders and the amount of their respective bids:

Rogers Construction Co., Inc., Brattleboro, Vt.	\$564,602.39
Caledonia, Inc., St. Johnsbury, Vermont	736,956.00
Cappy-Simone, Inc., Freeport, Long Island, N.Y.	747,442.10
Welch & Corr Construction Corp., West Springfield, Massachusetts	774,347.30
Weaver Brothers Construction Co., Inc., Concord, NH	834,996.05

The engineer's estimate was 566,996.55

Contract No. WRB-SCS-26 was awarded to Rogers Construction Company, Inc. of Brattleboro, Vermont, on February 27, 1970.

V RECORDS

The Sponsor will maintain in a centralized location a record of all inspections performed both individually and jointly by the Sponsor and the Service, and of all significant actions taken by the Sponsor with respect to operation and maintenance. The Service may inspect these records at any reasonable time.

VI, GENERAL

A. The Sponsor will:

1. Prohibit the installation of any structures or facilities that will interfere with the operation or maintenance of the structural measures.
2. Obtain prior Service approval of the Plans and Specifications for any alteration or improvement to the structural measures.
3. Obtain prior Service approval of any agreement to be entered into with other parties for the operation or maintenance of all or any part of the structural measures, and provide the Service with a copy of the agreement after it has been signed by the Sponsor and the other party.

B. Service personnel will be provided the right of free access to the structural measures at any reasonable time for the purpose of carrying out the terms of this Plan.

C. The responsibilities of the Sponsor under this Plan are effective simultaneously with the acceptance of the works of improvement in whole or in part.

III ESTABLISHMENT PERIOD (continued 2)

resulting from major erosion damage, (4) major revegetation due to failure to obtain an adequate vegetative cover, and (5) restoring areas with significant erosion caused by unusual flow (volume, recurrence or extended period of time) in emergency spillways.

- F. No action with respect to needed repairs during the Establishment Period will be taken by the Sponsor or the Service which would lessen or adversely affect any legal liability of any contractor or his surety for payment of the cost of the repairs.

IV INSPECTIONS AND REPORTS

- A. During the Establishment Period the Sponsor and the Service will jointly inspect the structural measures at least annually and after unusually severe floods or the occurrence of any other unusual condition that might adversely affect the structural measures. It is desirable the annual inspections be performed during the month shown below. Any supplemental inspections then determined necessary will be scheduled and agreed to at that time.

May

(Month)

- B. After the Establishment Period the structural measures will be inspected annually by the Sponsor, preferably during the month shown below, and after unusually severe floods or the occurrence of any other unusual condition that might adversely affect the structural measures.

May

(Month)

- C. After the Establishment Period the Service may inspect the structural measures at any reasonable time.
- D. A written report will be made of each inspection. The report of joint inspections will be prepared by the Sponsor with the assistance of the Service. A copy of each report will be provided by the party preparing the report to the other party within ten days of the date on which the inspection was made.

III ESTABLISHMENT PERIOD (continued)

2. Repairs determined by the Service to have been occasioned by improper operation or maintenance, or both.
 3. Repairs applicable to municipal or industrial water supply or to any other purpose for which construction costs are not authorized to be paid for in whole or in part with funds appropriated to the Service.
 4. Repairs that are mutually determined by the Sponsor and the Service as being items of normal maintenance rather than major repair and are not therefore in keeping with the spirit and intent of the Establishment Period provisions.
- B. The Establishment Period for structural measures (exclusive of any associated vegetative work) is a period of three years ending at midnight on the third anniversary of the date on which the structural measure is accepted.
- C. The Establishment Period for vegetative work associated with a structural measure is a period from date of acceptance of the initial vegetative work to midnight of the date on which the Service writes the Sponsor advising that an adequate vegetative cover has been obtained. However, this period shall not exceed two growing seasons or the end of the Establishment Period for the associated structural measure whichever is greater in time.
- D. As used in the two preceding paragraphs, and elsewhere in this Plan, the following words have the meanings described below:
- ACCEPTED, ACCEPTANCE: The date structural or vegetative measures are accepted from the contractor when a contract is involved, or the date structural or vegetative measures are completed to the satisfaction of the Service when force account operations are involved.
- ADEQUATE VEGETATIVE COVER: A minimum of seventy percent (70%) cover of the desirable species, with no active rilling that cannot be controlled by the vegetation.
- E. Major repair may involve such things as (1) repairing separated joints, cracks or breaks in the principal spillway, (2) correcting seepage, (3) replacing significant backfill around structures

OPERATION AND MAINTENANCE PLAN

I OPERATIONS

- A. The Sponsor will be responsible for and will operate or have operated without cost to the Service the structural measures in compliance with any applicable Federal, State and local laws, and in a manner that will assure that the structural measures will serve the purpose for which installed as set forth in the Work Plan.
- B. The Service will, upon request of the Sponsor and to the extent that its resources permit, provide consultative assistance in the operation of the structural measures.

II MAINTENANCE

- A. The Sponsor will:
 - 1. Be responsible for and promptly perform or have performed without cost to the Service except as provided in Paragraph III, Establishment Period, all maintenance of the structural measures determined by either the Sponsor or the Service to be needed.
 - 2. Obtain prior Service approval of all plans, designs and specifications for maintenance work involving major repair.
- B. The Service will, upon request of the Sponsor and to the extent that its resources will permit, provide consultative assistance in the preparation of plans, designs and specifications for needed repair of the structural measures.

III ESTABLISHMENT PERIOD

- A. During an Establishment Period, as herein defined, the Service will bear such part of the cost of any needed major repairs to the structural measures, including associated vegetative work, as is proportionate to the original construction costs borne by the Service in the construction of the structural measures except that the Service will not bear any of the cost for:
 - 1. Repairs to channels or portions thereof which do not have permanent linings such as concrete, riprap, or grouted rock.

OPERATION AND MAINTENANCE AGREEMENT
FOR
STRUCTURAL MEASURES

THIS AGREEMENT made on August 26, 1968 is between the Soil Conservation Service, United States Department of Agriculture, hereinafter referred to as the Service, and the following organizations, hereinafter referred to as the Sponsor:

City of Berlin, New Hampshire
Coos County Conservation District

The Sponsor and the Service agree to carry out the plan on the attached four pages for the operation and maintenance of structural measures in the Dead River Watershed Project, State of New Hampshire. The measures covered by this agreement are identified as:

one multiple purpose structure plus Jericho Brook diversion channel, diversion dike and floodway, known as Site No. 1, Dead River Watershed, located in Berlin, Coos County, New Hampshire, along Jericho Brook approximately 1.3 miles west (upstream) of the intersection of Route #110 and Jericho Brook.

Name of Sponsor City of Berlin, New Hampshire
By E. F. Gago Title Mayer

This action was authorized at an official meeting of the Sponsor named immediately above on August 26, 1968 at Berlin, New Hampshire

Attest W. H. [Signature] Title City Clerk

Name of Sponsor Coos County Conservation District
By Edwin C. Luzzell Title Chairman

This action was authorized at an official meeting of the Sponsor named immediately above on Aug 31, 1968 at Berlin, N.H.


Attest William E. [Signature] Title Secretary (Pro Tem)

Soil Conservation Service, United States Department of Agriculture

By [Signature] Title State Conservationist


U. S. DEPARTMENT OF AGRICULTURE - SOIL CONSERVATION SERVICE

DEAD RIVER WATERSHED
MULTIPLE PURPOSE DAM - NO. 1
COOS COUNTY
NEW HAMPSHIRE



Reference:


U.S.G.S. 15' Quadrangle
Mt. Washington, New Hampshire



STATE <u>NH</u>		PROJECT _____			
BY <u>RW</u>	DATE _____	CHECKED BY _____	DATE _____	JOB NO. <u>NH-772-L</u>	
SUBJECT <u>LAYOUT CONTENTS.</u>				SHEET _____ OF _____	

ITEM	SHEET NO.
LOCATION OF POST @ RANGE	
PRINCIPAL SPILLWAY LAYOUT	
EM, SPILLWAY CURVE DATA	
ANGLE BETWEEN DAM & $\frac{1}{2}$ $\frac{1}{2}$	

STATE	N.H.	PROJECT	Dead A. Site 1		
BY	HSS	DATE	2/26/68	CHECKED BY	RW
		DATE	2-28-68	JOB NO	NH-770P
SUBJECT	Location of Post @ Range 344 & Lot 1415 with respect to Base Line of Survey @ Dam				SHEET ____ OF ____



$$\alpha = 200^\circ + 180^\circ - 338^\circ 22' = 41^\circ 38'$$

$$L = 189.5 \sin 41^\circ 38' \\ = 189.5 \times 0.66436 = 125.896 \text{ SAY } 125.9$$


$$d = 189.5 \cos 41^\circ 38' \\ d = 189.5 \times 0.74741 = 141.634 \text{ SAY } 141.6$$

Station of Post along ~~B~~ of Survey

$$\text{Station } (49+40) + 141.6 = 50+81.6$$

B-49

STATE IL PROJECT DEAD RIVER SITE
BY P.W. DATE 6-19-62 CHECKED BY RAW DATE 7/2/65 JOB NO. 115-700-L
SUBJECT PRINCIPAL SPILLWAY LAYOUT SHEET 1 OF 1



$$M = \frac{L}{800} (G_1 - G_2) = \frac{178}{800} (0.00 + 1.953) = .312$$

$$Z_3 = M \frac{0.2}{(4/2)^2} = .312 \frac{256}{4096} = .019$$

$$Z_4 = .312 \frac{1024}{4096} = .078$$

$$Z_5 = .312 \frac{2304}{4096} = .176$$

$$Z_6 = .312 \frac{4096}{4096} = .312$$

$$Z_7 = .312 \frac{6144}{4096} = .488$$

$$Z_8 = .312 \frac{8704}{4096} = .702$$

$$Z_9 = .312 \frac{11872}{4096} = .956$$

$$Z_{10} = .312 \frac{15648}{4096} = 1.248$$

NOTE: ABOVE DIMENSIONS FOR
LENGTHS OF PIPES ARE BASED
ON NOMINAL LENGTHS.

JOINT NO.	DISTANCE FROM FACE OF RISER	INVERT OF CONDUIT
J-1	0.33	1327.00
POYC J-2	12.33	1327.00
J-3	28.33	1326.98
J-4	44.33	1326.92
J-5	60.33	1326.82
J-6	76.33	1326.70
J-7	92.33	1326.51
J-8	108.33	1326.30
J-9	124.33	1326.04
PT J-10	140.33	1325.75
J-11	156.33	1325.44
J-12	172.33	1325.12
J-13	188.33	1324.71
OUTLET	204.33	1324.30

B-50

STATE <u>NEW HAMPSHIRE</u>	PROJECT <u>DETID RIVER WATERSHED PROJECT</u>		
BY <u>RWM</u>	DATE <u>12/28/67</u>	CHECKED BY <u>SMW</u>	DATE <u>6-18-68</u>
SUBJECT <u>EM. SP. CURVE DATA (INLET)</u>			JOB NO. <u>SITE 1</u>
			SHEET <u>1</u> OF <u>2</u>

$$1. \Delta = 37^\circ \quad \frac{\Delta}{2} = 18^\circ 30'$$

$$2. R = 125'$$

$$3. D = \frac{5729.65}{R} = \frac{5729.65}{125} = 45.83720$$

$$4. L = 100 \left(\frac{\Delta}{D} \right) = 100 \frac{37}{45.8372} = 80.72 = \underline{80.72}$$

$$5. T = R \tan \frac{\Delta}{2} = (125)(.33460) = 41.825 = \underline{41.82}$$

$$6. E = R \operatorname{EXSEC} \frac{\Delta}{2} = (125)(.05449) = 6.81125 = \underline{6.81}$$

$$7. M = R \operatorname{VERS} \frac{\Delta}{2} = (125)(.05168) = 6.46 = \underline{6.46}$$

$$8. LC = 2 R \sin \frac{\Delta}{2} = (250)(.31730) = 79.325 = \underline{79.33}$$

$$d_{100} = \frac{18^\circ 30'}{80.720} = 22.91873^\circ$$

$$d_1 = .2291873^\circ$$

$$d_{25} = (.2291873)(25) = 5.72968 = 5^\circ 43'.78$$

$$d_{5.72} = (.2291873)(5.72) = 1.3109^\circ = 1^\circ 18.7'$$

$$C_{25} = 2 R \sin d_{25} = (250)(.044835) = 24.96'$$

$$C_{5.72} = 2 R \sin d_{5.72} = (250)(.02260) = 5.65'$$

Station	Chord in feet	Deflection Δ in degrees	Deflection Δ in deg. & min
P.C. 3+00	—	0.000	0°-00'
3+25	24.96	5.729	5° 44'
3+50	24.96	11.458	11° 28'
3+75	24.96	17.187	17° 12'
P.T. 3+80.72	5.72	18.498	18° 30'
PI = (3+00) + 41.82 = 3+41.82			
B-51			

STATE NEW HAMPSHIRE		PROJECT DEAD RIVER WATERSHED PROJECT	
BY RWI	DATE	CHECKED BY RW	DATE 6-18-68
SUBJECT EM SPILLWAY CURVE DATA (OUTLET)		JOB NO. SITE 1	
		SHEET 2 OF 2	

1. $\Delta = 35^\circ \quad \frac{\Delta}{2} = 17^\circ 30'$
2. $R = 250'$
3. $D = \frac{5729.65}{250} = 22.9186$
4. $L = 100\left(\frac{\Delta}{D}\right) = 100 \frac{35}{22.9186} = 152.7144$
5. $T = R \tan \frac{\Delta}{2} = (250)(.31530) = 78.825$
6. $E = R \operatorname{EXSEC} \frac{\Delta}{2} = (250)(.04553) = 11.3825$
7. $M = R \operatorname{VERS} \frac{\Delta}{2} = (250)(.04628) = 11.570$
8. $LC = 2R \sin \frac{\Delta}{2} = (500)(.30071) = 150.355$

$$d_{100} = \frac{\Delta}{2} = L = \frac{152.7144}{152.7144} = 11.45932$$

$$d_1 = .1145932$$

$$d_{25} = (.1145932)(25) = 2.8647 = 2^\circ 51.9' \checkmark$$

$$d_{7144} = (.1145932)(2.7144) = 0.31104 = 0^\circ - 18.7' \checkmark$$


$$C_{25} = 2R \sin d_{25} = (500)(.04998) = 24.99 \checkmark$$

$$C_{7144} = 2R \sin d_{7144} = (500)(.00544) = 2.715 \checkmark$$

Station	Chord in feet	Deflection δ in degrees	Deflection δ in degrees & minutes
PC 9+00	—	0.000	0° - 0'
9+25	24.99	2.8647	2° - 52' ✓
9+50	24.99	5.7294	5° - 44'
9+75	24.99	8.5941	8° - 36'
10+00	24.99	11.4588	11° - 28'
10+25	24.99	14.3235	14° - 19'
10+50	24.99	17.1882	17° - 11'
10+52.72	2.72	17.4992	17° - 30'
		B-52	


STATE NEW HAMPSHIRE		PROJECT SEAD RIVER WATERSHED			
BY DMA	DATE 9/18/68	CHECKED BY	DATE	JOB NO NH-770-P	
SUBJECT Angle between Dam & E of R					SHEET 1 OF

I LEFT ABUTMENT



$$\tan \alpha = \frac{100}{700} = .142857 = 8^{\circ}07'-48''$$

II RIGHT ABUTMENT



$$\tan \theta = \frac{100}{500} = .20000 = 11^{\circ}18'-36''$$

STATE	NH	PROJECT	Deer River Ws. Site 1	
BY	HSS	DATE	12/15/67	CHECKED BY
SUBJECT		DATE		JOB NO.
				NH 770
		SHEET 4 OF		

General Considerations:

Drilling & Geologic Investigations have shown more extensive bedrock in the Emergency Spillway sites than was anticipated at the time the Watershed Work plan was prepared.

This finding dictates the Emergency spillway be raised & narrowed to reduce costly rock excavation. Studies were made to obtain optimum costs between rock excavations and extra fill caused by increased fill heights.

The studies showed the most economical combination to be: the alignment selected with a crest elevation of 1362.0 and an emergency spillway width of approx. 100 feet.

In the Watershed Work Plan the principal spillway was planned using a 1 stage inlet. In this design a two stage inlet was used for the following reasons:

A. TRASH PROBLEM

1. The flood pool is very wooded and is expected to produce much trash.
2. Beavers inhabit the general site area and are usually attracted to PL 566 impoundments. They can be expected to make attempts at modifying water levels.
3. The two stage inlet allows use of the modified grating type trash rack at the low stage particularly when beavers drop trash into the riser. When the beavers are not active, the gratings are to be removed.
4. The two stage trash rack gives more trash area before the principal spillway becomes

STATE	N. H.	PROJECT	Dead River U.S. Site 1
BY	HSS	CHECKED BY	
DATE	12/15/67	DATE	
SUBJECT		JOB NO	NH-770
		SHEET	5 OF

interval between clogging of the stages
5. The site is relatively remote during the snow season so that inspections may become limited.

6. A 2 stage inlet has desirable trash features.

B. ECONOMICS

1. The two stage alternative raises the water levels a small amount. However, the bedrock in the emergency has made raising the E.S. Crest an economical measure in any case. The increase in water level caused by the 2 stage alternative does not result in any additional cost in fill.

2. The cost of additional concrete & trash rack cost is considered worth while.

C. OTHER

1. With a 2 stage the Gate Lift will not become inundated as frequently as with a single stage

2. CLASS "C" Dam with recreation

L. H. Drigh

STATE INDIANA PROJECT LEAD RIVER W/S SITE 1
BY DATE CHECKED BY DATE JOB NO
9-18-67 D Kotes 10-18-67
SUBJECT STRUCTURE CLASSIFICATION SHEET 6 OF
AC PER ECHS-73 E.M. 27

MAX. HEIGHT OF DAM 38.5 FT

ELEV. TOP OF DAM 1366.5

STORAGE BELOW TOP OF DAM (FROM PROJECTED
STAGE-STORAGE CURVE = 3750 AC-FT (EST)

K_s

$$\frac{(38.5)(3750)}{1000} = \frac{1443.75}{20} \rightarrow K_s = 25$$

K_p

FLOOD AREA, CITY OF BERLIN 250 PEOPLE (EST.)
 $\rightarrow K_p = 20$

K_w

EST. AVE. FLOOD PLAIN WIDTH = 300 FT $\rightarrow K_w = 5$

K_d

DISTANCE FROM STRUCTURE TO

DAMAGE CENTER = 3.2 MILES

$$K = \frac{K_s + K_p + K_w}{K_d} = \frac{25 + 20 + 5}{1.0} = 50 \rightarrow K_d = 1.0$$

CLASS C STRUCT.

OTHER FACTORS

FAILURE MAY CAUSE LOSS OF LIFE

COMMERCIAL & RESIDENTIAL BUILDINGS ARE
IN FLOOD PLAIN

STAGE - STORAGE DATA

BASE ELEV. DAM HT. TOPO OF DAM FL.

SCALE: 1" = 300 FT. 1 IN² = 2.0661 ACRES

[illegible]

AD-A156 748


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
SITE NUMBER 1 DEAD RI. (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV JUL 79


2/8

UNCLASSIFIED


F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A



U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICESCS-309
8-58

RESERVOIR SEDIMENTATION DESIGN SUMMARY

WATERSHED DEAD RIVER SITE NO. 1 STATE NEW HAMPSHIRE
 LOCATION COOS COUNTY DATE 9-21-69
 DATA COMPUTED BY E/ WILLIAM A. BONIN TITLE GEOLOGIST
 COPIED BY R.M.W 9-22-67

SEDIMENT SOURCES (AVERAGE ANNUAL)

TYPE OF EROSION		PRESENT CONDITIONS			FUTURE (AFTER CONS. TREATMENT)		
		ACRES	SOIL LOSS (TONS/AC)	TOTAL (TONS)	ACRES	SOIL LOSS (TONS/AC)	TOTAL (TONS)
SHEET EROSION	CULTIVATED LAND						
	B	2723	0.039	108.9			
	C	1229	0.089	109.4		NEGLECTABLE CHANGE	
	D	125		DEPOSITIONAL AREA			
	IDLE LAND						
	PASTURE-RANGE						
	WOODLAND						
	OTHER						
TOTAL SHEET EROSION			DELIVERY RATE (%)		TONS DELIVERED	DELIVERY RATE (%)	TONS DELIVERED
			20	218.3	43.7		
CHANNEL EROSION	GULLY						
	STREAMBANK						
	STREAMBED				42.0		
FLOODPLAIN SCOUR							
OTHER (ROADSIDE ETC.)							
TOTALS					85.7		

AREA OF WATERSHED:

414.7 ACRES

6.48 SQ. MI.

* PROJECTED FROM THE RESULTS OBTAINED ON A SIMILAR STREAM,
 LANGIN BROOK SITE, COLD R.-OLD COURSE SACO
 ME. & N.H.

DEPOSITION

AVERAGE DRY WEIGHT OF UPLAND SOILS:		
63 LBS/CU. FT.		
TEXTURE OF SEDIMENT		
%	%	%
CLAY	SILT	COARSE

AVERAGE ANNUAL SEDIMENT DELIVERED TO SITE FROM ALL SOURCES (TONS)		TRAP EFFICIENCY (%)	ANNUAL DEPOSITION (TONS)	DESIGN PERIOD (YRS)	PERIOD TOTAL DEPOSITION (TONS)
PRESENT	SHEET EROSION 43.7	59	43.8	100	4380
FUTURE	BED LOAD 42.0	100	42.0	100	4200
DESIGN TOTALS			100	100	8580

SEDIMENT STORAGE REQUIREMENTS

CONDITION OF SEDIMENT	% OF TOTAL	DEPOSITION (TONS)	VOLUME WEIGHT OF SEDIMENT		STORAGE REQUIRED		STORAGE ALLOCATION (ACRE FEET)		
			LBS/CU. FT.	TONS/AC. FT.	ACRE- FEET	WATERSHED INCHES	SEDIMENT POOL	RETARDING POOL	OTHER
FINISHED	100	4250	60	7083	3.29		4.34		
UNFINISHED	60	2550	110	2318	1.65				
RELINQUISHED	10	1450	85	1700	0.70			0.70	
TOTALS		8250			5.64	0.015			

B-60

STATE NEW HAMPSHIRE		PROJECT DEAD RIVER W/S SITE 1			
BY R. WEHNINGER	DATE 9-20-67	CHECKED BY D. KEATES	DATE 10-18-67	JOB NO.	
SUBJECT SOIL COVER COMPLEX CURVE NUMBER				SHEET 11 OF	

DRAINAGE AREA = 6.48 SQ MI = 4147 ACRES

SUB * AREA	LAND USE*	SOIL * GROUP	ACRES*	COMPLEX * NUMBER	COMPLEX NO. TIMES ACRES
A	FOREST	A-B	1425	65.5	93338
	FOREST	C-D	1180	72.9	86022
C	FOREST	A-B	830	65.5	54365
	FOREST	C-D	120	72.9	8748
E-1	FOREST	A-B	477	65.5	31243
	IDLE	D	115	83	9545
			4147		283261

$$\text{WEIGHTED NO.} = \frac{283261}{4147} = 68.3$$

→ USE 68, AMC II
85 AMC III

* DATA TAKEN FROM,

1) FOREST SERVICE LTR TO MR. ADDISON DTD 10-30-63

2) SOIL COVER COMPLEX NO'S, PRESENT/FUTURE BY E.L.R., 7-29-64

BOTH REFERENCES IN DEAD RIVER W/S HYDROLOGY BOOK I.

STATE <u>N.H.</u>		PROJECT <u>SEASIDE RIVER SITE 1</u>			
BY <u>D.K.</u>	DATE <u>10-17-67</u>	CHECKED BY <u>R.W.</u>	DATE <u>12-8-67</u>	JOB NO. _____	
SUBJECT <u>Tc</u>				SHEET <u>12</u> OF _____	

by IS-1015

Subarea A

50% of area with these slopes

$$\begin{aligned}\frac{1300}{7550} \times 100 &= 17\% \\ \frac{1300}{6750} \times 100 &= 19\% \\ \frac{900}{4700} \times 100 &= 19\% \\ \frac{500}{3000} \times 100 &= 16.7\% \\ \hline 4/71.7\end{aligned}$$

ave. slope = 18%

50% of area with these slopes

$$\begin{aligned}\frac{200}{3000} \times 100 &= 6.7\% \\ \frac{200}{2650} \times 100 &= 7.5\% \\ \frac{300}{3100} \times 100 &= 9.7\% \\ \frac{300}{3750} \times 100 &= 8.0\% \\ \hline 4/31.9\end{aligned}$$

ave. slope = 8%

wgt slope

$$\begin{aligned}0.5(18) &= 9 \\ 0.5(8) &= 4 \\ \hline \text{weighted slope} &= 13\%\end{aligned}$$

$$\begin{aligned}L &= 12250 \text{ ft.} \\ Y &= 13\% \\ CN &= 69\end{aligned}$$

$$L = 0.95 \text{ hrs.}$$

$$T_c = 1.67(0.95) = 1.6 \text{ hrs.}$$

STATE <u>N.H.</u>		PROJECT <u>DEAD RIVER</u>		SITE <u>1</u>	
BY <u>D.K.</u>	DATE <u>10/19/67</u>	CHECKED BY <u>R.W.</u>	DATE <u>12-8-67</u>	JOB NO.	
SUBJECT <u>Tc</u>				SHEET <u>13</u> OF <u> </u>	

channelized flow through subareas B & C

Length	Fall	Slope	V.	Tc
9500'	180"	1.9%	3.1	.8 hrs.

$T_c \text{ E-1} = T_c \text{ subarea A} + \text{channel Travel Time in subarea C}$

$T_c = 1.6 + 0.8 = 2.4 \text{ hrs.}$ AS PER WORK PLAN

STATE	NH	PROJECT	Dead River W.S. Site 1		
BY	HSS	DATE	12/15/67	CHECKED BY	JOB NO.
SUBJECT				SHEET 14 OF	

Low stage design
Designing as a 2 stage riser

As per work plan

Set permanent pool level at elevation
1352.0 (Recreation Pool).
4 AC-FT. sediment considered deposited below
elevation 1352.0


Ideally, release rate thru 1st stage
should be as near as possible to the
rate that would have been obtained
using a single stage riser with the
water surface at the same elevation

This cannot easily be done, therefore, proportion
orifice dimensions as large as possible yet
compatible with standard riser.

Set second stage elevation as close to
elevation of first stage as possible &
still have reasonable trash rack arrangement.

STATE NEW HAMPSHIRE	PROJECT DEAD RIVER SITE 1		
BY R. WENNINGER	DATE 10-2-67	CHECKED BY D. Yeates	DATE 10-18-67
SUBJECT COVERED TOP RISER PROPORTIONS		SHEET 15 OF	

POSSIBLE RELATION OF SIZES & ELEVATIONS
Using 42" Pipe




By EM SCS-50
 $H_2 = (2D + 6")$ TO 20' for standard
on this scheme
 $H_2 = 2 \times 3.5 + .5 = 7.5'$!!! 4' PROVIDED
but still considered a good
solution for the conditions

B-65

STATE	N.H.		PROJECT	DEAD RIVER SITE 1	
BY	R. WENINGER	DATE	11-22-67	CHECKED BY	D. K.
SUBJECT	ORIFICE FLOW			DATE	11/27/67
				JOB NO.	
				SHEET 16 OF	

From SKETCH

TRY: Following of Second Stage crest at elev. 1356.0



USE 2 ORIFICES

$$C_o = .60$$

SEETR-29

$$C_d = 3.1$$

" "

LOW STAGE WEIR FLOW

$$Q_{wl} = C_d l_p H_p^{3/2} = 3.1(2)(2.625)H_p^{3/2}$$

$$Q_{wl} = 16.28 H_p^{3/2}$$

LOW STAGE ORIFICE FLOW

$$Q_{ol} = C_o a_o \sqrt{2g h_o} = .60(2)(2.625)(8.020)h_o^{1/2}$$

$$Q_{ol} = 50.53 h_o^{1/2}$$

Q when second stage begins operating

$$h_o = 1356 - 1353 = 3.0$$


$$3^{1/2} = 1.732$$

$$Q_{h=1356} = 50.53 \times 1.732 = 87.52 \text{ cfs}$$

$$\text{or } \frac{87.52}{6.48} = 13.5 \text{ c.s.m. Reasonable}$$

STATE NEW HAMPSHIRE	PROJECT DEAD RIVER SITE 1
BY R. WENNINGER	DATE 11-21-67
CHECKED BY	DATE
JOB NO.	
SUBJECT PRINCIPAL SPILLWAY DIMENSIONS	
SHEET 17 OF	

Assuming:



*plunge pool
maybe used*

B-67

STATE N.H. PROJECT DEAD RIVER SITE 1
BY R. WEININGER DATE 11-20-67 CHECKED BY DK DATE 11/27/67 JOB NO. _____
SUBJECT _____

RISER CREST WEIR & CONDUIT FLOW


SHEET 13 OF _____

WEIR FLOW

$$Q_{wh} = C_h L_h H_h^{3/2}$$

$$= 3.1(10.5)(2) H_h^{3/2}$$

$$Q_{wh} = 65.10 H_h^{3/2}$$



CONDUIT FLOW

$$Q_{ph} = C_p h_p^{1/2}$$

$$C_p = A_p \sqrt{\frac{2g}{1 + K_e + K_f l_p}}$$

TRY 3.5' I.D. R/C

$$A_p = 9.62 \text{ ft}^2$$

$$M = 0.012$$

$$K_e = 1.0$$

$$K_f = .00502$$

$$l_p = (1371.6 - 1351.0)3 + 16' + (1371.6 - 1334.25)2.5 + 4 + 1' = 176.18 \text{ SAY } 176'$$

$$C_p = 9.62 \sqrt{\frac{64.32}{1 + 1.0 + (.00502)(176)}}$$

$$C_p = 45.43$$

$$Q_{ph} = 45.43 h_p^{1/2}$$


$$Q_{ph \text{ max}} = 45.43 (1362.0 - 1326.75)^{1/2} = 269.7 \text{ CFS} < 276.0$$

USE 42" PIPE

STATE	NEW HAMPSHIRE		PROJECT	DEAD RIVER SITE 1	
BY	R WENNINGER	DATE	10-5-67	CHECKED BY	D. Keates
		DATE	10-18-67	JOB NO.	
SUBJECT	RAINFALL - RUNOFF RELATION				SHEET 19 OF

DATA TAKEN FROM TP-40, TP49, & WORK PLAN

TIME		10YRAMCII CN=68		10YRAMCII +1"/DAY SNOWMELT CN=68		10YRAMCIII CN=85		100YRAMCII CN=68	
HRS	DAYS	P(INCH)	Q(INCH)	SNOWMELT (INCH)	Q(INCH)	Q(INCH)		P(INCH)	Q(INCH)
1		1.54	.07	.04	.11	.48		2.21	.26
2		2.01	.19	.08	.27	.81		2.92	.59
3		2.48	.37	.13	.50	1.16		3.50	.90
6		3.00	.63	.25	.88	1.59		4.50	1.53
12		3.90	1.14	.50	1.64	2.37		5.35	2.13
24	1	4.85	1.78	1	2.78	3.24		6.85	3.29
	2	5.80	2.47	2	4.47	4.12		8.00	4.23
	4	7.20	3.57	4	7.57	5.45		10.10	6.05
	7	8.60	4.74	7	11.74	6.80		12.10	7.84
	10	9.9	5.87	10	15.87	8.06		14.00	9.60



PLOTTED: R. WEININGER 10-5-67
 V'D: D. Keates 10-18-67
 REF: TP40, TP49

STATE NH PROJECT DEAD RIVER SITE
BY R. W. DATE 12-1-57 CHECKED BY S. K. DATE 12-1-57 JOB NO.
SUBJECT Elevation of top of dam SHEET 26 OF

FREEBOARD HYDROGRAPH ROUTING ELEVATION 1370.9

F.S. HYDROGRAPH ROUTING ELEVATION 1362.24

WAVE FREEBOARD

$F = \text{FETCH} = 4500 \text{ FT} = 0.85 \text{ MILES}$

$V = \text{VELOCITY OF WIND} = 100 \text{ MPH}$

$H = \text{HT OF WAVES} = 0.17 \sqrt{VF} + 2.50 - F$
 $= 0.17 (9.22) + 2.50 = .96$

SEELYE
DESIGN
4-66

$H = 3.11 \text{ FT}$

$1362.24 + 3.11 = 1365.35$

FROST DEPTH

ASSUME MAX. FROST DEPTH = 5.0 FT

$1362.24 + 5.0 = 1367.24$

SEELYE
DESIGN
5-32

MAXIMUM FREEBOARD ELEVATION

REQUIRED = 1370.9

SET TOP OF DAM AT
ELEVATION 1371.0

11/1/67

12-5-67 D.E.S.

11/1/67

t_w - TIME FROM SPILLWAY TO END OF PIPE 6.6

t_w - TIME FROM SPILLWAY TO END OF PIPE 6.6

V_{w0} - VOLUME OF WATER IN PIPE AT t_w 1560

V_{w0} - VOLUME OF WATER IN PIPE AT t_w 1600

Q_0 - MAXIMUM DISCHARGE AT t_w 510 CFS

Q_p - PIPE DISCHARGE AT t_w 271 CFS

$Q_e = Q_0 - Q_p$ 239 CFS

Q_1 - PEAK INFLOW 475 CFS

V_1 - TOTAL INFLOW VOLUME 1552 AC FT

$t_w (Q_1/V_1)^{1/2.1} =$ 2.02

$V_{w0}/V_1 =$.784

V_{w0} - INFLOW VOLUME AT t_w 1527 AC FT

$t_1 = t_w - t_e$ 1.2

$$\left[\frac{V_1 - V_{w0} - (V_{w0} - V_{w1})}{Q_p + Q_e (Q_0)} \right]^{12.1}$$

1552 - 1527 - 1603 - 1560

271 - 239 - 39

3.9
2.4

B-83

4.2 SW

STATE	N.H.	PROJECT	DEAD RIVER SITE
BY	R.M.W.	CHECKED BY	D.K.
DATE	12-6-67	DATE	12/14/67
SUBJECT	EMERGENCY SPILLWAY EXIT SLOPE & VEL.		JOB NO.
			SHEET 34 OF

CRITICAL OUTLET CHANNEL SLOPE

$$b = 100 \text{ FT.}, M = 0.04, Q_E = 39 \text{ CFS @ EL. 1362.24}$$

$$q_E = 0.39 \text{ CFS/FT} \quad q = 25\% \text{ OF } q_E = 0.0975 \text{ CFS/FT}$$

$$d_c = \sqrt[3]{\frac{q^2}{g}} = \sqrt[3]{\frac{(0.0975)^2}{32.2}} = 0.067 \text{ FT} \quad \text{SEE ES-98}$$

$$S_c = \frac{21.42 \cdot n^2 (100)}{q_c^3} = \frac{21.42 (0.04)^2 (100)}{(0.0975)^3} = 5.8\% \quad \text{SEE ES-98}$$

\therefore USE 4 %

EM-27

MAX. VELOCITY THRU E.S. @ CONTROL SECTIONE. S. HYDROGRAPH

$$q_E = 0.39 \text{ CFS/FT}$$

$$d_c = 0.07 \text{ FT}$$

ES-98

$$V_c = 2.33 \text{ FPS}$$

"

MAX. VELOCITY THRU E.S. @ CONTROL SECTIONFREEBOARD HYDROGRAPH

$$Q_E = 7975 - 302 = 7673 \text{ CFS}$$

$$q_E = 76.73 \text{ CFS/FT}$$

$$d_c = 5.7 \text{ FT}$$

ES 98

$$V_c = 13.6 \text{ FPS}$$

ES 98

HYDROGRAPH COMPUTATION
FREEBOARD HYDROGRAPH

SHEET 31
J. D. Keates 10-12-67
R.V. FURNING 9-20-67

WATERSHED OR PROJECT DEAD RIVER STATE NEW HAMPSHIRE

STRUCTURE SITE OR SUBAREA SITE 1

DR. AREA 6.48 SQ. MI. T_c 2.4 HR. RUNOFF CONDITION NO. II

RUNOFF CURVE NO. 58 STORM DISTRIB. CURVE 2 HYDROGRAPH FAMILY NO. 2

STORM DURATION 6 HR. RAINFALL: POINT 20.3 IN. AREAL 20.3 IN.

Q 15.57 IN. $0.7E =$
COMPUTED T_p 1.69 HR. T_o 5.33 HR.

$(T_o \div T_p)$: COMPUTED 3.17 : USED 3 REVISED T_p 1.78

$q_p = \frac{484 A}{REV. T_p} =$ 1762 CFS. $Q_{dp} =$ 27434 CFS.

1 (COLUMN) = $(1/T_p) REV. T_p$ q (COLUMN) = $(q_c/q_p) Q_{dp}$

DATA FROM TABLE 3.21-7 (270F52)

LINE NO.	t HOURS	q CFS	LINE NO.	t HOURS	q CFS	LINE NO.	t HOURS	q CFS
1	0	0	21	11.40	137	41		
2	0.57	82	22	11.95	82	42		
3	1.14	466	23	12.50	55	43		
4	1.71	2550	24	13.10	27	44		
5	2.28	8532	25	13.65	0	45		
6	2.84	14540	26			46		
7	3.42	16872	27	$\phi = (4T)(EF)$		47		
8	4.00	15774	28	645A		48		
9	4.55	12360	29	$\Delta T = .57$		49		
10	5.13	11220	30	$\phi = 115.002$		50		
11	5.70	9427	31			51		
12	6.26	7654	32	$\phi = (1.57)(115.002)$		52		
13	6.84	5651	33	645(6.43)		53		
14	7.40	3744	34	= 1531		54		
15	8.00	2297	35			55		
16	8.55	1450	36	% ERROR		56		
17	9.10	890	37	$\frac{15.8 - 15.57}{15.57}$		57	100 = 1.5	452
18	9.66	500	38	1.157		58		
19	10.25	330	39	B-81		59		

Emergency Spillway

HYDROGRAPH COMPUTATION

D. Keates 11/13/67
at R. V. H. 10-16-67WATERSHED OR PROJECT Dead RiverSTATE N. H.STRUCTURE SITE OR SUBAREA Site 1DR. AREA 6.48 SQ. MI. T_c 2.4 HR.RUNOFF CONDITION NO. IRUNOFF CURVE NO. 68 STORM DISTRIB. CURVE B HYDROGRAPH FAMILY NO. 3STORM DURATION 6 HR.

RAINFALL:

POINT 8.3 IN.AREAL 8.3 IN. Q 4.49 IN.COMPUTED T_p 1.68 HR. $7(T_c)$ T_o 4.70 HR. $(T_o + T_p) \frac{4.7}{1.68}$ COMPUTED 2.30USED 3REVISED T_p 1.563 $q_p = \frac{484 A}{REV. T_p} = \frac{484 \times 6.48}{1.563} = 2000$ CFS. $Qq_p = 8.980$ CFS. $t(\text{COLUMN}) = (t/T_p) REV. T_p$ $q(\text{COLUMN}) = (q_c/q_p) Qq_p$

LINE NO.	t HOURS	q CFS	LINE NO.	t HOURS	q CFS	LINE NO.	t HOURS	q CFS
1	0	0	21	10.66	27	41		
2	0.53	36	22	11.19	18	42		
3	1.07	71	23	11.72	9	43		
4	1.60	2590	24	12.25	0	44		
5	2.13	4290	25	$sz = 0.53$	$sq = 35.7$	45		
6	2.66	4878	26	$Q = 3T(FR)$		46		
7	3.20	555	27	645 A		47		
8	3.73	3998	28	$Q = 0.55 (1530)$		48		
9	4.26	3459	29	645 (1448)		49		
10	4.80	3055	30	$Q = 4.55$ INCHES		50		
11	5.33	2600	31			51		
12	5.86	2200	32			52		
13	6.39	1838	33	$\frac{755-459}{2.11} \times 100 = 1.34\% < 5\%$		53		
14	6.93	1500	34			54		
15	7.46	1200	35			55		
16	8.00	900	36			56		
17	8.53	600	37			57		
18	9.06	300	38			58		
19	9.59	0	39	B-80		59		

NEW HAMPSHIRE DEAD RIVER SITE 1

DRAWDOWN TIME

Neglecting base flow

[illegible]

EMERGENCY SPILLWAY STAGE & DISCHARGE DATA (Cont.)

[illegible]


EMERGENCY SPILLWAY STAGE & DISCHARGE DATA

REF: ES-124

(10) $D = d_x + \frac{V^2}{2g}$ FT	(11) WATER SURFACE = 1354.0 + D	(12) $H_p =$ WATER SURFACE - 1362.0	(13) q cgs/ft	(14) $q_E = q_b$ CGS	(15) ELEV 1362.0 + H_p
0		0			1362.0
		0.1	0.10	10	1362.1
		0.2	0.25	25	1362.2
		0.4	0.4	40	1362.3
		0.4	0.5	50	1362.4
		0.6	0.8	80	1362.6
		0.8	1.2	120	1362.8
		1.0	1.7	170	1363.0
		1.1	1.9	190	1363.1
9.12	1363.12	1.12	2	200	
9.73	1363.73	1.73	4	400	
		2.0	5.3	530	1364.0
10.13	1364.13	2.13	6	600	
10.52	1364.52	2.52	8	800	
10.83	1364.83	2.83	10	1000	
		3.0	11	1100	1365.0
11.55	1365.55	3.55	15	1500	
		4.0	18.4	1840	1366.0
12.20	1366.20	4.20	20	2000	
12.72	1366.72	4.72	25	2500	
		5.0	28.0	2800	1367.0
13.15	1367.15	5.15	30	3000	
		6.0	39.0	3900	1368.0
14.05	1368.05	6.05	40	4000	
14.92	1368.92	6.92	50	5000	
				B-76	

DEAD RIVER SITE

H₁ vs δ
Emergency Spillway



EMERGENCY SPILLWAY STAGE & DISCHARGE DATA (CONT)

B-74

DEAD RIVER SITE 1

EMERGENCY SPILLWAY STAGE & DISCHARGE DATA

REF: ES-124

$$b = 100 \text{ FT. } M = 0.04 \frac{1}{2} z = 625 \quad n^2 (l_c - l_n) = .0960$$

$$l_2 - l_1 \approx 400 \text{ FT. } (l_c - l_n) = 625 \text{ FT.}$$

(1) q CFS/FT	(2) $(l_c - l_n) n^2$	(3) ES 124 Z OF 52 d_x 60 F52	(4) $M^2 (l_c - l_n)$ $F_o d_x =$ dx ES 124 60 F52	(5) $(l_c - l_n)$ 625 (col 4)	(6) $(l_c - l_n) =$ $(l_c - l_n) +$ $(l_2 - l_1) =$ 400 + (col 5)	(7) $M^2 (l_c - l_n)$ $= .0016 \times$ (col 5)	(8) d_1 ES 124 60 F52	(9) ES 139 10 F1 $v^2 / 2g$ FT
0	.0960	0						
2	"	1.02	.018	11.25	411.25	.658	9.12	< .1
4	"	1.46	.022	13.75	413.75	.662	9.73	< .1
6	"	1.78	.023	14.38	414.38	.663	10.13	< .1
8	"	2.08	.025	15.63	415.63	.665	10.52	< .1
10	"	2.32	.0255	15.94	415.94	.6655	10.82	< .1
15	"	2.87	.026	16.25	416.25	.666	11.55	< .1
20	"	3.31	.0225	14.06	414.06	.6625	12.20	< .1
25	"	3.73	.023	14.38	414.38	.663	12.72	< .1
30	"	4.12	.024	15.00	415.00	.664	13.15	< .1
40	"	4.86	.026	16.25	416.25	.666	14.05	< .1
50	"	5.54	.0215	13.44	413.44	.6615	14.81	< .1

SECTION 1

B-73

SECTION 2

B-73

SECTION 3

B-73

STATE <u>NH</u>		PROJECT <u>DEAD RIVER</u>		SITE <u>1</u>	
BY <u>P.M.W.</u>	DATE <u>12-7-67</u>	CHECKED BY <u>D.K.</u>	DATE <u>12/14/67</u>	JOB NO.	
SUBJECT <u>ELEVATION OF EMERGENCY SPILLWAY CREST</u>				SHEET <u>22</u> OF <u> </u>	

REQUIRED STORAGE:

$Q = 4.10 \text{ INCHES}$ WORK PLAN

$Q = \frac{4.10 \times 4147}{12} = 1416.9 \text{ AC-FT}$

TOTAL SEDIMENT = 5 AC-FT

RECREATION = 1235.6 AC-FT
1240.6

TOTAL NECESSARY STORAGE TO E.S. CREST = 2657.5 A.F.

FROM STAGE-STORAGE CURVE:

2657.5 AC-FT → EL. 1361.25

FROM ECONOMIC DATA, USE EL. 1362.0

Storage to elev. 1362.0 = 2800 A.F.
- 1240.6
1559.4

OR $\frac{1559.4 \times 12}{4147} = 4.51" > 4.10" \text{ O.K.}$
(PROVIDED) (NEEDED)

STATE	NH	PROJECT	Dead R. Site 1		
BY	HSS	DATE	6/13/68	CHECKED BY	RW
		DATE	8-68	JOB NO	
SUBJECT	Reservoir Drain Pipe Size				SHEET ____ OF ____

Ave. annual runoff ≈ 22 inches
or $\frac{22}{365} = 0.0603$ inches/day

$$\text{or } \frac{0.0603}{0.03719} = 1.62 \text{ c.s.m.}$$

$$\text{or } 1.62 \times 6.48 = 10.5 \text{ cfs (ave rate of runoff)}$$

Try 30" RCP reservoir drain $S = 0.005$

$$Q_{30} = 4.909 \text{ Ft.}^2$$

From "Design" Seelye

$$Q = 25 \text{ cfs (water level with top of entrance)}$$

$25 > 10.5 \text{ cfs}$ O.K.

using 24" RCP $Q = 14 > 10.5$ Also O.K.

Estimate time to empty reservoir

$$S = 1236 \text{ A.F. (Beneficial Stor.)} + 5 \text{ (Sed. Stor.)} = 1241 \text{ AF}$$

$$\text{Using 30" RCP } Q_{\text{max}} = .62 a \sqrt{2gh}$$
$$h = 1352 - (1329.5 + \frac{2.5}{2}) = 21.25'$$

$$Q_{\text{max}} = .62 \times 4.909 \times 8.02 \times \sqrt{21.25}$$
$$= 112.3 \text{ cfs}$$

$$Q_{\text{ave}} = (112.3 + 25)^{\frac{1}{2}} = 68.7 \text{ cfs}$$

$$Q_{\text{net}} = 68.7 - 10.5 = 58.2$$

$1 \text{ cfs} = 1.98 \text{ AF/D.}$

$$T = \text{time to empty} = \frac{1241}{58.2 \times 1.98} = 10.8 \text{ Days O.K.}$$

T with 24" Pipe = 20.1 Day (Excessive)

\therefore Use 30" RCP Reservoir Drain

$$Q_{\text{Max.}} = 112.3 \text{ (30")}$$

$$\frac{112.3}{6.48} = 17.3 \text{ csm B-85}$$

STATE N.H.	PROJECT Dead R. Site 1		
BY HSS	DATE 6/12/68	CHECKED BY RW	DATE 6-24-68
SUBJECT Tailwater in Outlet Channel			JOB NO NH 770
			SHEET _____ OF _____

$$Q_{max} = 270 \text{ cfs}$$

$$n = 0.035$$

$$b = 16'$$

$$s = 0.005$$

$$z = 2$$

$$Q/b = \frac{270}{16} = 16.9 \text{ cfs/ft.}$$

$$z/b = \frac{2}{16} = 0.125$$

From ES-24 1 of 3

$$d_c = 1.9'$$

$$\frac{nQ}{b^{8/3} s^{1/2}} = \frac{.035 \times 270}{16^{4/3} \times .005^{1/2}} = \frac{9.45}{1630 \times .07071} = .082$$

$$z = 2'$$

From ES-55 2 of 4

$$\frac{d}{b} = 0.165 \therefore d = .165 \times 16 = 2.64'$$

$$A = d(b + zd) = 2.64(16 + 2.64 \times 2) = 56.4 \text{ Ft}^2$$

$$V = \frac{Q}{A} = \frac{270}{56.4} = 4.8 \text{ fps. OK.}$$

When $Q = 270 \text{ cfs}$ of Channel inv @ 1320.5

Elev of WS. = 1323.14

Set top of Rip Rap @ EL 1323.5

B-86

in need of

STATE NH	PROJECT DEAD RIVER SITE 1			GPO 1958 O-470868
BY RW	DATE 8-68	CHECKED BY	DATE	JOB NO. NH-770-H
SUBJECT FLOODWAY - ELEV. TOP OF DAM			SHEET _____ OF _____	

THE RIGHT SIDE (LOOKING DOWNSTREAM)
OF THE DAM MUST BE RAISED ABOVE
THE ELEVATION NORMALLY REQUIRED, TO
PROVIDE FREEBOARD FOR THE FLOODWAY FLOW.

THE TOP ELEVATIONS OF THE DAM ADJACENT
TO THE FLOODWAY WILL BE DETERMINED
BY CONSIDERING THE FOLLOWING:

1. THAT ALL THE JERICHO BROOK FLOW
ENTERS THE FLOOD POOL THRU THE FLOOD-
WAY & DIVERSION CHANNEL.

2. THAT THE PEAK FREEBOARD FLOW
PASS THE FLOODWAY WITHOUT OVERTOPPING
THE DAM.

$$\text{PEAK INFLOW} = (16872)(5.66/6.48)^* = 14740$$

$$\text{POOL ELEV. @ PEAK FLOW} = 1363.8^*$$

3. THAT THE FLOODWAY FLOW, WHEN THE POOL
ELEV. IS MAXIMUM, PASS WITHOUT
OVERTOPPING THE DAM

$$\text{MAX. POOL ELEV.} = 1370.9$$

$$\text{FLOW IN BROOK WHEN POOL ELEV.}$$

$$\text{EQUALS 1370.9 IS } (7975)(5.66/6.48)$$

$$= 6966 \text{ CFS}$$

4. THAT AN ARBITRARY FLOODWAY FLOW
(VALUE BETWEEN THOSE IN PARA. 2 & 3 ABOVE)
PASS WITHOUT OVERTOPPING THE DAM

$$\text{SAY FLOW} = 13280 \text{ CFS}$$

$$\text{POOL ELEV. @ 13280} = 1367.0$$

B-87

* SEE FREEBOARD ROUTING - BROOK DRAINAGE AREA

STATE		PROJECT		JOB NO.	
NEW HAMPSHIRE		DEAD RIVER SITE		NH-770-H	
BY	DATE	CHECKED BY	DATE		
RW	8-68				
SUBJECT				SHEET ____ OF ____	
n-FLOODWAY					

SELECTION OF n 2 STA 22+00 TO 17+00

STEP 1 0.025 CHANNEL IN ROCK & EARTH

STEP 2 0.015 IRREGULARITY

STEP 3 0.010 SIZE & SHAPE

STEP 4 0.020 OBSTRUCTIONS

STEP 5 0.007 VEGETATION

STEP 6 0.000 DEGREE OF MEANDERING

TOTAL 0.077

STATE	NEW HAMPSHIRE	PROJECT	DEAD RIVER SITE
BY	R.W.	CHECKED BY	HSS
DATE	2-1-68	DATE	2/26/68
SUBJECT	M - FLOOD WAY		JOB NO. NH-770-H
			SHEET 1 OF 1

SELECTION OF n

NEH, SEC 5, SUP. B 195

\pm STA 17+00 TO 9+00

STEP 1 0.025 CHANNEL IN ROCK & EARTH

STEP 2 0.010 MODERATE DEGREE OF
IRREGULARITY

STEP 3 0.010 VARIATION IN SIZE & SHAPE
LARGE & SMALL SECTIONS
ALTERNATING, SHAPE CHANGES.

STEP 4 0.008 MINOR EFFECT OF OBSTRUCTIONS

STEP 5 0.007 LOW DEGREE OF EFFECT
CAUSED BY VEGETATION

STEP 6 0.000 DEGREE OF MEANDERING

TOTAL 0.060

$n = .060$

THIS VALUE BASED ON FOLLOWING:

FLOODWAY. CLEARED & GRUBBED

PLANED & SEEDING

DAM PARTLY RIP RAPPED

STATE	NEW HAMPSHIRE		PROJECT	DEAD RIVER SITE	
BY	R.W.	DATE	2-16-68	CHECKED BY	HSS
				DATE	2/26/68
SUBJECT	N - FLOOD WAY				JOB NO. NH-770-H
					SHEET ____ OF ____

SELECTION OF N

FROM STA 9+00 TO END OF STUDY (25+00)

STEP 1 CHANNEL IN EARTH & ROCK 0.025

STEP 2 MODERATE DEGREE OF
IRREGULARITY 0.015

STEP 3 VARIATION IN SIZE
& SHAPE, LARGE & SMALL
SECTIONS ALTERNATING
SHAPE CHANGES 0.010

STEP 4 APPRECIABLE EFFECT
OF OBSTRUCTIONS 0.030

STEP 5 VERY HIGH EFFECT
CAUSED BY VEGETATION 0.070

STEP 6 DEGREE OF MEANDERING 0.000

TOTAL 0.15

L-90

B-90

LAB REPORT

UNITED STATES GOVERNMENT

Memorandum

TO : C. H. Dingle, State Conservation Engineer,
SCS, Durham, New Hampshire

DATE: April 22, 1968

FROM : Lorn P. Dunnigan, Head, Soil Mechanics Laboratory,
SCS, Lincoln, Nebraska

SUBJECT: ENG 22-5, New Hampshire WP-08, Dead River, Site No. 1 (Coos County)

ATTACHMENTS

1. Form SCS-354, Soil Mechanics Laboratory Data, 4 sheets.
2. Form SCS-355, Triaxial Shear Test Data, 3 sheets.
3. Form SCS-352, Compaction and Penetration Resistance Report, 5 sheets.
4. Form SCS-353, Soil Classification, 1 sheet.
5. Form SCS-130, Drain Materials, 1 sheet.

DISCUSSION

FOUNDATION

- A. Bedrock: Bedrock underlies the till on the abutments and the alluvium in the floodplain at depths of from 0 to 27 feet. The bedrock is described in the geology report for this site.

Durability tests were made on the rock cores from test hole 505. During the Los Angeles abrasion test the loss was 45.8 percent. Gradation A (Federal specification) was used for the test. The ledge rock procedure was used for the soundness test and the loss during 5 cycles was only 0.09 percent.

- B. Soil Classification: The soil on the abutments is primarily glacial till. Sample 4.1 and 214.1 are considered to be representative of the majority of the till on the left abutment. The grain-size curve for these two samples and curves for two other samples from the spillway are shown on the attached form SCS-353 for comparison. The gradation of these four samples fall within a relatively narrow range and the properties of the materials are expected to be comparable. The till on this abutment is stratified in some zones as indicated by variable and high permeability rates and by sample 503.2 which represents a water worked till from the 11 to 14-foot depth. Sample 4.1 contains 15 percent fines and is classified as non-plastic SM. Sample 214.1 contains 10 percent fines and is an SM-SP. The water worked till contains 28 percent fines and is classified as non-plastic SM. There is some muck and alluvium in the vicinity of centerline station 34+00 on this abutment.

B-91

2 -- C. H. Dingle -- 4/22/68

Lorn P. Dunnigan

Subj: ENG 22-5, New Hampshire WP-08, Dead River, Site No. 1

The mantle material in the floodplain between approximate centerline stations 21+50 and 27+50 consist of a surface zone of muck overlying pervious alluvium that is logged primarily as SP and SP-SM. Sample 502.1 was submitted from approximately the toe area downstream from centerline station 24+50. The material represented contains 13 percent fines and is classed as non-plastic SM.

The muck averages about 1.5 feet thick and ranges up to 6.5 feet thick. The sandy alluvium ranges from 0 to about 20 feet thick.

The till on the right abutment and diversion area ranges from about 30 feet at approximately centerline station 20+00 to from 0 to about 5 feet on the rest of the abutment right of centerline station 19+00. Samples were submitted from test holes 7 and 10 on the abutment. These samples are somewhat finer grained than the till on the left abutment. They contain about 30 percent fines and they are classed as non-plastic SM and low plasticity SC-SM.

- C. Shear Strength: The blow count in the till and the alluvium is relatively high and, based on this data, it appears that the shear strength of the till and the alluvium is adequate for the embankment planned. It is planned to strip the muck from the foundation and its shear strength will not be a problem.
- D. Consolidation: With the muck removed the consolidation potential of the till and of the alluvium is expected to be very low.
- E. Permeability: The permeability of the till and of the alluvium is expected to be highly variable. Field permeability tests were made and the data are reported in the geology report.

EMBANKMENT

- A. Classification: The majority of the fill material at this site is represented by samples 4.1, 59.1, 207.1, 214.1 and 221.1. The gradation curves for each of these samples falls within a relatively narrow range as shown on the attached form SCS-353. Sample 4.1 contains 14 percent fines and is classed as a non-plastic SM. The other four samples referred to above contain from 8 percent to 11 percent fines and they are classed as SP-SM.

The bulk dry density of the gravel size material is in excess of 160 pcf.

3 -- C. H. Dingle -- 4/22/68

Lorn P. Durnigan

Subj: ENG 22-5, New Hampshire WP-08, Dead River, Site No. 1

- B. Compacted Density: Standard Proctor compaction tests were made on the minus No. 4 fraction of samples 207.1, 214.1, 221.1, 4.1 and 7.1. The maximum dry densities obtained fell within a relatively narrow range of from 120 pcf to 124 pcf.

In addition to the standard compaction tests a relative density test was made on the minus 1 1/2-inch fraction of sample 214.1. The test was made in accordance with ASTM designation D2049. The minimum density obtained is 115 pcf and the maximum density obtained is 139.1 pcf.

- C. Permeability: Permeability consolidation tests were made on the minus No. 4 fraction of sample 214.1 (68W1663). The tests were made at densities of 95 percent of Proctor and at 100 percent of Proctor.

The test data obtained are summarized as follows:

Test γ_d		k in fpd			Consolidation ft/ft		
pcf	% Proctor	2000 psf	4000 psf	8000 psf	2000 psf	4000 psf	8000 psf
114.5	94.5	3.000	5.000	7.000	0.004	0.008	0.014
120.9	100	0.055	0.038	0.035	0.012	0.017	0.020

The test data for the test at 95 percent of Proctor is not conclusive. You will note that the permeability rate increased as the load was increased and that the consolidation potential was less under these loadings than it was at 100 percent of Proctor. We don't know the reason for this apparent discrepancy but we will set up a check test and report the data when the test is complete.

- D. Shear Strength: Consolidated undrained triaxial shear tests were made on sample 214.1 (68W1663). One test was made on the minus No. 4 material compacted to 95 percent of standard Proctor density and one test was made on the material finer than one inch compacted a density of approximately 128 pcf. The test specimens for the minus one inch material were graded so that they contained 40 percent gravel. The test specimen diameter was 4.0 inches.

The test data are summarized as follows:

Sample No.	% Gravel in Test Specimen	Test Specimen Diameter (Inches)	Test Density (pcf)	Degree of Saturation	Shear Strength Parameters			
					Total Stress		Effctv. Stress	
					ϕ deg	c psf	ϕ deg	c psf
68W1663	0	1.4	114	76.3	42.0	0	--	--
68W1663	40	4.0	128	80.9	43.5	0	43.5	0

B43

4 -- C. H. Dingle -- 4/22/68

Lorn P. Dunnigan

Subj: ENG 22-5, New Hampshire WP-08, Dead River, Site No. 1

You will note that the degree of saturation is low for both tests. The 1.4 inch diameter test specimens were soaked prior to testing and the 4.0 inch specimens were molded at saturation. The computations for the degree of saturation are based on the moisture content after test and weight loss during the test. The material tested contains a relatively low percentage of non-plastic fines and the specimens drain very rapidly. This is believed to be the reason for the low degree of saturation. The test results have been interpreted as $c = 0$ and this was done to make allowance for the low degree of saturation.

The test density used for the specimens containing gravel is equal to 95 percent of the minus No. 4 Proctor density adjusted for 40 percent gravel. It is interesting to note that this density is within 3 pcf of 70 percent of relative density on the minus 1 1/2-inch fraction.

- E. Durability of Rock: The Los Angeles abrasion test and the sodium sulfate soundness tests were made on five samples. The test data obtained are summarized as follows:

Sample Number		Los Angeles Abrasion		Sodium Sulfate Soundness	
Field	Laboratory	Gradation	% Wear	Procedure	% Loss
18	1666	G	37.5	Ledge Rock	0.1
227	1667	G	62.5	Ledge Rock	0.2
230	1670	G	55.1	Ledge Rock	0.08
505	1671	A	45.8	Ledge Rock	0.09
4.1	1653	A	45.9	Coarse Aggregate	2.73
59.1	1659				
	1658				

It was noted that thin sections of 63W1668 (Field No. 228) could be flaked with the fingers, therefore, no tests were made.

The gradation referred to in the table under Los Angeles Abrasion corresponds to grading in the Federal specification for this test.

SLOPE STABILITY

The stability of the proposed 3:1 upstream slope and the 2 1/2:1 downstream slope was checked with an infinite slope method of analysis. The analyses is summarized as follows:

5 -- C. H. Dingle -- 4/22/68

Lorn P. Dunnigan

Subj: ENG 22-5, New Hampshire WP-08, Dead River, Site No. 1

Slope	Condition	γ Sat. pcf	Shear Parameters		F_s
			ϕ deg	c psf	
3:1 Upstream	Horizontal flow lines	128.5	42°	0	1.22
3:1 Upstream	Parallel flow lines	128.5	42°	0	1.37
2 1/2:1 Downstream	No Drain - Horizontal flow lines	128.5	42°	0	0.99
2 1/2:1 Downstream	No Drain - Parallel flow lines	128.5	42°	0	1.14
3:1 Downstream	No Drain - Horizontal flow lines	128.5	42°	0	1.22
2 1/2:1 Downstream	Drained	128.5	42°	0	2.25

CONCLUSIONS AND RECOMMENDATIONS

- A. Site Preparation: We concur with the proposal to remove the muck from the foundation area of the dam. The water table is high and dewatering will be necessary.
- B. Cutoff: A multiple-purpose flood-control and recreation dam is planned. The till and alluvium overlying bedrock is primarily an SP-SM. These materials are stratified and contain zones of high permeability. In order to insure that the dam functions as intended we suggest that the cutoff trench bottom on bedrock on the abutments and in the floodplain section. Cutoff to bedrock can be obtained with trench depths of 11 feet or less except where the centerline cross a "topographic high" on each side of the floodplain. In the areas of the topographic high cuts in the range of 30 feet will be necessary to bottom the trench on rock. The till may not be as variable as it appears to us and it may be possible to reduce seepage by upstream blanketing or by some other method of cutoff.

Glacial till like sample 7.1 (68W1654) contains 33 percent fines and 14 percent finer than 0.005 mm. It is classed as an SC-SM. If this type of material is available in sufficient quantity we suggest that it be used for backfill. The permeability rate of this material placed at 98 percent of Proctor density would be very low.

If material like sample 7.1 is not available or if it cannot be easily identified in the field, material like sample 4.1 or sample 214.1 may be used. We suggest that it be placed at approximately 100 percent of Proctor density with the control on the minus No. 4 fraction in order to insure uniform low permeability fill. We suggest a placement moisture content wet of optimum if possible.

It might be possible to reduce excavation by locating the cutoff upstream from centerline.

B-95

6 -- C. H. Dingle -- 4/22/68

Lorn P. Dunnigan

Subj: ENG 22-5, New Hampshire WP-08, Dead River, Site No. 1

- C. Principal Spillway: The proposed location for the principal spillway is near the base of the left abutment. This location was selected in the field as best location of several alternates studied. The bedrock profile at this location is somewhat irregular and it occurs at depths of from about 5 feet to 14 feet. The alluvium overlying the bedrock is described as loose to very compact and pervious. The water table occurs at or above ground surface and the blow count varies from two blows per foot to more than 200 blows per foot. It appears, on the basis of this information, that it would be desirable to excavate the principal spillway trench to a uniform gradient in or on bedrock and to backfill the trench with material like that suggested for the cut-off trench. Consolidation of the backfill under the conduit would be very low as indicated by the consolidation data obtained on the permeability test specimens.
- D. Drain: A drain is suggested to control the phreatic line in the embankment and to provide a safe outlet for seepage from the foundation. As a minimum, a trench drain is suggested at about c/b = 0.6. We suggest that the drain tap the most pervious stratum in the upper 10 feet and that it extend up the abutment to permanent pool elevation.

We suggest that the filter-drain completely encompass the conduit on the drain line.

The suggested filter limits are shown on the attached form SCS-130.

E. Embankment Design:

1. Placement of Materials: The materials available for use in the embankment are those represented with the gradation curves plotted on the attached form SCS-353. It is primarily on SP-SM. If it is possible to select enough material like sample 7.1 for a thin core section in the embankment this would be highly desirable because it would result in a core with low permeability and the placement density could be controlled to a minimum of 95 percent of standard Proctor.

If it is not possible to use the finer grained materials as discussed in the cutoff section of the report then we suggest that a core section be constructed of the till like the sample represented with the grain size plots on form SCS-353 by placing them at near 100 percent of Proctor density with the density controlled on the minus #4 fraction. We suggest a placement moisture content slightly on the wet side of standard Proctor optimum.

7 -- C. H. Dingle -- 4/22/68

Lorn P. Dunnigan

Subj: L.S. 22-5, New Hampshire WP-08, Dead River, Site No. 1

The shell sections would also consist of till but the control could be by method specification. We suggest that the method specified result in a density of about 128 pcf or higher.

The consolidation data on the permeability samples indicate that there will be very little difference in the consolidation potential of the material placed at 95 percent of Proctor and the material placed at 100 percent of Proctor so differential settlement between the sections should not be a problem.

2. Slopes: The data and analyses indicate that proposed slopes have acceptable factors of safety.

3. Settlement: An overfill allowance of 0.5 foot is suggested to compensate for residual settlement in the fill and foundation.

P. Dike: It is proposed to construct the dike out of material like that used in the embankment and 3:1 slopes are planned. This appears to be adequate.

Lorn P. Dunnigan

cc:

C. H. Dingle, Durham (3)

N. F. Bogner, Upper Darby

DETAILED GEOLOGIC INVESTIGATION OF DAM SITE

Report No. NH-770G

Investigated by:

William A. Bonin, Geologist

Durham, New Hampshire

C. R. Penney, Field Assistant

Plymouth, New Hampshire

November 21, 1967

GENERAL

State	: New Hampshire	Dam No.	: 1
County	: Coos	Fund Class	: WP-02 (2006)
Township	: Berlin	Structure Class	: c
Watershed	: Dead River	Site Group	: I

SITE DATA

Drainage area	: 6.48 square miles (4,147 acres)
Type of structure	: earth
Purpose	: flood control and recreation
Valley trend	: east (downstream)
Maximum height of fill	: 45 feet
Length of fill	: 2,935 feet
Volume of compacted fill	: 236,000 cubic yards
Steepness of abutments	: 50% and 10% left; 10% and 2% right
Emergency spillway width	: 100 feet

DETAILED GEOLOGIC INVESTIGATION OF DAM SITE

Report No. NH-7703

Investigated by: 12/12/67

William A. Bonin
William A. Bonin, Geologist

Durham, New Hampshire

C. R. Penney, Field Assistant

Plymouth, New Hampshire

November 21, 1967

GENERAL

State : New Hampshire

Dam No. : 1

County : Coos

Fund Class : WP-08 (2006)

Township : Berlin

Structure Class: c

Watershed: Dead River

Site Group : I

SITE DATA

Drainage area : 6.48 square miles (4,147 acres)

Type of structure : earth

Purpose : flood control and recreation

Valley trend : east (downstream)

Maximum height of fill : 45 feet

Length of fill : 2,935 feet

Volume of compacted fill : 236,000 cubic yards

Steepness of abutments : 50% and 10% left; 18% and 2% right

Emergency spillway width : 100 feet

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-112

DRAWING NO.

SHEET 1 OF 1

DATE

DISE

19. Aside from the two low saddles, the foundation and borrow soils are represented by sample 53.1 and 59.1. This overburden is generally semi-pervious and dense. It correlates to the fill material (See item 1).
20. Up to 5 feet of muck was probed in the low, wet saddles. Beneath the muck there is $\frac{1}{2}$ to 2 feet of compact and semi-pervious silty sands. (Sample 52.1) over compact and very pervious, gravels and sands (Sample 52.2) with 15% hard, rounded cobbles and boulders to 18 inches.
21. The depth to bedrock is an assumed depth in this area and the thickness of the outwash is unknown.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE*B-111*

DRAWING NO.

SHEET OF

DATE

to be very pervious. The most pervious material is the "open-work" cobbles and boulders (See TP-5 from 2 to 5 feet). Sample 502.1 represents the finer gradation of the variable outwash.

11. The bedrock has overall adequate "in-place" strength. Leakage rates through the bedrock are minor or insignificant.

DIVERSION AREA

12. There are many surface boulders. The overburden is generally shallow. Sample 10.1 represents most of this material. The water level is at or a few feet above the hard bedrock surface.
13. Sample 904.1 represents a limited area of pervious, coarse-grained soil.

BORROW AND EMERGENCY SPILLWAY AREA

14. The topographic map of the bedrock is contoured to the top of the bedrock surface. A small amount of this rock, as in TP-211 (5 to 9 feet) and DH-208 (10 to 18 feet), can be excavated as earth.
15. Additional borrow is available to the west of this area (See TP's -102; -201, -204).
16. The pegmatite and Oliverian granite are obviously durable rocks. The schistose rock is a non-durable, soft, degradable rock. These rock types can be selected or rejected for use as riprap by field examination.
17. The selection or rejection of the biotite gneiss for use as riprap will present problems as noted:
 - (a) Where granitized, it has the hardness and durability of the granite.
 - (b) Elsewhere it is hard and granular with friable surfaces or decomposed to some depth (4' in TP-211, 3' in TP-501, 5' in TP-502).

Abrasion and soundness tests may assist in the determination of suitability for riprap.

ADDITIONAL BORROW AREA

18. The high knob centered at DH-153 is a good source of fill. More borrow is available to the west of this area (See TP's -151 and -152). The material is represented by sample 4.1. It correlates to the fill material (See item 1).

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-110

DRAWING

SHEET

COMMENTS AND CONCLUSIONS

1. Sample 214.1 and the correlation samples (namely: 4.1, 59.1, 207.1 and 221.1) represent our fill material and most of the overburden at the site. This material is relatively dry (4.6% moisture), somewhat cemented and difficult to excavate. It includes hard, subangular to subrounded rocks as follows:

3%	3" - 6"
2%	6" - 12"
1%	12" - 18" plus occasional larger boulders

This soil in-place is dense and semi-pervious. Most of the cobbles and boulders are near the surface.

2. Surface boulders in the borrow and emergency spillway area total:

53 cubic yards per acre	6" - 18"
311 cubic yards per acre	18" - 36"

3. Surface boulders elsewhere on the site total:

35 cubic yards per acre	6" - 18"
173 cubic yards per acre	18" - 36"

4. There is also 4,250 cubic yards of boulder rock excavation within the grid survey (See drawing sheets 2 and 3).

5. Core material and quality drain fill materials in sufficient quantity are not available on site or within reasonable distance of the site.

AT THE DAM

6. Sample 7.1 represents the overburden in the high "topo" feature that crosses the right abutment.
7. Sample 214.1 is similar to the overburden in the high "topo" feature along the left abutment. Sample 503.2 represents a very pervious inclusion in an otherwise semi-pervious abutment.
8. The foundation is wet except for the high ground along the centerline.
9. There is up to 6.5 feet of muck across the low area in the foundation. The bedrock surface is very irregular in this area. There is some 10 feet of near vertical relief on the bedrock surface. There are outcrops and bedrock was cored at depths of up to 19 feet.
10. The overburden across the low area is thick and variable in type, strength and permeability. Some strata within this outwash are observed

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-109

DRAWING NO.

SHEET OF

The underlying bedrock generally consists of hard, sound and durable, weakly foliated Oliverian granite, hard granular textured biotite gneiss and occasional highly weathered schists.

Exceptions:

Four feet of bedrock (biotite gneiss) was easily excavated from 5 - 9 feet in test pit (TP-211)

Eight feet of very soft biotite-hornblende schist was corered from 10 to 12 feet. Core recovery in similar material was very low.

DIKE

There are no bedrock outcrops in this area. Surface rocks are common but they are not as numerous as at the dam. The areal extent of outwash and till material was determined in the test pitting program. The vertical extent of these materials and the depth to bedrock was not determined.

Except for the area of the saddles, the overburden is glacial till. Up to 5 feet of muck was probed in the saddles. The underlying outwash deposits consist of 0.5 to 2.0 feet of compact and semi-pervious gray SM soil (15% silt and 10% hard, subangular to subrounded gravel) over compact and pervious SP-SM and GP-GM soil. (40 - 60% hard rounded gravels to 3 inches, 5% silt and 15% hard, rounded cobbles and boulders to 18 inches). The water level is at or near the surface and the pit walls were caving. In test pit (TP-57) the ground water was a bright iridescent orange color.

The glacial till in the foundation and adjacent borrow areas is an SM and SP-SM soil. It has 10 - 25% hard, subangular gravel to 3 inches and 10 to 15% silt. It is dense and semi-pervious to pervious. It includes up to 25% hard, subangular rocks from 3 to 24 inches.

In the borrow areas, oversize material includes hard, subangular to sub-rounded rock as follows:

5%	3" - 6"
5%	6" - 12"
10%	12" - 24"

REFERENCES:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-108

DATE: 1961

10/11

There are numerous hard, subangular surface rocks in the above discussed areas, that is:

35 cubic yards per acre from 6 to 18" in size
173 cubic yards per acre from 18" to 36" in size

plus
(rocks over one cubic yard as noted on sheets 2 and 3)

EMERGENCY SPILLWAY AND PRIMARY BORROW AREA

This area has many hard, subangular surface rocks. There are 53 cubic yards per acre from 3 to 18 inches and 311 cubic yards per acre from 18 to 36 inches. Shoulders well over one cubic yard are common. Much of the topsoil in this area has been lost to sheet erosion following forest fires.

The upper few feet of the till (usually one foot but up to 6 feet) are a more rocky SM soil. The overburden is otherwise a less silty sand (SP-SM) with 25% hard, subangular gravel to 3 inches and 10% silt (i.e. non-plastic fines with no dry strength). This material is light olive-tan color, only slightly moist, very dense and semi-pervious. It contains 5% hard subangular rocks to 18 inches. Some of the gravel and plus three inch material is decomposed. Occasional large boulders (some over one cubic yard) occur within the overburden.

IN PLACE TEST DATA

TP - 205 @ 5.0' dry density 118.9 #/Ft³
 4.6% moisture on - 3/4"

TP - 207 @ 5.0' dry density 106.2 #/Ft³
 4.6% moisture on - 3/4"

The following particle-size distribution curve (field determination on dry sieve) is typical of the borrow material:

REFERENCE:

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

13-107

DRAWING NO.

SHEET 6

DATE

The bedrock encountered in these excavations include hard pegmatite, granite and biotite gneiss.

AREA UPSTREAM FROM THE RIGHT WING OF THE DAM
BETWEEN JERICHO BROOK AND THE RESERVOIR

It is through this area that Jericho Brook will be diverted into the reservoir basin. An aqueduct system, as along the broken profile from test pits (TP-11) to (TP-907), may be constructed to maintain water quality through circulation in the reservoir basin.

In test pits (TP-A, -B, -C, -D, -E, -F) hard and granular bedrock (biotite gneiss) was encountered at depths of 2.5 to 4.5 feet. The overburden is a loose and pervious alluvium till with 20% silt and less than 5% gravel. The water level is at or immediately above the bedrock surface. In test pit (TP-F), the furthest downslope of the lettered pits, hard, pink granite was encountered at 6 feet.

Test pits (TP-11, -901 to -903) encountered hard bedrock within 3.5 feet of the surface. The overburden is a moist, silty sand with less than 5% hard angular gravel to 3 inches and 20% silt. Test pits (TP-904, -905) were dug to 10 feet. Bedrock was probably encountered at the bottom of test pit (TP-905). The overburden is dry, pervious and compact gravelly sands and sandy gravels with 10% silt and 40 to 60% hard subangular to subrounded gravel. This coarse material (SP-SM and GP-GM) has 30% hard subangular to subrounded cobbles and boulders to 24 inches. Test pits (TP-906 to -910) encountered hard bedrock within 6 feet of the surface. The overburden is wet. It consists of muck, boulders and very little SM soil with SM-ML inclusions. The overburden includes up to 80% hard angular to subangular cobbles and boulders to 24 inches. The underlying bedrock includes granular textured biotite gneiss, coarse grained granite and pegmatite.

ADDITIONAL BORROW AREAS

Section KK', through the high topographic feature, demonstrates a thick section of till. Drill hole (DH-153) penetrated 49 feet of overburden, which is some 25 feet below the water surface elevation in the swamp. The water level in this boring, measured 8 days after completion of the boring, was at 10.5 feet. The bottom 10 feet of this boring consist of lodgment till that was smeared into a depression in the bedrock surface. The overburden is otherwise the usually sandy till; i.e., silty sands w/15% silt and 15% hard angular gravel, semi-pervious to pervious, and dense. Test pit (TP-4) showed the water-worked inclusions within this sandy till. In one such inclusion at 22 feet in drill hole (DH-153) a permeability rate of 2.6 feet per day was recorded.

Test pit (TP-151) and test pit (TP-152) on section LL' were excavated 5 to 10 feet into the sandy till (SM with 10% silt). Refusal at these depth was presumably near bedrock. The overburden contains up to 35% subangular cobbles and boulders to 1 cubic yard.

REFERENCES:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

13106

DRAWING NO.

SHEET

DATE

D.H. No.	Test Section (ft. - to)	Pressure Loss (psi/min)	W.L. (ft)	Head (ft)	Q (gpm)	K (lps)
303	20.5 - 25.5	greater than 10	2.1	48.1	0.2	0.09
	25.5 - 29.5	less than 10	2.1	48.1	none	--
504	16.5 - 21.5	less than 5	2.6	48.6	none	--
	21.5 - 26.5	less than 10	2.6	48.6	none	--
505	20.0 - 25.0	less than 5	0.0	46.0	none	--
	24.0 - 29.0	none	0.0	46.0	none	--
	29.0 - 34.0	none	0.0	46.0	none	--
18	12.0 - 17.0	less than 10	0.0	34.5	none	--

An occasional partial loss of drill water was noted while coring in drill hole (DH-18). A temporary artesian flow, estimated at 2 gpm, was noted from 15 to 16 feet in drill hole (DH-302) and from 37.5 feet in drill hole (DH-18).

Right Abutment (base of abutment to top of dam)

Except for the high topographic feature investigated with drill hole (DH-19) and test pit (TP-7), this is an area of extensive outcrops and very thin overburden.

Test pit seven (TP-7) was excavated 11 feet into very dense and impervious till. This material is a silty fine to medium sand with 20% silt and less than 5% gravel. There are occasional decomposed and hard subangular pink granite cobbles to 12 inches. The drill hole (DH-19) encountered similar soil to 27 feet and pegmatite was cored from 27 to 52 feet. The overburden took no water; and except for the test section from 37.0 to 42.0, where packers could not be seated, the bedrock took no water.

The outcrops include hard and durable pegmatite and associated graphitic granite. Relatively hard to highly weathered bitite gneiss outcrops between sills of hard pegmatite in the channel bank.

Test pits (TP-9, -11, and -13) were dug 2 feet to bedrock. Test pit (TP-10) was dug to refusal at 6 feet (presumably bedrock). The overburden is generally a firm and pervious silty till with 5% hard angular rock to eighteen inches. In test pit (TP-10) the water level is at 3 feet; in test pit (TP-11) the water level is at the surface.

Test pit (TP-14), the highest excavation on this abutment, was dug in an obscurely stratified till to bedrock at 9 feet. The material is firm and pervious to semi-pervious. It includes silty sands and sandy silts with pockets of medium to coarse sand. Some boulders to one cubic yard were encountered. The water level in November 1966 was at 3 feet. In August 1967 water was brought to the surface by running test pitting equipment over the backfilled pit.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B105

DRAWING NO.

SHEET 01

DATE

the proposed embankment.

The water level is at or near the surface.

Bedrock outcrops in this area. The outcrops include hard and durable pegmatite, graphic granite and some biotite gneiss.

The overburden is up to 19 feet thick. It consists of firm to dense, semi-pervious sands with 15% silt and 10% gravel (SM); loose to very compact, pervious, stratified sands with up to 20% silt and 30% gravel (SP to SM); and openwork rounded and subrounded cobbles and boulders (40% larger than 3 inches, the minus 3 inch is a loose and very pervious GP with 80% larger than $\frac{1}{8}$ inch).

The cored bedrock varied in type and quality. Core recoveries as low as 18, 20 34 and 42% for 5 foot runs are recorded. It appears that only hard pegmatite was recovered in core runs that penetrated both the pegmatite and biotite gneiss. The poorest recoveries occurred in the granular, friable and sometime decomposed biotite gneiss. In drill hole (DH-505) an A-rod was driven 1.5 feet into the biotite gneiss between two core runs.

Bedrock was excavated in test pits (TP-501, -502). In test pit (TP-501) the bedrock from 5 to 6 feet came out in decomposed rock fragments that broke down to SM soil and thin angular slabs of fresh rock up to 18 inches in maximum dimension. Much water was flowing through this zone. The bedrock (biotite gneiss) at 6 feet is hard and fractured. In test pit (TP-502) the biotite gneiss was decomposed and easily excavated from 3 to 6 feet. At 6 feet the rock is hard.

Permeability tests²⁴ in the overburden are not indicative of the actual leakage through the variable, alluvium outwash material. The inability to effectively seat the casing and high water table and low head conditions resulted in negative test results and insignificant flows.

The overall quality of the bedrock hindered or precluded pressure testing much of the bedrock.

- (1) In DH-301, packers couldn't enter the cored rock.
- (2) In DH-302, packers couldn't be seated at all.
- (3) In DH-303, the packers couldn't be seated from 9.5 to 20.5.
- (4) In DH-504, the packers couldn't be seated from 10.5 to 16.5.
- (5) In DH-18, the packers couldn't be seated from 17.0 to 28.0

The following pressure test data was obtained:

REFERENCE

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-104

<u>Test Depth</u> (ft)	<u>Casing Size</u>	<u>W.L.</u> (ft)	<u>Head</u> (ft)	<u>Q</u> (gpm)	<u>K</u> (fpm)
10.0	4"	20.5	10.6	1.1	22.8
20.0	4"	20.5	21.0	12.0	125 $\frac{1}{2}$
20.0	4"	18.2	19.2	9.0	103 $\frac{2}{2}$
25.0	4"	20.5	20.5	0.3	3.2

1/ Turbulent flow Q/A = 0.34 fps

2/ Turbulent flow Q/A = 0.25 fps

In drill holes (DH-16, -17) the water level is deep; i.e., 21.4 and 20.5 feet.

In drill hole (DH-15), near the top of dam elevation, the water level is shallow; i.e., 1.7 feet.

The bedrock includes pegmatite, granite, granitized biotite gneiss and biotite gneiss. With the exception of the biotite gneiss, which is slightly friable along fracture, the bedrock is other wise hard, sound and durable.

Summary of Pressure Testing Results:

<u>D.H. No.</u>	<u>Test Section(NX)</u> (fr. - to)	<u>Pressure Loss</u> (psi/min)	<u>W.L.</u> (ft)	<u>Head</u> (ft)	<u>Q</u> (gpm)	<u>K</u> (fpm)
15	11.0 - 16.0	less than 10	1.7	54.7	none	--
	15.0 - 20.0	none	1.7	51.2	none	--
	20.0 - 25.0	less than 10	1.7	52.4	7.2	3.1
16	26.3 - 46.0	greater than 10	21.4	67.4	4.6	0.5
17	31.0 - 40.0	less than 5	20.5	66.5	none	--

Test pit (TP-503) was dug into the steep abutment slope in the downstream section of this glacial till feature. The upper 11 feet of till is typical of the feature; i.e., silty sands with 5% hard subangular gravel to 3 inches, 15% silt, moist, dense and semi-pervious. The section from 11 to 24 feet is a water-worked inclusion in the till deposit. It is a silty sand with 20% coarse sand to $\frac{1}{4}$ inch, 20% silt, wet, dense and pervious. The high permeability rates in drill hole (DH-17) probably occurred in a similar material.

Foundation (between base of abutments)

This area was investigated with four test pits (TP-501, -502, -5, -602) and six drill holes (DH-501, -502, -503, -504, -505 and -18).

This low area was also extensively probed on 50-foot centers. There is up to 6.5 feet of muck, average thickness 1.5 feet, within the base width of

REFERENCES:

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-103

REPORT NO.

SHEET NO.

DATE

SUMMARY OF FINDINGS

GENERAL

From October 27 to November 7, 1966, a Unit 3/4-yard backhoe (model 1020) and Caterpillar D-6 bulldozer were used to excavate 41 test pits in the foundation area of the dam and emergency spillway-borrow area. Twenty-six additional test pits were excavated from August 1 to August 8, 1967, using a John Deer backhoe (model JD-350) and Caterpillar D-6 bulldozer. The additional test pits were dug in the foundation and borrow areas of the dike, the area between Jericho Brook and the basin, and emergency spillway area.

The drilling program, 21 borings totaling 674 feet, was accomplished from May 25 to July 13, 1967, using 2 skid-mounted drill rigs -- Acker E3, belt drive, hand feed, 36 h.p. and S&H 35 H, hydraulic, 28 h.p. with an Oliver OC-4 tractor.

Thirteen (13) large disturbed samples have been submitted to the Soils Lab for testing and correlation. Some 75 feet of NX core from six (6) borings have also been submitted for durability tests.

FOUNDATION AREA OF THE DAM

Left Abutment (top of dam to base of abutment)

Four test pits (TP-1, -2, -601, -503) and three drill holes (DH-15, -16, -17) delineate this feature. It is a thick deposit of till (26 to 27 feet) which thins to 10 feet near the top of dam elevation.

Test pits (TP-1, -2, -601) located at the base of the hill on the upstream side of the feature, encountered bedrock at 5 to 7.5 feet.

In test pit (TP-1), 1.5 feet of the bedrock (biotite gneiss) was decomposed and easily excavated. In test pit (TP-2), the biotite gneiss was hard and durable from the surface. The water level in these pits is at the surface. This overburden is a rather non-descript bouldery till (SP-SM, SM and ML) with a foot of surface muck. It is wet, loose to firm and pervious to semi-pervious.

Drill holes (DH-16, -17) put down through the top of the feature, encountered the thick section of SM till with 15% silt. This overburden is dense to very dense and generally semi-pervious. In drill hole (DH-16), the overburden accepted no water. In drill hole (DH-17), drill water was lost in a very pervious zone from 18.5 to 20.0 feet and the following permeability test results were obtained:

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-102

DRAWING NO.

SHEET 01

The outwash material between the till features in the foundation of the dam includes sands, gravels and openwork cobbles and boulders. This material is pervious to very pervious and is generally compact. It is up to 19 feet thick and directly overlies bedrock. Outwash also occurs in both saddles in the foundation of the dike. This material includes compact and pervious to very pervious sands and gravels to a depth of over 11 feet.

Muck in the foundation of the dam is up to 6.5 feet thick. In the foundation of the dike up to 5.0 feet of muck was probed.

In contrast to the homogeneous glacial till overburden, the bedrock is structurally complex and variable in type and quality. Oliverian granite intrudes the Ammonoosuc volcanics at the dam site.

The Oliverian granite is a weakly foliated, pink to gray, medium to coarse-grained rock. The principal dark mineral is biotite, which constitutes only a few percent of the rock. Pink pegmatite with occasional graphic intergrowths of quartz and feldspar are associated with the granite. The pegmatites range in size from small dikes and sills (defined by our shallow borings) to larger tabular bodies (greater than 25 feet thick). The granite and pegmatite are hard, sound and durable.

The Ammonoosuc volcanics include biotite gneiss, biotite schist and biotite-hornblende schist.

The gneiss is a fine-grained, dark gray rock consisting of quartz, biotite, plagioclase and potash feldspar. It is generally well foliated and has a fragmental texture. As a rule the weathered surface is granular, friable and disintegrates rather readily. The unweathered rock is apparently sound. There is a granitized zone within the gneiss in contact with the Oliverian granite. The more schistose rock is deeply weathered and decomposed.

The rock structure strikes North 10 to 30° East and dips 5 to 30° Southeast.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B101

DRAWING NO.

SHEET 01

DATE

GENERAL GEOLOGY

The site is located in the very rugged White Mountain Region of northern New Hampshire. It is within the dissected and glaciated Upland Section of the New England Physiographic Province.

Drainage from the northeast flank of Black Crescent Mountain forms Jericho Brook which flows past the reservoir basin, a large upland swamp near the watershed divide. The drainage area controlled is 6.5 square miles, of which 5.7 square miles is diverted from Jericho Brook. Continental glaciation in a mountainous area has created a situation where a large reservoir basin is without a correspondingly large drainage area.

Except for the area of the swamp, the overburden consists of glacial till as ground moraine. This till was carried in and on the ice and not deposited until the ice became stagnant and melted. With continued thinning and retreat of the ice sheet to the northwest, a large volume of glacial meltwater flowed over the watershed divide. This huge glacial river entered the watershed at the location of the dike. It flowed through the area of the upland swamp. And in a complex cycle of glacial-fluvial erosion and deposition, it created and destroyed a temporary glacial lake and cut the spectacular "pothole" at the outlet of the swamp. When deglaciation of the area was complete, the glacial water course was left high and virtually "dry" on the watershed divide. Since immediate post glacial time, the only water that flows into the pothole results from direct rainfall in the basin and unusual flood flows which spill over from Jericho Brook into the upland swamp. In more recent time, that is about 70 years ago, the area was burned over and much of the topsoil was lost to sheet erosion.

The perimeter of the basin is extremely bouldery. Very large boulders, 50 to 150 cubic yards or so, are common. With the exception of the topographic high features in the vicinity of the centerline of the dam and the closed high feature north of the emergency spillway, the glacial till is generally thin or absent. This till was somewhat water-worked at the time of deposition. Lenses of clean, sorted sands with obscure stratification and flow structure around cobbles occurs occasionally within an otherwise massively structured till. The till is rather homogeneous throughout the area. It is an SP-SM and SM soil with 20 to 25% subangular gravel to 3 inches, 10 to 15% silt, 10% coarse sand and 55% fine to medium sands. It is only slightly moist and generally dense and semi-pervious. The coarse fraction, except for occasional decomposed gravel particles and cobbles, is hard, sound and durable. The fine fraction is non-plastic and has no dry strength. The till was excavated with difficulty due to the cobbles, boulders and high percentage of gravel being held firmly within the matrix. This matrix is relatively dry and shows slight iron oxide cementation. The upper few feet of the till (usually one foot but up to 5 or 6 feet depending on the amount of post glacial and recent erosion) contains 5% - 3 to 6 inch, 4% - 6 to 12 inch and 1% - 12 to 18 inch subangular rocks. Beneath the surface till 3 to 18-inch rocks constitute 5% of the material. Over one cubic yard boulders can occur anywhere in the glacial till overburden.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-100

REPORT NO.

SHEET NO.

DATE

NOTE: This site involves construction of the following:

- (a) Dike, 1,665 feet long and 14 feet high, along the watershed divide.
- (b) Diversion and flood way to conduct Jericho Brook, 5.66 square miles (3,622 acres) drainage area, into the reservoir basin.
- (c) An aqueduct system to maintain water quality through circulation in the reservoir basin.

STORAGE ALLOCATION

	<u>Volume</u>	<u>Surface Area</u>	<u>Depth at Dam</u>	<u>Depth at Dike</u>
	(acre-feet)	(acres)	(feet)	(feet)
Sediment pool	5	3	--	--
Recreation pool	1,257	135	25	--
Floodwater pool	1,417	174	35	4

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-99

DRAWING NO.

DATE

NOTE: This site involves construction of the following:

- (a) Dike, 1,665 feet long and 14 feet high, along the watershed divide.
- (b) Diversion and flood way to conduct Jericho Brook, 5.66 square miles (3,622 acres) drainage area, into the reservoir basin.
- (c) An aqueduct system to maintain water quality through circulation in the reservoir basin.

STORAGE ALLOCATION

	<u>Volume</u>	<u>Surface Area</u>	<u>Depth at Dam</u>	<u>Depth at Dike</u>
	(acre-feet)	(acres)	(feet)	(feet)
Sediment pool	5	3	--	--
Recreation pool	1,257	135	25	--
Floodwater pool	1,417	174	35	4

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-113

DRAWING NO.

SHEET 2 OF 12

DATE _____

GENERAL GEOLOGY

The site is located in the very rugged White Mountain region of northern New Hampshire. It is within the dissected and glaciated Upland Section of the New England Physiographic Province.

Drainage from the northeast flank of Black Mount Mountain forms Jericho Brook which flows past the reservoir basin. A large upland swamp near the watershed divide. The drainage area controlled is 6.5 square miles, of which 5.7 square miles is diverted from Jericho Brook. Continental glaciation in a mountainous area has created a situation where a large reservoir basin is without a correspondingly large drainage area.

Except for the area of the swamp, the overburden consists of glacial till as ground moraine. This till was carried on and on the ice and not deposited until the ice became stagnant and melted. With continued thinning and retreat of the ice sheet to the northwest, a large volume of glacial meltwater flowed over the watershed divide. This high glacial river entered the watershed at the location of the dike. It flowed through the area of the upland swamp. And in a complex cycle of glacial-fluvial erosion and deposition, it created and destroyed a temporary glacial lake and cut the spectacular "pothole" at the outlet of the swamp. When deglaciation of the area was complete, the glacial water course was left high and virtually "dry" on the watershed divide. Since immediate post glacial time, the only water that flows into the pothole results from direct rainfall in the basin and unusual flood flows which spill over from Jericho Brook into the upland swamp. In more recent time, that is about 70 years ago, the area was burned over and much of the topsoil was lost to sheet erosion.

The perimeter of the basin is extremely bouldery. Very large boulders, 50 to 150 cubic yards or so, are common. With the exception of the topographic high features in the vicinity of the centerline of the dam and the closed high feature north of the emergency spillway, the glacial till is generally thin or absent. This till was somewhat water-worked at the time of deposition. Lenses of clean, sorted sands with discrete stratification and flow structure around cobbles occurs occasionally within an otherwise massively structured till. The till is rather homogeneous throughout the area. It is an SP-SM and SM soil with 10 to 25% subangular gravel to 3 inches, 10 to 15% silt, 10% coarse sand and 55% fine to medium sands. It is only slightly moist and generally dense and semi-pervious. The coarse fraction, except for occasional decomposed gravel particles and cobbles, is hard, sound and durable. The fine fraction is non-plastic and has no dry strength. The till was excavated with difficulty due to the cobbles, boulders and high percentage of gravel being held firmly within the matrix. This matrix is relatively dry and shows slight iron oxide cementation. The upper few feet of the till (usually one foot but up to 5 or 6 feet depending on the amount of post glacial and recent erosion) contains 5% - 3 to 4 inch, 15% - 6 to 12 inch and 15% - 12 to 18 inch subangular rocks. For all the surface till 3 to 18-inch rocks constitute 5% of the material. Over one cubic yard boulders can occur anywhere in the glacial till overburden.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-114

DRAWING NO.

SHEET 1 OF 12

DATE _____

The outwash material between the till features in the foundation of the dam includes sands, gravels and openwork cobbles and boulders. This material is pervious to very pervious and is generally compact. It is up to 19 feet thick and directly overlies bedrock. Outwash also occurs in both saddles in the foundation of the dike. This material includes compact and pervious to very pervious sands and gravels to a depth of over 11 feet.

Muck in the foundation of the dam is up to 6.5 feet thick. In the foundation of the dike up to 5.0 feet of muck was probed.

In contrast to the homogeneous glacial till overburden, the bedrock is structurally complex and variable in type and quality. Oliverian granite intrudes the Ammonoosuc volcanics at the dam site.

The Oliverian granite is a weakly foliated, pink to gray, medium to coarse-grained rock. The principal dark mineral is biotite, which constitutes only a few percent of the rock. Pink pegmatite with occasional graphic intergrowths of quartz and feldspar are associated with the granite. The pegmatites range in size from small dikes and sills (defined by our shallow borings) to larger tabular bodies (greater than 25 feet thick). The granite and pegmatite are hard, sound and durable.

The Ammonoosuc volcanics include biotite gneiss, biotite schist and biotite-hornblende schist.

The gneiss is a fine-grained, dark gray rock consisting of quartz, biotite, plagioclase and potash feldspar. It is generally well foliated and has a fragmental texture. As a rule the weathered surface is granular, friable and disintegrates rather readily. The unweathered rock is apparently sound. There is a granitized zone within the gneiss in contact with the Oliverian granite. The more schistose rock is deeply weathered and decomposed.

The rock structure strikes North 10 to 30° East and dips 5 to 30° Southeast.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-115

DRAWING NO.

SHEET 11 OF 12

DATE

SUMMARY OF FINDINGS

GENERAL

From October 27 to November 7, 1966, a Unit 3/4-yard backhoe (model 1020) and Caterpillar D-6 bulldozer were used to excavate 41 test pits in the foundation area of the dam and emergency spillway-borrow area. Twenty-six additional test pits were excavated from August 1 to August 8, 1967, using a John Deere backhoe (model JD-350) and Caterpillar D-6 bulldozer. The additional test pits were dug in the foundation and borrow areas of the dike, the area between Jericho Brook and the basin, and emergency spillway area.

The drilling program, 21 borings totaling 674 feet, was accomplished from May 25 to July 18, 1967, using a skid-mounted drill rigs -- Acker RG, belt drive, hand feed, 36 h.p. and S&W 35 H, hydraulic, 28 h.p. with an Oliver OC-4 tractor.

Thirteen (13) large disturbed samples have been submitted to the Soils Lab for testing and correlation. Some 75 feet of NX core from six (6) borings have also been submitted for durability tests.

FOUNDATION AREA OF THE DAM

Left Abutment (top of dam to base of abutment)

Four test pits (TP-1, -2, -601, -503) and three drill holes (DH-15, -16, -17) delineate this feature. It is a thick deposit of till (26 to 27 feet) which thins to 10 feet near the top of dam elevation.

Test pits (TP-1, -2, -601) located at the base of the hill on the upstream side of the feature, encountered bedrock at 5 to 7.5 feet.

In test pit (TP-1), 1.5 feet of the bedrock (biotite gneiss) was decomposed and easily excavated. In test pit (TP-2), the biotite gneiss was hard and durable from the surface. The water level in these pits is at the surface. This overburden is a rather non-descript bouldery till (SP-SM, SM and ML) with a foot of surface muck. It is wet, loose to firm and pervious to semi-pervious.

Drill holes (DH-16, -17) put down through the top of the feature, encountered the thick section of SM till with 15% silt. This overburden is dense to very dense and generally semi-pervious. In drill hole (DH-16), the overburden accepted no water. In drill hole (DH-17), drill water was lost in a very pervious zone from 18.5 to 20.0 feet and the following permeability test results were obtained:

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-116

DRAWING NO.

SHEET 5 OF 12

DATE

<u>Test Depth</u> (ft)	<u>Casing Size</u>	<u>W.L.</u> (ft)	<u>Head</u> (ft)	<u>Q</u> (gpm)	<u>K</u> (fpm)
10.0	4"	20.5	10.6	1.1	22.8
20.0	4"	20.5	21.0	12.0	125 $\frac{1}{2}$
20.0	4"	18.2	19.2	9.0	103 $\frac{2}{2}$
25.0	4"	20.5	20.5	0.3	3.2

1/ Turbulent flow Q/A = 0.34 fps

2/ Turbulent flow Q/A = 0.25 fps

In drill holes (DH-16, -17) the water level is deep; i.e., 21.4 and 20.5 feet.

In drill hole (DH-15), near the top of dam elevation, the water level is shallow; i.e., 1.7 feet.

The bedrock includes pegmatite, granite, granitized biotite gneiss and biotite gneiss. With the exception of the biotite gneiss, which is slightly friable along fracture, the bedrock is other wise hard, sound and durable.

Summary of Pressure Testing Results:

<u>D.H. No.</u>	<u>Test Section(NX)</u> (fr. - to)	<u>Pressure Loss</u> (psi/min)	<u>W.L.</u> (ft)	<u>Head</u> (ft)	<u>Q</u> (gpm)	<u>K</u> (fpm)
15	11.0 - 16.0	less than 10	1.7	54.7	none	--
	15.0 - 20.0	none	1.7	51.2	none	--
	20.0 - 25.0	less than 10	1.7	52.4	7.2	3.1
16	26.3 - 46.0	greater than 10	21.4	67.4	4.6	0.5
17	31.0 - 40.0	less than 5	20.5	66.5	none	--

Test pit (TP-503) was dug into the steep abutment slope in the downstream section of this glacial till feature. The upper 11 feet of till is typical of the feature; i.e., silty sands with 5% hard subangular gravel to 3 inches, 15% silt, moist, dense and semi-pervious. The section from 11 to 14 feet is a water-worked inclusion in the till deposit. It is a silty sand with 20% coarse sand to $\frac{1}{4}$ inch, 20% silt, wet, dense and pervious. The high permeability rates in drill hole (DH-17) probably occurred in a similar material.

Foundation (between base of abutments)

This area was investigated with four test pits (TP-501, -502, -503, -504) and six drill holes (DH-301, -302, -303, -304, -305 and -18).

This low area was also extensively probed on 50-foot centers. There is up to 6.5 feet of muck, average thickness 1.5 feet, within the base width of

REFERENCE:	U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE B-117	DRAWING NO. SHEET <u>1</u> OF <u>12</u> DATE _____
------------	---	--

the proposed embankment.

The water level is at or near the surface.

Bedrock outcrops in this area. The outcrops include hard and dense pegmatite, graphic granite and some biotite gneiss.

The overburden is up to 19 feet thick. It consists of fine to medium, semi-pervious sands with 15% silt and 10% gravel (SM); loose to very compact, pervious, stratified sands with up to 20% silt and 30% gravel (SM to GM); and openwork rounded and subrounded cobbles and boulders (10% larger than 3 inches, the minus 3 inch is a loose and very pervious G₁ with 5% larger than 1/2 inch).

The cored bedrock varied in type and quality. Core recoveries as low as 10, 20, 30 and 40% for 5 foot runs are recorded. It appears that only hard pegmatite was recovered in core runs that penetrated both the pegmatite and biotite gneiss. The poorest recoveries occurred in the granular, friable and sometime decomposed biotite gneiss. In drill hole (DH-505) an A-rod was driven 1.5 feet into the biotite gneiss between two core runs.

Bedrock was excavated in test pits (TP-501, -602). In test pit (TP-501) the bedrock from 5 to 8 feet came out in decomposed rock fragments that broke down to SM soil and thin angular slabs of fresh rock up to 16 inches in maximum dimension. Much water was flowing through this zone. The bedrock (biotite gneiss) at 8 feet is hard and fractured. In test pit (TP-602) the biotite gneiss was decomposed and easily excavated from 3 to 8 feet. At 8 feet the rock is hard.

Permeability tests in the overburden are not indicative of the actual leakage through the variable, alluvium outwash material. The inability to effectively test the casing and high water table and low head conditions resulted in negative test results and insignificant flows.

The overall quality of the bedrock hindered or precluded pressure testing much of the bedrock.

- (1) In DH-501, packers couldn't enter the cored rock.
- (2) In DH-502, packers couldn't be seated at all.
- (3) In DH-503, the packers couldn't be seated from 9.5 to 20.5.
- (4) In DH-504, the packers couldn't be seated from 12.5 to 14.5.
- (5) In DH-505, the packers couldn't be seated from 17.0 to 35.0.

The following pressure test data was obtained:

REFERENCES:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-118

DRAWING NO.

SHEET 1 OF 2

DATE _____

D.H. No.	Test Section(HX) (fr. - to)	Pressure Loss (psi/min)	W.L. (ft)	Head (ft)	Q (gpm)	K (fpm)
303	20.5 - 25.5	greater than 10	2.1	48.1	0.2	0.09
	25.5 - 29.5	less than 10	2.1	48.1	none	--
504	16.5 - 21.5	less than 5	2.6	48.6	none	--
	21.5 - 26.5	less than 10	2.6	48.6	none	--
505	20.0 - 25.0	less than 5	0.0	46.0	none	--
	24.0 - 29.0	none	0.0	46.0	none	--
	29.0 - 34.0	none	0.0	46.0	none	--
18	12.0 - 17.0	less than 10	0.0	34.5	none	--

An occasional partial loss of drill water was noted while coring in drill hole (DH-18). A temporary artesian flow, estimated at 2 gpm, was noted from 15 to 16 feet in drill hole (DH-302) and from 37.5 feet in drill hole (DH-18).

Right Abutment (base of abutment to top of dam)

Except for the high topographic feature investigated with drill hole (DH-19) and test pit (TP-7), this is an area of extensive outcrops and very thin overburden.

Test pit seven (TP-7) was excavated 11 feet into very dense and impervious till. This material is a silty fine to medium sand with 20% silt and less than 5% gravel. There are occasional decomposed and hard subangular pink granite cobbles to 12 inches. The drill hole (DH-19) encountered similar soil to 27 feet and pegmatite was cored from 27 to 52 feet. The overburden took no water; and except for the test section from 37.0 to 42.0, where packers could not be seated, the bedrock took no water.

The outcrops include hard and durable pegmatite and associated graphic granite. Relatively hard to highly weathered bitite gneiss outcrops between sills of hard pegmatite in the channel bank.

Test pits (TP-9, -11, and -13) were dug 2 feet to bedrock. Test pit (TP-10) was dug to refusal at 6 feet (presumably bedrock). The overburden is generally a firm and pervious SM till with 5% hard angular rock to eighteen inches. In test pit (TP-10) the water level is at 3 feet; in test pit (TP-11) the water level is at the surface.

Test pit (TP-1.), the highest excavation on this abutment, was dug in an obscurely stratified till to bedrock at 9 feet. The material is firm and pervious to semi-pervious. It included silty sand and sandy silts with pockets of medium to coarse sand. Some boulders to one cubic yard were encountered. The water level in November 1966 was at 3 feet. In August 1967 water was brought to the surface by running test pitting equipment over the backfilled pit.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B119

DRAWING NO.

SHEET 5 OF 12

DATE

The bedrock encountered in these excavations included hard pegmatite, granite and biotite gneiss.

AREA UPSTREAM FROM THE RIGHT WING OF THE DAM
BETWEEN JERICHO BASIN AND THE RESERVOIR

It is through this area that Jericho Brook will be diverted into the reservoir basin. An aqueduct system, as along the broken profile from test pits (TP-11) to (TP-907), may be constructed to maintain water quality through circulation in the reservoir basin.

In test pits (TP-A, -B, -C, -D, -E, -F) hard and granular bedrock (biotite gneiss) was encountered at depths of 2.5 to 4.5 feet. The overburden is a loose and porous alluvium till with 20% silt and less than 5% gravel. The water level is at or immediately above the bedrock surface. In test pit (TP-F), the furthest downslope of the lettered pits, hard, pink granite was encountered at 6 feet.

Test pits (TP-11, -901 to -903) encountered hard bedrock within 3.5 feet of the surface. The overburden is a moist, silty sand with less than 5% hard angular gravel to 3 inches and 20% silt. Test pits (TP-904, -905) were dug to 11 feet. Bedrock was probably encountered at the bottom of test pit (TP-905). The overburden is dry, pervious and compact gravelly sands and sandy gravels with 10% silt and 40 to 60% hard subangular to subrounded gravel. This coarse material (SP-SM and GP-GM) has 30% hard subangular to subrounded cobbles and boulders to 2 1/2 inches. Test pits (TP-906 to -910) encountered hard bedrock within 6 feet of the surface. The overburden is wet. It consists of muck, boulders and very little SM soil with SM-ME inclusions. The overburden includes up to 80% hard angular to subangular cobbles and boulders to 2 1/2 inches. The underlying bedrock includes granular textured biotite gneiss, coarse grained granite and pegmatite.

ADDITIONAL BORROW AREAS

Section KK', through the high topographic feature, demonstrates a thick section of till. Drill hole (DH-153) penetrated 49 feet of overburden, which is some 15 feet below the water surface elevation in the swamp. The water level in this boring, measured 8 days after completion of the boring, was at 11.5 feet. The bottom 10 feet of this boring consist of lodgment till that was sheared into a depression in the bedrock surface. The overburden is otherwise the usually sandy till; i.e., silty sands w/15% silt and 15% hard angular gravel, semi-pervious to pervious, and dense. Test pit (TP-1) showed the water-worked inclusions within this sandy till. In one such inclusion at 22 feet in drill hole (DH-153) a permeability rate of 2.6 feet per day was recorded.

Test pit (TP-151) and test pit (TP-152) on section LL' were excavated 5 to 11 feet into the sandy till (SM with 1 1/2% silt). Refusal at those depths was probably near bedrock. The overburden contains up to 35% subangular cobbles and boulders to 2 1/2 inches.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-120

DRAWING NO.

SHEET 2 OF 12

DATE

There are numerous hard, subangular surface rocks in the above discussed areas, that is:

35 cubic yards per acre from 6 to 18" in size
173 cubic yards per acre from 18" to 36" in size
plus
rocks over one cubic yard as noted on sheets 2 and 3

EMERGENCY SPILLWAY AND PRIMARY BORROW AREA

This area has many hard, subangular surface rocks. There are 53 cubic yards per acre from 3 to 18 inches and 311 cubic yards per acre from 18 to 36 inches. Boulders well over one cubic yard are common. Much of the topsoil in this area has been lost to sheet erosion following forest fires.

The upper few feet of the till (usually one foot but up to 6 feet) are a more rocky SM soil. The overburden is otherwise a less silty sand (SP-SM) with 25% hard, subangular gravel to 3 inches and 10% silt (i.e. non-plastic fines with no dry strength). This material is light olive-tan color, only slightly moist, very dense and semi-pervious. It contains 5% hard subangular rocks to 18 inches. Some of the gravel and plus three inch material is decomposed. Occasional large boulders (some over one cubic yard) occur within the overburden.

IN PLACE TEST DATA

TP - 205 @ 5.0' dry density 118.9 #/Ft³
 4.6% moisture on - 3/4"

TP - 207 @ 5.0' dry density 106.2 #/Ft³
 4.6% moisture on - 3/4"

The following particle-size distribution curve (field determination on dry sieve) is typical of the borrow material:

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-121

DRAWING NO.

SHEET 10 OF 12

DATE

The underlying bedrock generally consists of hard, sound and durable, weakly foliated Oliverian granite, hard granular textured biotite gneiss and occasional highly weathered schists.

Exceptions:

Four feet of bedrock (biotite gneiss) was easily excavated from 5 - 9 feet in test pit (TP-211)

Eight feet of very soft biotite-hornblende schist was cored from 10 to 18 feet. Core recovery in similar material was very low.

DIKE

There are no bedrock outcrops in this area. Surface rocks are common but they are not as numerous as at the dam. The areal extent of outwash and till material was determined in the test pitting program. The vertical extent of these materials and the depth to bedrock was not determined.

Except for the area of the saddles, the overburden is glacial till. Up to 5 feet of muck was probed in the saddles. The underlying outwash deposits consist of 0.5 to 2.0 feet of compact and semi-pervious gray SM soil (1% silt and 10% hard, subangular to subrounded gravel) over compact and pervious SP-SM and GP-GM soil. (40 - 60% hard rounded gravels to 3 inches, 5% silt and 15% hard, rounded cobbles and boulders to 18 inches). The water level is at or near the surface and the pit walls were caving. In test pit (TP-57) the ground water was a bright iridescent orange color.

The glacial till in the foundation and adjacent borrow areas is an SM and SP-SM soil. It has 10 - 25% hard, subangular gravel to 3 inches and 10 to 15% silt. It is dense and semi-pervious to pervious. It includes up to 25% hard, subangular rocks from 3 to 24 inches.

In the borrow areas, oversize material includes hard, subangular to sub-rounded rock as follows:

5%	3" - 6"
5%	6" - 12"
10%	12" - 24"

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-122

DRAWING NO.

SHEET 15 OF 18

DATE

COMMENTS AND CONCLUSIONS

1. Sample 211.1 and the correlation samples (namely: 4.1, 59.1, 207.1 and 221.1) represent our fill material and most of the overburden at the site. This material is relatively dry (4.6% moisture), somewhat cemented and difficult to excavate. It includes hard, subangular to subrounded rocks as follows:

3%	3" - 6"
2%	6" - 12"
1%	12" - 18" plus occasional larger boulders

This soil in-place is dense and semi-pervious. Most of the cobbles and boulders are near the surface.

2. Surface boulders in the borrow and emergency spillway area total:

53 cubic yards per acre	6" - 18"
311 cubic yards per acre	18" - 36"

3. Surface boulders elsewhere on the site total:

35 cubic yards per acre	6" - 18"
173 cubic yards per acre	18" - 36"

4. There is also 4,250 cubic yards of boulder rock excavation within the grid survey (See drawing sheets 2 and 3).

5. Core material and quality drain fill materials in sufficient quantity are not available on site or within reasonable distance of the site.

AT THE DAM

6. Sample 7.1 represents the overburden in the high "topo" feature that crosses the right abutment.
7. Sample 211.1 is similar to the overburden in the high "topo" feature along the left abutment. Sample 503.2 represents a very pervious inclusion in an otherwise semi-pervious abutment.
8. The foundation is wet except for the high ground along the centerline.
9. There is up to 6.5 feet of muck across the low area in the foundation. The bedrock surface is very irregular in this area. There is some 10 feet of near vertical relief on the bedrock surface. There are outcrops and bedrock was cored at depths of up to 19 feet.
10. The overburden across the low area is thick and variable in type, strength and permeability. Some strata within this outwash are observed

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-123

DRAWING NO.

SHEET 13 OF 15

DATE

FOR IN-SERVICE USE ONLY

to be very pervious. The most pervious material is the "open-work" cobbles and boulders (See TP-5 from 2 to 5 feet). Sample 501.1 represents the finer gradation of the variable outwash.

11. The bedrock has overall adequate "in-place" strength. Leakage rates through the bedrock are minor or insignificant.

DIVERSION AREA

12. There are many surface boulders. The overburden is generally shallow. Sample 1.1 represents most of this material. The water level is at or a few feet above the hard bedrock surface.
13. Sample 901.1 represents a limited area of pervious, coarse-grained soil.

BORROW AND EMERGENCY SPILLWAY AREA

14. The topographic map of the bedrock is contoured to the top of the bedrock surface. A small amount of this rock, as in TP-211 (5 to 9 feet) and DH-10 (10 to 18 feet), can be excavated as earth.
15. Additional borrow is available to the west of this area (See TP's -102, -201, -201).
16. The pegmatite and Oliverian granite are obviously durable rocks. The schistose rock is a non-durable, soft, degradable rock. These rock types can be selected or rejected for use as riprap by field examination.
17. The selection or rejection of the biotite gneiss for use as riprap will present problems as noted:
- (a) Where granitized, it has the hardness and durability of the granite.
 - (b) Elsewhere it is hard and granular with friable surfaces or decomposed to some depth (4' in TP-211, 5' in TP-901, 5' in TP-800).

Abrasion and soundness tests may assist in the determination of suitability for riprap.

ADDITIONAL BORROW AREA

18. The high knob centered at DH-153 is a good source of fill. More borrow is available to the west of this area (See TP's -151 and -152). The material is represented by sample 4.1. It correlates to the fill material (See item 1).

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-124

DRAWING NO.

SHEET 14 OF 15

DATE _____

DIKE

19. Aside from the two low saddles, the foundation and borrow soils are represented by sample 53.1 and 59.1. This overburden is generally semi-pervious and dense. It correlates to the fill material (See item 1).
20. Up to 5 feet of muck was probed in the low, wet saddles. Beneath the muck there is up to 2 feet of compact and semi-pervious silty sands (Sample 53.1) over compact and very pervious, gravels and sands (Sample 59.1) with 15% hard, rounded cobbles and boulders to 18 inches.
21. The depth to bedrock is an assumed depth in this area and the thickness of the outwash is unknown.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-125

DRAWING NO.

SHEET 15 OF 15

DATE

ENGINEERING INTERPRETATIONS, RECOMMENDATIONS AND
CONCLUSIONSGeneral

The structure, a multiple-purpose flood control - recreation dam, is located in a large basin on the northerly side of Jericho Brook, in Berlin, New Hampshire.

Centerline of Dam

Various centerline of dam locations have been studied. A centerline along the high topographical features, as proposed in planning, would probably require the least amount of fill; but this particular centerline would propose difficulty during construction due to the number of angles required for layout along the high features.

The demonstrated centerline was chosen for the following reasons:

1. On the left abutment, the proposed centerline is located on the upstream side of the high features. By locating the dam upstream of these features, pervious zones, such as found in BH-17 from 18.5 to 20.0 feet, could be cut-off with the blanket effect of the fill against the slope. Also, the pervious zones would be in a more desirable location in the foundation.
2. The high topographical feature upstream of the centerline in the vicinity of station 29+00 and 34+00 could be used as a source of borrow. This could be excavated to a level that is approximately the elevation of the surrounding swamp. Any stratifications of sand, such as found in TF-4, therefore, would not be in the foundation of the dam.
3. On the right abutment, in the vicinity of station 20+00 and 19+00, the centerline goes through a high feature. Investigation didn't indicate any stratification of pervious sands in the feature. The bulk of the feature lies downstream of the centerline; and if any stratification is present, it would be more desirable having it downstream of the centerline rather than upstream.
4. With the proposed centerline, there would be a better opportunity to extend the cut-off to bedrock in the area of the high features. This possibility could be further


REFERENCES:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-126

DRAWING NO.

SHEET 1 OF 8
DATE 10/21/51



DEAD RIVER WATERSHED PROJECT MULTIPLE PURPOSE DAM NO. 1

DRAINAGE AREA 414.7 ACRES
FLOOD STORAGE 155.9 ACRE FT
WATER SURFACE AREA 132 ACRES
HEIGHT OF DAM 46 FEET
VOLUME OF FILL 269,549 CUBIC YARDS

BUILT UNDER THE WATERSHED PROTECTION AND
FLOOD PREVENTION ACT

by
COOS COUNTY SOIL CONSERVATION DISTRICT,
CITY OF BERLIN, NEW HAMPSHIRE

and the
NEW HAMPSHIRE WATER RESOURCES BOARD

with assistance of
U S DEPARTMENT OF AGRICULTURE, SOIL CONSERVATION SERVICE

1968
1/2

INDEX

SHEET 1 - COVER SHEET	SHEET 2 - LOCATION MAP
SHEET 3 - PLAN OF STORAGE AREA	SHEET 4 - PLAN OF DAM LENGTH
SHEET 5 - PLAN OF DAM HEIGHT	SHEET 6 - PLAN OF DAM PROFILE OF DYE
SHEET 7 - PLAN OF DAM PROFILE OF DYE	SHEET 8 - PLAN OF DAM PROFILE OF DYE
SHEET 9 - PLAN OF DAM PROFILE OF DYE	SHEET 10 - PLAN OF DAM PROFILE OF DYE
SHEET 11 - PLAN OF DAM PROFILE OF DYE	SHEET 12 - PLAN OF DAM PROFILE OF DYE
SHEET 13 - PLAN OF DAM PROFILE OF DYE	SHEET 14 - PLAN OF DAM PROFILE OF DYE
SHEET 15 - PLAN OF DAM PROFILE OF DYE	SHEET 16 - PLAN OF DAM PROFILE OF DYE
SHEET 17 - PLAN OF DAM PROFILE OF DYE	SHEET 18 - PLAN OF DAM PROFILE OF DYE
SHEET 19 - PLAN OF DAM PROFILE OF DYE	SHEET 20 - PLAN OF DAM PROFILE OF DYE
SHEET 21 - PLAN OF DAM PROFILE OF DYE	SHEET 22 - PLAN OF DAM PROFILE OF DYE
SHEET 23 - PLAN OF DAM PROFILE OF DYE	SHEET 24 - PLAN OF DAM PROFILE OF DYE
SHEET 25 - PLAN OF DAM PROFILE OF DYE	SHEET 26 - PLAN OF DAM PROFILE OF DYE
SHEET 27 - PLAN OF DAM PROFILE OF DYE	SHEET 28 - PLAN OF DAM PROFILE OF DYE
SHEET 29 - PLAN OF DAM PROFILE OF DYE	SHEET 30 - PLAN OF DAM PROFILE OF DYE
SHEET 31 - PLAN OF DAM PROFILE OF DYE	SHEET 32 - PLAN OF DAM PROFILE OF DYE
SHEET 33 - PLAN OF DAM PROFILE OF DYE	SHEET 34 - PLAN OF DAM PROFILE OF DYE
SHEET 35 - PLAN OF DAM PROFILE OF DYE	SHEET 36 - PLAN OF DAM PROFILE OF DYE
SHEET 37 - PLAN OF DAM PROFILE OF DYE	SHEET 38 - PLAN OF DAM PROFILE OF DYE
SHEET 39 - PLAN OF DAM PROFILE OF DYE	SHEET 40 - PLAN OF DAM PROFILE OF DYE
SHEET 41 - PLAN OF DAM PROFILE OF DYE	SHEET 42 - PLAN OF DAM PROFILE OF DYE
SHEET 43 - PLAN OF DAM PROFILE OF DYE	SHEET 44 - PLAN OF DAM PROFILE OF DYE
SHEET 45 - PLAN OF DAM PROFILE OF DYE	SHEET 46 - PLAN OF DAM PROFILE OF DYE
SHEET 47 - PLAN OF DAM PROFILE OF DYE	SHEET 48 - PLAN OF DAM PROFILE OF DYE
SHEET 49 - PLAN OF DAM PROFILE OF DYE	SHEET 50 - PLAN OF DAM PROFILE OF DYE
SHEET 51 - PLAN OF DAM PROFILE OF DYE	SHEET 52 - PLAN OF DAM PROFILE OF DYE
SHEET 53 - PLAN OF DAM PROFILE OF DYE	SHEET 54 - PLAN OF DAM PROFILE OF DYE
SHEET 55 - PLAN OF DAM PROFILE OF DYE	SHEET 56 - PLAN OF DAM PROFILE OF DYE
SHEET 57 - PLAN OF DAM PROFILE OF DYE	SHEET 58 - PLAN OF DAM PROFILE OF DYE
SHEET 59 - PLAN OF DAM PROFILE OF DYE	SHEET 60 - PLAN OF DAM PROFILE OF DYE
SHEET 61 - PLAN OF DAM PROFILE OF DYE	SHEET 62 - PLAN OF DAM PROFILE OF DYE
SHEET 63 - PLAN OF DAM PROFILE OF DYE	SHEET 64 - PLAN OF DAM PROFILE OF DYE
SHEET 65 - PLAN OF DAM PROFILE OF DYE	SHEET 66 - PLAN OF DAM PROFILE OF DYE
SHEET 67 - PLAN OF DAM PROFILE OF DYE	SHEET 68 - PLAN OF DAM PROFILE OF DYE
SHEET 69 - PLAN OF DAM PROFILE OF DYE	SHEET 70 - PLAN OF DAM PROFILE OF DYE
SHEET 71 - PLAN OF DAM PROFILE OF DYE	SHEET 72 - PLAN OF DAM PROFILE OF DYE
SHEET 73 - PLAN OF DAM PROFILE OF DYE	SHEET 74 - PLAN OF DAM PROFILE OF DYE
SHEET 75 - PLAN OF DAM PROFILE OF DYE	SHEET 76 - PLAN OF DAM PROFILE OF DYE
SHEET 77 - PLAN OF DAM PROFILE OF DYE	SHEET 78 - PLAN OF DAM PROFILE OF DYE
SHEET 79 - PLAN OF DAM PROFILE OF DYE	SHEET 80 - PLAN OF DAM PROFILE OF DYE
SHEET 81 - PLAN OF DAM PROFILE OF DYE	SHEET 82 - PLAN OF DAM PROFILE OF DYE
SHEET 83 - PLAN OF DAM PROFILE OF DYE	SHEET 84 - PLAN OF DAM PROFILE OF DYE
SHEET 85 - PLAN OF DAM PROFILE OF DYE	SHEET 86 - PLAN OF DAM PROFILE OF DYE
SHEET 87 - PLAN OF DAM PROFILE OF DYE	SHEET 88 - PLAN OF DAM PROFILE OF DYE
SHEET 89 - PLAN OF DAM PROFILE OF DYE	SHEET 90 - PLAN OF DAM PROFILE OF DYE
SHEET 91 - PLAN OF DAM PROFILE OF DYE	SHEET 92 - PLAN OF DAM PROFILE OF DYE
SHEET 93 - PLAN OF DAM PROFILE OF DYE	SHEET 94 - PLAN OF DAM PROFILE OF DYE
SHEET 95 - PLAN OF DAM PROFILE OF DYE	SHEET 96 - PLAN OF DAM PROFILE OF DYE
SHEET 97 - PLAN OF DAM PROFILE OF DYE	SHEET 98 - PLAN OF DAM PROFILE OF DYE
SHEET 99 - PLAN OF DAM PROFILE OF DYE	SHEET 100 - PLAN OF DAM PROFILE OF DYE



U S DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
COVER SHEET
BERLIN, NEW HAMPSHIRE
MULTIPLE PURPOSE DAM NO. 1
DEAD RIVER WATERSHED PROJECT

FOR IN SERVICE USE ONLY

turn over of the water throughout the site if the Jericho Brook base flow is allowed to enter the recreation pool in the vicinity of the principal spillway. To lessen such a potential short circuiting, flows as large as possible will be diverted into the reservoir as far upstream as is feasible.

It is quite probable that this water quality diversion will be a small pipe or channel conducting flow from Jericho Brook to a point well upstream of the dam.

Arthur N. Luktala

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-133

DRAWING NO.

SHEET *6* OF *8*

DATE *12/26/47*

FOR IN SERVICE USE ONLY

The dike will be subject to small heads during flood times and no head during normal conditions. It is anticipated that no unusual design measures are required.

The only foundation treatment required appears to be the removal of the muck encountered in the two saddles.

A cut-off will be excavated 3 or 4 feet into the ground to penetrate through the zone of frost action.

Drainage measures are expected to be accomplished by selective placement. Outwash material from the saddles and the coarsest of the borrow materials will be placed in a downstream blanket zone. In the saddles and low areas, where the dike is subject to the greatest head, oversize rocks can be wasted on the downstream face and toe of the structure.

Proposed side slopes for the dike are 3:1 both upstream and downstream.

Adequate borrow material is available for construction of the dike from the high topographical features located both upstream and downstream of the centerline. It is important that any of these areas used are dressed and neatly graded and provided with positive drainage because of the recreation involved.

Local complications preclude diverting waters from one watershed to another. Therefore, the use of this saddle for an emergency spillway will not be allowed.

Verde Rock Diversion

This diversion is primarily required to divert a major portion of Verde Rock into this relatively economical site.

Test holes, surface outcrops and the irregular topography indicate that the diversion will involve rock excavation.

Studies are being made to determine the most economical manner to accomplish the diversion. The varying rock depth and irregular rock surface complicates these studies.

The final solution is expected to be a wide floodway involving soil and rock excavation along with some diking and riprapping sections.

Since this structure is to be used for multi-purpose recreation, it is imperative that the water quality be adequate for bathing. Some question exists whether there will be sufficient

REFERENCE

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-132

DRAWING NO.

SHEET 7 OF 8
APR 12 1967

FOR IN SERVICE USE ONLY

If the quantity of oversize is adequate, a zone of riprap on the lower upstream face of the dam will be called for. A zone of this nature, particularly on the right abutment where the dam also serves as a dike for the Jericho Brook diversion, would keep the face of the slope from eroding during flood flows. Bedrock excavated from the emergency spillway could be used as riprap. The quantity of oversize material appears large enough so that any excess rock not used as riprap will be considered for use in a fill zone containing oversize material up to 18", or as a rock fill.

Due to the expansive pool area and the easterly trend of the valley, the prevailing west winds would make the dam vulnerable to wave action. A zone of riprap would help in stabilizing the upstream slope of the dam.

Proposed side slopes for the dam are 3:1 upstream and $2\frac{1}{2}$:1 downstream.

The primary borrow source is the emergency spillway area. The emergency spillway excavation (55,000 c.y.) will not provide sufficient borrow, so the area adjacent to the spillway will be used for borrow. From the recreation aspect, it is important that the area be sloped, neatly dressed, and provided with positive drainage.

The high topographical feature located upstream of the centerline in the area to the right of the principal spillway will be used as a source of borrow. It will be excavated to some predetermined elevation well below recreation pool level.

The area west of the high feature was investigated as a borrow source. The overburden was relatively rocky and somewhat thin in places.

The Jericho Brook diversion will be another source of borrow materials. These materials will be used in any necessary diking to contain flows in the water quality circulation system, or in the dam itself, depending on the volume of the excavations. Much excavation in this area is expected to be small. Rock excavation from this source will be used as riprap.

Dike

A 1,600-foot dike is required on the upper end of the storage basin to prevent flood flows from entering the Ammonoosuc Watershed.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-131

DRAWING NO.

SHEET 6 OF 8

DATE 12/26/67

FOR IN SERVICE USE ONLY

2. Any unsuitable materials in the foundation will be removed particularly in the area of the left abutment from station 31+00 to 37+00.
3. The steep slope on the left abutment next to the principal spillway location should be cut back to an acceptable slope.

Emergency Spillway

The emergency spillway is located on the left abutment. The layout was based on a study of the bedrock contours of the area. An economic study was developed to determine the most economic proportioning of the structure. The study shows a spillway with a 100-foot bottom width, a crest elevation of 1362.0, and a top of dam elevation of 1371.0 to be the most economical layout.

The emergency spillway layout does not yield sufficient fill to construct the dam. It will be necessary to go to a borrow area for additional fill. The rock excavated from the spillway will be used for riprap as required.

The control section will bottom on bedrock. The side slopes proposed are 1:1 in rock and 4:1 in earth.

An additional safety factor has been provided. The emergency spillway crest was set one foot above the elevation required for a 100-year long-duration storm. This reduced the amount of rock excavation and still left the control section on bedrock.

The emergency spillway outlets into a drainage way that enters the stream approximately 2,000 feet below the structure. Therefore, flowing water in the emergency spillway will not impinge on the dam.

The profile of the emergency spillway is such that it provides maximum bulk. The exit channel is directed away from the structure and a considerable distance downstream before discharge is permitted on natural relief.

Embankment and Borrow Areas - Dam

All of the available borrow, from the emergency spillway and borrow areas, appears to be homogeneous.

It appears as if more compactive effort could be used in a core zone because of the lack of good quality core material. The shell zones could be designed to incorporate oversize material in the 1-2 inch range.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-130

DRAWING NO.

SHEET 5 OF 8

DATE 10/21/67

FOR IN SERVICE USE ONLY

required. Material for such a drain would undoubtedly have to come from materials located off site.

It may be possible to relieve the pervious zone found in DH-17 from 18.5 to 20.0 by tapping into that strata with a trench if it is encountered during foundation excavations.

The approximately 5,000 cubic yards of GP-GM material as found in TP-994 might be considered a useable pit run blanket material in the low area (station 22+00 to 28+00).

The geologist has indicated that leakage through bedrock is minor.

Other factors to be considered in drainage design are as follows:

1. Sand and gravel of significant quantity and quality are not available on site or within close proximity (except as noted above).
2. The closest source of pit run sands and gravels occurs in the Lead River Valley adjacent to IH Route 110, approximately 4 miles away.

Principal Spillway

The principal spillway location is proposed at the base of the high feature on the left abutment. This appears to be the best location. By moving the alignment to the left into the slope, a sizeable excavation will be required. Moving the alignment to the right would result in bridging the two outcrops of bedrock which would be undesirable. Moving the alignment to a location where the pipe would be all on bedrock would not allow a pond drain system without excessive excavation of rock.

It appears that a cantilever outlet with a plunge pool will be the appropriate energy dissipator for the pipe outlet. If bedrock is encountered in the plunge pool, it will be blasted out to the required grades.

Foundation Treatment - Dam

1. Any muck in the foundation area of the dam will be excavated to a suitable material prior to the placement of any fill. It will be important during construction to see that excavation includes muck around nested boulders and bottoms out on a firm material.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-129

DATE: 11/20/60.

BY: [Signature]
[Signature]

FOR IN SERVICE USE ONLY

From the high feature on the right abutment to Jericho Brook a cut-off can be extended to bedrock with shallow cuts of 0 to 7 feet.

Drainage - Dam

Stratification of the water-worked till and the perviousness of the alluvium outwash indicates the need for drainage measures.

On the left abutment from DH-15 toward the high features, bedrock could be reached with a standard trench drain. In the area of the high "topo," bedrock is over 20 feet deep as indicated by DH-16 and DH-17. To what depth should a trench drain be extended in the area of these features? A pipe collector could be installed and outleted in the drainage way, between the high features, in the vicinity of station 31+00.

At the base of the high feature, in the area of the principal spillway, a trench could be extended around the toe, beyond the embankment, to intercept any stratifications or lenses present.

In the flat area between the base of the abutments, the outwash is up to 19 feet deep as indicated by DH-505. A pipe collector drain is recommended in this area. A blanket drain may also be necessary if the embankment material is not compatible with the foundation material.

Openwork cobbles and boulders are described as representing portions of the overburden in this area. What measures should be taken in the design and construction phases if it is anticipated that they present a serious problem?

The foundation in this area appears as if consolidation will present no problem.

With the foundation being so pervious and ground water at the ground surface, it is expected that dewatering to an elevation close to bedrock will be extremely difficult. To what depth should a trench be extended across this area? Should any other special measures be taken in this area?

The high feature investigation by DH-19 shows 27 feet of overburden. To what depth should the trench be extended in the area of deep overburden?

Because the fill is generally homogeneous, and there is some question as to obtaining a downstream shell zone significantly more pervious than the core zone, a chimney drain may be

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-128

DRAWING NO.

SHEET 3 OF 8

DATE 10/26/47

FOR IN SERVICE USE ONLY

increased if the cut-off were placed upstream of the centerline.

5. Having only one angle in the dam would simplify construction.

Cut-off - Dam

The fact that this structure is a multiple-purpose recreation dam, with a 135-acre lake and a maximum depth of 25 feet, would indicate the need for a cut-off.

A cut-off will disclose and obstruct any stratifications or lenses found in the water-worked till of the foundation. A good quality core material is not available on site, so any cutting off will have to be accomplished with the available soils on site.

It appears as though an upstream cut-off can be extended to bedrock on the left abutment with cuts of 10 feet or less until you reach the high feature near the stream. In this particular feature, bedrock is 27 feet deep as indicated by PH-17. It is not believed necessary to extend the cut-off to bedrock in this area. Possibly extending it 10 feet or so to lengthen the flow path would be adequate. A blanket could be placed on the face of the slope and extended some distance upstream if necessary.

In the area of the principal spillway, bedrock was encountered from 8 to 11 feet. Some of it was highly weathered and easily excavated with a backhoe. It is anticipated that zones of weathered rock carrying much water will be removed. To the right of the principal spillway there is an outcrop of bedrock, indicating some sharp relief in the bedrock surface.

Across the foundation area, between the base of the abutments, bedrock was encountered from 0-11 feet upstream of the centerline. It appears that a positive cut-off can be realized. If water is at the ground surface in much of this area, so it is expected that water will be a major problem during construction.

On the high feature near the base of the right abutment, bedrock was encountered at 17 feet as indicated by PH-17. To what depth should the cut-off be extended in this area? PH-19 and TP-7 indicated this to be very dense and impervious. A depth of 5 feet to penetrate the surface zone may be adequate for PH-17.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

B-127


DRAWING NO.

SHEET 8 OF 8

DATE 12/1/57

CONCRETE SPILLWAY

1. The spillway is to be constructed of concrete and shall be designed to pass a flood of 10,000 cfs.
2. The spillway shall be 100 feet wide at the crest and 15 feet high.
3. The spillway shall be 10 feet wide at the base and 15 feet high.
4. The spillway shall be 10 feet wide at the crest and 15 feet high.
5. The spillway shall be 10 feet wide at the crest and 15 feet high.
6. The spillway shall be 10 feet wide at the crest and 15 feet high.
7. The spillway shall be 10 feet wide at the crest and 15 feet high.




Station	Elevation	Notes
1+00	100.0	Top of spillway crest
1+25	95.0	Top of spillway base
1+50	90.0	Top of spillway base
1+75	85.0	Top of spillway base
2+00	80.0	Top of spillway base


Station	Elevation	Notes
1+00	100.0	Top of spillway crest
1+25	95.0	Top of spillway base
1+50	90.0	Top of spillway base
1+75	85.0	Top of spillway base
2+00	80.0	Top of spillway base

PROFILE ALONG & OF PRINCIPAL SPILLWAY


1" = 10' HORIZ. SCALE
1" = 10' VERT. SCALE

DEAD RIVER WATERSHED PROJECT
MULTIPLE PURPOSE DAM NO. 1
BERLIN, COOS COUNTY, NEW HAMPSHIRE
PRINCIPAL SPILLWAY
U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE





APPENDIX C
PHOTOGRAPHS



Anderson-Nichols & Co., Inc.		U. S. ARMY ENGINEER DIV. NEW ENGLAND	
CONCORD		CORPS OF ENGINEERS	
NEW HAMPSHIRE		WALTHAM, MASS.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
SITE NO. 1, DEAD RIVER DAM			
PHOTO INDEX			
JERICO LAKE		NEW HAMPSHIRE	
		SCALE: NOT TO SCALE	
		DATE: JULY, 1979	



Figure 2 - Looking north along the top of the dam embankment from the alignment break.



Figure 3 - Looking south along the top of the dam embankment from the alignment break.



Figure 4 - Looking along the top of the dam embankment from the south abutment.



Figure 5 - Looking toward south abutment at vehicle tracks near downstream toe of dam.




Figure 6 - Looking toward north abutment at vehicle tracks near downstream toe of dam.




Figure 7 - Vehicle tracks along downstream toe near principal spillway discharge channel.



Figure 8 - Looking north at principal spillway outlet pipe and toe drains.



Figure 9 - Closeup of principal spillway outlet pipe and toe drains.



Figure 10 - Looking at a spring 100 feet downstream
of the toe of dam near the south abutment.



Figure 11 - Looking southeast across emergency
spillway and at north end of dam
embankment.



Figure 12 - Looking at north end of dam embankment.



Figure 13 - Looking downstream from north bank of Jericho Lake at emergency spillway discharge channel.




Figure 14 - Looking north at principal spillway riser.




Figure 15 - Looking east at emergency spillway discharge channel.



Figure 16 - Looking south along crest of dike.



Figure 17 - Looking north along crest of dike from south abutment.

AD-A156 748

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
SITE NUMBER 1 DEAD RI. (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV JUL 79

3/3

UNCLASSIFIED

F/G 13/13


NL



END

FORMED

END



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A




Figure 18 - Looking upstream from the crest of the dam embankment at Jericho Lake.



Figure 19 - Looking downstream at the principal spillway discharge channel.

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS



**NATIONAL PROGRAM OF INSPECTION
OF NON-FED. DAMS**

SITE NO. 1 DEAD RIVER DAM
BERLIN, NEW HAMPSHIRE

REGIONAL VICINITY MAP

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS

ANDERSON-NICHOLS & CO., INC.

CONCORD, NH

MAP BASED ON, DEAD RIVER WATERSHED
PROJECT COVER SHEET MAP. U.S. DEPARTMENT
OF AGRICULTURE, SOIL CONSERVATION SERVICE.

JOB NO.

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALEDEAD RIVER SITE #1
(JERICHO BROOK)TEST FLOOD ANALYSISDRAINAGE AREA: 6.98 mi²STORAGE: ^NORMAL POOL (1352 msl) = 1239.6 ACRE-Feet^EMERGENCY SPWY CREST (1362 msl) = 2795.0 ACRE-Feet

SIZE CLASSIFICATION: INTERMEDIATE

HAZARD CLASSIFICATION: SIGNIFICANT

TEST FLOOD: PMF

DETERMINATION OF PROBABLE MAXIMUM FLOOD (PMF)(1) USE COE/NED PMF PEAK FLOW RATES GRAPH-W/ BASIN (SLOPE IS 685 FT/mi)
IN MOUNTAINOUS CATEGORY; FLOW RATE IS 2130 CSM

∴ PMF = 2130 CFS/SQ. MILE X 6.98 SQ. MILES = 13802 CFS

(2) FROM SOIL CONSERVATION SERVICE DESIGN DATA, A FREEBOARD
HYDROGRAPH HAS BEEN DEVELOPED FOR A 6-HOUR
STORM WITH 20.3 IN RAINFALL WHICH GENERATES 15.6 IN
RUNOFF. RESULTING PEAK INFLOW IS 16870 CFS

DUE TO GREATER DETAIL OF SCS STUDY, THE TEST FLOOD
WILL BE 16870 CFS. THIS WILL BE CONSIDERED THE PMF AS
THE PROJECT DESIGN FLOOD > RECOMMENDED SPILLWAY DESIGN FLOOD (PMF)
ROUTING OF AN INFLOW VALUE OF 16870 BY SCS RESULTED
IN AN OUTFLOW DISCHARGE OF 7975 CFS. THIS CORRESPONDS
TO AN ELEVATION OF 1370.9' MSL ON THE RATING CURVE
DEVELOPED FOR THE PRINCIPAL AND EMERGENCY SPILLWAYS
(SEE APPENDIX B). THE CREST THE DAM IS 1371.0' (MSL).

SUMMARY: THE TEST FLOOD IS THE MAXIMUM CAPACITY
OF THE PRINCIPAL AND EMERGENCY SPILLWAYS COMBINED
JUST BEFORE THE DAM EMBANKMENT IS OVERTOPPED.

NOTE: SEE PLATE TITLED, "FLOOD ROUTING - EMERGENCY
SPILLWAY HYDROGRAPH", APPENDIX "B" FOR
DAM RATING CURVE.

JOB NO. 3273-11SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

DEAD RIVER SITE #1

BREACH ANALYSIS

(JERICHO BROOK)

GENERAL DISCUSSION OF ANALYSIS

- (A) DETERMINE DOWNSTREAM HAZARD CLASSIFICATION, FAILURE OF THE DAM WILL BE CONSIDERED WITH THE WATER SURFACE ELEVATION OF UPSTREAM IMPOUNDMENT AT TWO DIFFERENT ELEVATIONS:

- 1) WATER SURFACE AT NORMAL POOL (RECREATION POOL) ELEVATION OF 1352' msl.
- 2) WATER SURFACE AT MAXIMUM POOL ELEVATION OR THE ELEVATION BEFORE FLOW OCCURS IN THE EMERGENCY SPILLWAY; CORRESPONDS TO CREST ELEVATION OF EMERGENCY SPILLWAY AT 1362' msl. (NOTE: DUE TO THE EXTREMELY LARGE CAPACITY OF THE EMERGENCY SPILLWAY, IT IS UNREALISTIC TO ASSUME MAXIMUM POOL ELEVATION AT TOP OF DAM EMBANKMENT - ELEVATION 1371' msl.)

IN BREACH ANALYSIS IT IS UNREALISTIC TO ASSUME THE BREACH WIDTH WOULD BE $(.4)(\text{DAM WIDTH}) = (.4)(3035) = 1214'$. THEREFORE, ASSUME BREACH WIDTH OF 100'.

- (B) METHODOLOGY EMPLOYED FOR THE CALCULATION OF BREACH DISCHARGES, USING FORMULA*:

$$Q_b = 8/27 W_b \sqrt{g} Y_o^{3/2}$$

WHERE: Q_b = BREACH DISCHARGE, CUBIC FEET PER SECOND
 W_b = BREACH WIDTH, FEET
 g = ACCELERATION DUE TO GRAVITY, 32.2 ft/sec^2
 Y_o = DIFFERENCE OF POOL ELEVATION FROM UPSTREAM INVERT, FEET

NOTE: UPSTREAM INVERT = 1329.3' msl.

* BREACH DISCHARGE FORMULA FROM "RULE OF THUMB" GUIDANCE FOR ESTIMATING DOWNSTREAM DAM FAILURE HYDROGRAPHS, COE, APRIL 1978.

JOB NO. 5273-11SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

1 (C) DESCRIPTION OF DOWNSTREAM REACHES
2 FROM SITE NO. 1, DEAD RIVER DAM
3
4

5 BASED UPON PHYSICAL CHARACTERISTICS THE WATER-
6 COURSE HAS TWO DISTINCTLY DIFFERENT REACHES BELOW
7 THE DAM.
8

9 (1) REACH 1 IS FROM THE DAM TO A POINT
10 APPROXIMATELY 0.25 DOWNSTREAM OF THE
11 JERICHO BROOK BY ROUTE 110, OR A TOTAL
12 DISTANCE OF APPROXIMATELY 1.5 MILES
13 DOWNSTREAM (EAST) OF THE DAM. THIS REACH
14 HAS A STEEP SLOPE, HEAVILY WOODED
15 OVBANKS, AND A ROCKY CHANNEL BOTTOM.
16 THERE ARE NO INHABITED STRUCTURES
17 LOCATED IN THIS REACH WHICH WOULD BE
18 AFFECTED BY THE BREACH OF THE DAM
19 (AT NORMAL POOL ELEVATION)

20 (2) REACH 2 IS FROM THE POINT (1.75 MI. \downarrow DAM) WHERE JERICHO
21 BROOK TURNS SHARPLY TO THE SOUTHEAST AND
22 BECOMES KNOWN AS DEAD RIVER (FIELD INSPECTION
23 HAS REVEALED THAT JERICHO BROOK AND DEAD
24 RIVER ARE THE SAME WATERCOURSE) TO THE
25 JUNCTION OF THE DEAD RIVER WITH THE
26 ANDROSCOGGIN RIVER 3.0⁺ MILES DOWNSTREAM. IN
27 THIS REACH THE DEAD RIVER HAS A WIDE
28 FLAT FLOODPLAIN WITH CONSIDERABLE STORAGE
29 AND HAS AN EXTREMELY FLAT CHANNEL
30 GRADIENT. ON THE SOUTH BOUNDARY OF
31 THE FLOODPLAIN IS THE GRAND TRUNK CANADIAN
32 NATIONAL RAILROAD, ROUTE 110 AND NUMEROUS
33 COMMERCIAL, INDUSTRIAL, AND RESIDENTIAL
34 BUILDINGS. IN ADDITION, FOR THE LAST 0.75
35 MILES OF ITS COURSE, THE DEAD RIVER FLOWS
36 THROUGH A HEAVILY URBANIZED AREA OF THE
37 CITY OF BERLIN INCLUDING THE CENTRAL BUSINESS
38 DISTRICT.
39

JOB NO. 3273-11SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

II. SUMMARY OF BREACH WITH RESERVOIR AT NORMAL OR RECREATION POOL LEVEL (1352.0 FT. MSL)

(A) BREACH DISCHARGE, Q_1 , DETERMINATION

$$Q_1 = 8/27 W_b \sqrt{g} Y_0^{3/2}$$

$$W_b = 100 \text{ FEET}$$

$$\sqrt{g} = 5.67 \text{ FEET}^{1/2} / \text{SECOND}$$

$$Y_0 = (1352.0 - 1329.3) \text{ FEET} = 22.7 \text{ FEET}$$

$$Q_1 = 8/27 \cdot 100 \cdot 5.67 (22.7)^{3/2} = 18169 \text{ CFS}$$

ASSUME MINIMAL ANTECEDENT DISCHARGE, Q_2

$$Q_2 = \text{DISCHARGE OVER PRINCIPAL SPILLWAY (TWO-STAGE RISER)} = 25 \text{ CFS (STAGE IS 2 FEET)}$$

$$\text{TOTAL BREACH DISCHARGE IS } 18169 + 25 = 18194 \approx 18200 \text{ CFS}$$

(B) DISCUSSION OF RESULT OF (A) BREACH AT NORMAL POOL UPON DOWNSTREAM REACHES, INCLUDES HISTORICAL FLOODING

(1) REACH 1 - NO IMPACT ON INHABITED STRUCTURES; THE RT. 110 CROSSING OF JERICHO BROOK COULD BE COMPLETELY INUNDATED WITH A DEPTH OF FLOODING OF APPROXIMATELY 7.0 FEET (SEE CALCULATIONS ON PAGES 10-15 OF 18)

(2) REACH 2 -

(a) THE FIRST STRUCTURE AFFECTED BY THE DAM'S BREACH IS LIKELY TO BE THE CONVERSE BUILDING (CLOSED) ON THE NORTH SIDE OF ROUTE 116 (BETWEEN ROUTE 116 AND THE RR TRACKS) 0.4 MILES BELOW OR SOUTHEAST OF ROUTE 116'S CROSSING OF JERICHO BROOK. ASSUMING:

(1) NO REACH STORAGE ABOVE CONVERSE BUILDING DUE TO STEEP SLOPE OF STREAM

(2) MINIMAL ANTECEDENT FLOW, 25 CFS

THE BREACH DISCHARGE CORRESPONDS TO A DEPTH OF FLOODING OF APPROXIMATELY 13.2 FEET ON THE STAGE-DISCHARGE RATING CURVE DEVELOPED FOR REPRESENTATIVE CROSS-SECTION AT CONVERSE BUILDING (SEE PAGES 6-9 OF 18 FOR CALCULATIONS). ONCE FLOW OVERTOPS THE RAILROAD TRACK EMBANKMENT, THE CONVERSE BUILDING COULD BE FLOODED; THE EMBANKMENT

JOB NO. 3273-11SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

1 IS APPROXIMATELY 100' ABOVE THE CHANNEL
2 INVERT AND THE CONVERSE BUILDING SILL IS
3 2 FEET BELOW THE TOP OF THE EMBANKMENT.
4 THEREFORE, A 3-5-FOOT DEPTH OF FLOODING
5 COULD BE EXPECTED AT THE CONVERSE
6 BUILDING, WITH THE DAM BEING BREACHED
7 (AT NORMAL POOL ELEVATION), CAUSING
8 CONSIDERABLE DAMAGE.

9 ⑥ FLOODING HISTORY — DOWNSTREAM IN REACH 2 IS
10 THE URBANIZED AREA OF BERLIN ALONG THE
11 DEAD RIVER WATERCOURSE, WHICH IS THE GREATER
12 DOWNSTREAM HAZARD AREA. THIS AREA HAS
13 EXPERIENCED EXCESSIVE FLOOD DAMAGES ON
14 AT LEAST THREE OCCASIONS IN THIS CENTURY.
15 MAJOR FLOODING EVENTS IN THIS AREA IN
16 1927, 1936, AND 1953 WERE RESPONSIBLE FOR
17 THE CONSTRUCTION OF THE MULTIPLE-PURPOSE
18 (FLOOD CONTROL AND RECREATION) STRUCTURES,
19 INCLUDING THE DAM AND THE DILE, AT SITE NO. 1,
20 DEAD RIVER WATERSHED. THE CONSIDERABLE
21 FLOODING PROBLEMS EXPERIENCED ON THE
22 DEAD RIVER IN THE CITY OF BERLIN ARE
23 DISCUSSED EXTENSIVELY IN THE WORK PLAN FOR
24 WATERSHED PROTECTION, FLOOD PREVENTION, AND
25 RECREATION, DEAD RIVER WATERSHED (JUNE 1965,
26 USDA SOIL CONSERVATION SERVICE, COOS COUNTY
27 SOIL CONSERVATION DISTRICT.

28 SEVERAL EXCERPTS FROM THIS PUBLICATION
29 INCLUDE:

30 "PAST RECORDS SHOW THAT FLOODING FROM THE
31 DEAD RIVER HAS CONSTANTLY PLAGUED THE CITIZENRY
32 OF BERLIN. ON A NUMBER OF OCCASIONS, FLOODS HAVE
33 DISRUPTED TRANSPORTATION AND CAUSED SERIOUS
34 DAMAGE TO RESIDENCES AND BUSINESS AND COMMERCIAL
35 ESTABLISHMENTS. LOCAL CITIZENS IN BERLIN FEEL
36 FORTUNATE THERE HAS NEVER BEEN LOSS OF LIFE IN
37 THE TREACHEROUS DEAD RIVER CHANNEL DURING PERIODS
38 OF FLOODING." PAGE 12

39 "THE PRINCIPAL FLOODWATER DAMAGES ARE TO
D-6

JOB NO. 303-11SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

INDUSTRIAL, COMMERCIAL, AND RESIDENTIAL PROPERTY AND ROADS AND BRIDGES IN BERLIN. IN THE FLOODPLAIN BETWEEN HILLSIDE AVE. AND MAIN ST. THERE ARE APPROXIMATELY 26 RESIDENTIAL AND 44 COMMERCIAL BUILDINGS SUBJECT TO FLOOD DAMAGE FROM LARGE FLOODS." PAGE 7

- (C) SUMMARY OF BREACH ANALYSIS ON REACH 2—THE 1936 AND 1953 FLOODS WITH DISCHARGES ESTIMATED TO HAVE BEEN 2000 CFS AND 1000 CFS AND RECURRENCE INTERVALS OF 100 AND 33 YEARS, RESPECTIVELY, CAUSED CONSIDERABLE DAMAGE TO BERLIN. BREACH OF THE DAM, WITH TERICH LAKE AT NORMAL OR RECREATION POOL, COULD RESULT IN A DISCHARGE OF 18200 CFS, WHICH WOULD OVERTOP THE MAIN ST. BRIDGE BY APPROXIMATELY 4 FEET (SEE CALCULATIONS ON PAGES 15-18 OF 18) CAUSING AN EXCESSIVE AMOUNT OF DAMAGE TO MAIN ST. STORES AND POSSIBLY CONSIDERABLE LOSS OF LIFE (10 OR MORE). THE DAM IS THEREFORE CONSIDERED TO BE OF HIGH HAZARD POTENTIAL DUE TO THIS LIKLIHOOD OF SEVERE FLOODING IN THE CITY OF BERLIN.

IV BREACH OF DAM WITH RESERVOIR AT CREST OF EMERGENCY SPILLWAY (1362.0 FT. MSL)

THOUGH ANALYSIS NOT REQUIRED TO DETERMINE HAZARD BASED ON NORMAL POOL BREACH COMPUTATIONS

A BREACH OF DAM AT EMERGENCY SPILLWAY CREST WOULD RESULT IN DISCHARGE OF 31415 CFS AND

$$Q_1 = 8/27 \cdot 100 (5.67) (1362 - 1329.3)^{3/2}$$

$$= 31415 \text{ CFS}$$

CONSIDERABLY GREATER DAMAGES IN THE CITY OF BERLIN.

NOTE: RECONSTRUCTION OF MAIN ST. BRIDGE TO PASS 100-YEAR EVENT (1200 CFS) WOULD NOT ELIMINATE SEVERE FLOODING WITH DISCHARGE OF 18200 CFS.

JOB NO. 3073-1QUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

$Q_2 = \text{DISCHARGE OVER PRINCIPAL SPILLWAY}$
 (TWO STAGE RISER) = 280 CFS (FROM
 SPILLWAY RATING CURVE)

$$Q_{\text{TOTAL}} = Q_1 + Q_2 = 31,415 + 250 = 31,665$$

3044 31,700 CFS

② REACH 2:

FROM SHT 9 OF 18 - FLOOD DEPTH = 17.0'

ABOVE CHANNEL INVERT AT
CONVERSE BLDG

∴ 7' OF FLOODING WOULD BE
 EXPECTED AT THE
 BLDG ITSELF

③ MAIN ST - 3-4 FT OF FLOODING COULD BE
 EXPECTED (SEE SHT 16A, 18 OF 18)

① REACH 1: 8.5 - 9.0' FLOOD DEPTH OVER
 BRIDGE (SEE SHT 12 AND 13 OF 18)

NOTE: SEE PLATE TITLED, "FLOOD ROUTING - EMERGENCY
 SPILLWAY HYDROGRAPH", APPENDIX "B"
 FOR DAM RATING CURVE.

JOB NO. 3273-11

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE



BREACH CALCULATIONS FOR:

A. IMPACT AT CONVERSE BLDG. ON RT. 110

SCALE: VERTICAL 1" = 4'
HORIZONTAL 1" = 80'

DEAD RIVER

DO STRIKE AND HAZARDOUS AREA
TYPICAL CROSS-SECTION
AT COMPOSITE BUILDING
ON ROUTE 110 (BEARING)

NOTE: ASSUME SIDEWALLS
(A_B AND F_G) ARE VERTICAL;
NET REDUCTION IS 1.0000

DEAD RIVER
CROSS SECTIONAL
GEOMETRY (AT
CONVERSE BLDG.)

JOB NO. 3213-11RES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
V SCALE

USING CROSS SECTIONAL GEOMETRY AND CHANNEL
SLOPE IN MANNING'S EQUATION, STAGE-DISCHARGE
RATING CURVE CAN BE DEVELOPED FOR THE
CROSS SECTION

$$Q = \frac{1.486}{n} A R^{2/3} S^{1/2}$$

WHERE: Q = DISCHARGE, (CFS)
A = CROSS-SECTIONAL AREA,
(FT.²)
R = HYDRAULIC RADIUS, (FT.)
S = SLOPE, (FT/FT)
n = FRICTION FACTOR

S (SLOPE) IS ESTIMATED TO BE 0.002 FROM
USGS QUAD SHEET

n (FRICTION FACTOR) IS 0.04; ALSO OVERBANKS ARE
ESSENTIALLY GRAVEL W/ LITTLE VEGETATION,
THEREFORE, USE 0.04 FOR COMPOSITE
n VALUE FOR CHANNEL AND OVERBANKS

STAGE (FT.)	AREA (FT. ²)			TOTAL AREA (FT. ²)	WP (FT.)	R (FT.)	S (FT./FT.)	n	Q* (CFS)
	CHAN.	LOB	ROB						
2	15	0	0	15	15	10	0.002	0.04	25
4	45	100	100	245	215	1.14			444
6	75	400	400	815	815	1.07			1520
8	105	800	800	1705	815	2.09			4631
10	135	1200	1200	2535	815	3.11			8977
12	165	1600	1600	3365	815	4.12			14367
14	195	2000	2000	4195	815	5.12			20705
16	225	2400	2400	5025	815	6.12			27934

* SEE DISCHARGE CALCULATIONS ON PAGE 8 OF 15



INVENTORY OF DAMS IN THE UNITED STATES

STATE	IDENTITY NUMBER	DIVISION	STATE	COUNTY	CITY	COUNTY	CITY	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE DAY MO YR
NH	473	NED	NH	019	02			SITE NO. 1, DEAD RIVER	4429.8	7151.8	12 JUL 79

POPULAR NAME	NAME OF IMPONDMENT
JERICHO LAKE DAM	JE-ICHO LAKE
REGION	NEAREST DOWNSTREAM CITY - TOWN - VILLAGE
01 08	BERLIN
	POPULATION
	4
	15256

TYPE OF DAM	YEAR COMPLETED	PURPOSES	IMPONDING CAPACITIES
REPO	1970	CR	MAXIMUM 4720
			MINIMUM 1240

01ST OWN FED R PRVPPED SCS A VER/DATE
NED N N : B

REMARKS
20-1970

D/S HAS	SPILLWAY	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (CU)	POWER CAPACITY	NAVIGATION LOCKS
1	2035 U 126	8202	333705	1200	1200

OWNER	ENGINEERING BY	CONSTRUCTION BY
CITY OF BERLIN	SOIL CONSERVATION SERVIC	ROGERS CONSTRUCTION COMP

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
SCS	SCS	SCS	SCS

INSPECTION BY	INSPECTION DATE DAY MO YR	AUTHORITY FOR INSPECTION
ANDERSON-NICHOLS AND COMPANY, INC	07 JUN 79	PL92-367

REMARKS
32-TWO-STAGE RISER TOTALING 26 FEET, EMERGENCY SPILLWAY 100 FEET WIDE

APPENDIX E

INFORMATION AS
CONTAINED IN THE NATIONAL
INVENTORY OF DAMS

STAGE, FT. ABOVE
2 E OF MAIN ST BRIDGE

EMERGENCY POOL
BREACH Q

NORMAL POOL
BREACH
DISCHARGE


4.1-FT DEPTH
(997.1 FT MSL)

993 msl 0 5 10 15 20 25 30
DISCHARGE (CFS) $\times 10^3$

ANDERSON-NICHOLS

VERNON	BOSTON	CONCORD
RATING CURVE, MAIN ST. BRIDGE BERLIN, DEAN RIVER		
DATE	SCALE:	JOB NO. 3273-11
		SHEET NO. 18 of 18

ELEV. (MSL)



Anderson-Nichols & Company, Inc.

Subject _____

Sheet No. 16A of 18
Date _____
Computed _____
Checked _____

JOB NO _____

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

FOR THE CASE OF BREACH AT EMERGENCY
SPILLWAY ELEVATION A RESULTING
FLOOD DEPTH BETWEEN 3 to 4 FEET
WOULD BE EXPECTED AT MAIN ST.
(SEE SHT 18 OF 18)

D-20

JOB NO. _____

 SQUARES
 1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

① DETERMINATION OF FLOOD DEPTHS AT MAIN ST BRIDGE, BERLIN
 BRIDGE SPECIFICATIONS: CONC BOX, 10'H X 13'W, WEIR COEFF = 2.6

(1) Q: AT TOP OF ROAD, EL. 993 MSL (INVERT 976.0 MSL)

② ORIFICE FLOW

HEADWATER DEPTH IN TERMS OF DEPTH (HW/D) = $17/10 = 1.7$

FROM BPR CHART Q = 2210 CFS (170 CFS/FT X 13 FT)
 (P. 15)

(2) Q: FLOOD DEPTH OF 5' OVER ROAD, EL. 998 MSL

② ORIFICE FLOW

HEADWATER DEPTH IN TERMS OF DEPTH (HW/D) = $22/10 = 2.2$

FROM BPR CHART Q = 2600 CFS (200 CFS/FT X 13 FT)

③ WEIR FLOW

$$Q = CLH^{3/2} = 2.6 (5/.017 + 5/.01) (5)^{3/2} = 23084 \text{ CFS}$$

TOTAL FLOW = ORIFICE AND WEIR FLOW = 2600 + 23084 CFS
 = 25684 CFS

(3) Q: FLOOD DEPTH OF 2.5' OVER ROAD, EL. 995.5 MSL

② ORIFICE FLOW

HEADWATER DEPTH IN TERMS OF DEPTH (HW/D) = $19.5/10 = 1.95$

FROM BPR CHART Q = 2470 CFS (190 CFS/FT X 13 FT)

③ WEIR FLOW

$$Q = CLH^{3/2} = 2.6 (2.5/.017 + 2.5/.01) (2.5)^{3/2} = 4081 \text{ CFS}$$

TOTAL FLOW = 2470 + 4081 = 6551 CFS

SUMMARY


FROM RATING CURVE, CONSTRUCTED FOR
 MAIN ST. BRIDGE, A FLOOD DEPTH OF
 APPROXIMATELY 4 FEET OVER THE ROAD (STAGE OF 21 FT,
 997 MSL) COULD RESULT IF THE DAM WERE
 BREACHED. THIS WOULD RESULT IN FIRST FLOOR
 FLOODING BY 2 to 3 FEET OF NUMEROUS STORES
 ON MAIN ST, AS IS INDICATED BY ELEVATIONS (1ST FLOOR)
 SHOWN ON SEWER DRAWINGS, CAUSING EXCESSIVE DAMAGE.

CHART FOR DETERMINING ORIFICE FLOW FOR:

15 of 18

- (1) ROUTE 110 BRIDGE
- (2) MAIN ST. BRIDGE

CHART I



HEADWATER DEPTH
FOR BOX CULVERTS
WITH INLET CONTROL

HYDRAULIC CHART FOR BOX CULVERTS

HYDRAULIC CHART
FOR
BOX CULVERTS
Route 110
MAIN Street

D-18

5'- DIAMETER CMP ON
DIRT RD. (UNNAMED)
WITH PROJECTING ENTRANCE

CHART

EXAMPLE

D = 36 inches (3.0 feet)
Q = 66 cfs

	$\frac{HW}{D}$	HW (feet)
(1)	1.0	3.0
(2)	2.1	6.3
(3)	2.2	6.6

*D in feet

OVERTOPPING DISCHARGE

EXAMPLE

DIAMETER OF CULVERT (D) IN INCHES

DISCHARGE (Q) IN CFS

HEADWATER DEPTH IN DIAMETERS (HW/D)

HEADWATER DEPTH IN FEET

SCALE

	ENTRANCE TYPE
(1)	Headwall
(2)	Designed to conform to slope
(3)	Projecting


To use scale (2) or (3) project horizontally to scale (1), then use straight line through D and Q scales, or reverse as illustrated

HEADWATER DEPTH FOR C. M. PIPE CULVERTS WITH INLET CONTROL

RT. 110 STAGE-DISCHARGE

13 OF 18

(BRIDGE OVER JERICHO BROOK)



STAGE (FT. ABOVE ROADWAY)

D-16

JOB NO. 3273-11ANALYSIS
(W/ BREACH OF DAM)SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

1 STAGE-DISCHARGE RELATIONSHIP (SEE PAGE 13)
2 INDICATES THAT THE BREACH DISCHARGE
3 (18200 CFS) WOULD RESULT ROUGHLY A
4 7.0-FOOT DEPTH OF FLOODING OVER THE
5 ROUTE 110 ROADWAY AT THE BRIDGE OVER
6 JERICHO BROOK.
7

8 BREACH DISCHARGE (31,700 CFS) WOULD RESULT
9 IN A 8.5 TO 9.0 FOOT DEPTH OF FLOODING
10 OVER RT 110 ROADWAY AT THE BRIDGE OVER
11 JERICHO BROOK.
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39

JOB NO. 3273-11

ANALYSIS
RT 110SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALERT 110
CONT. $Q = CLH^{3/2}$ WHERE: Q = WEIR DISCHARGE (CFS) L = WEIR SECTION LENGTH (FT) H = AVERAGE DEPTH OF FLOODING, IS
HALF THE FLOOD DEPTH AT BRIDGE &TRIAL #1 : FLOOD DEPTH $\Delta E = 2'$

WEIR FLOW (LEFT ROADWAY) =

$$2.6(2/.04)(1)^{3/2} = 130 \text{ CFS}$$

WEIR FLOW (RIGHT ROADWAY) =

$$2.6(2/.01)(1)^{3/2} = 520 \text{ CFS}$$

ORIFICE FLOW ($HW/D = 9+6/9 = 1.7$) IS $140 \text{ CFS/FT} \times 22 \text{ FT} = 3080 \text{ CFS}$

TOTAL FLOW w/ 2' FLOOD DEPTH IS COMBINED

$$\text{PRESSURE AND WEIR FLOW} = 3080 + 130 + 520 = 3730 \text{ CFS}$$

TRIAL #2 : FLOOD DEPTH $\Delta E = 4'$

WEIR FLOW (LEFT) =

$$2.6(4/.04)(2)^{3/2} = 735 \text{ CFS}$$

WEIR FLOW (RIGHT) =

$$2.6(4/.01)(2)^{3/2} = 2942 \text{ CFS}$$

ORIFICE FLOW ($HW/D = 9+8/9 = 1.9$) IS $155 \text{ CFS/FT} \times 22 \text{ FT} = 3410 \text{ CFS}$

$$\text{TOTAL FLOW IS } 3410 + 735 + 2942 = 7087 \text{ CFS}$$

TRIAL #3 : FLOOD DEPTH $\Delta E = 6'$

WEIR FLOW (LEFT) =

$$2.6(6/.04)(3)^{3/2} = 2026 \text{ CFS}$$

WEIR FLOW (RIGHT)

$$2.6(6/.01)(3)^{3/2} = 8106 \text{ CFS}$$

ORIFICE FLOW ($HW/D = 9+10/9 = 2.1$) IS $165 \text{ CFS/FT} \times 22 \text{ FT} = 3630 \text{ CFS}$

$$\text{TOTAL FLOW IS } 3630 + 2026 + 8106 = 13762 \text{ CFS}$$

TRIAL #4 : FLOOD DEPTH $\Delta E = 8'$

WEIR FLOW (LEFT) =

$$2.6(8/.04)(4)^{3/2} = 4160 \text{ CFS}$$

WEIR FLOW (RIGHT) =

$$2.6(8/.01)(4)^{3/2} = 16640 \text{ CFS}$$

ORIFICE FLOW ($HW/D = 9+12/9 = 2.3$) IS $180 \text{ CFS/FT} \times 22 \text{ FT} = 3960$

$$\text{TOTAL FLOW IS } 3960 + 4160 + 16640 = 24760 \text{ CFS}$$

JOB NO. 3273-11

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

ANALYSIS OF DOWNSTREAM BRIDGES AND CULVERTS

- ① 5-FOOT DIAMETER CORRUGATED METAL PIPE
ON DIRT RD. .5mi DOWNSTREAM OF DAM.

TOP OF ROAD (CENTERLINE OF CULVERT) IS
2 FEET ABOVE LOW CHORD. THEREFORE,
HEADWATER, IN TERMS OF DIAMETER (HW/D),
IS 1.4 BEFORE STRUCTURE IS OVERTOPPED.
CAPACITY OF CULVERT, BEFORE OVERTOPPING,
IS 170 CFS (SEE PAGE 14 OF 18). BREACH
DISCHARGE WOULD PROBABLY WASH OUT THE LOW
EARTHEN EMBANKMENT

- ② 9'X22' CONCRETE BOX CULVERT ON ROUTE 110

TOP OF ROAD (CENTERLINE OF BRIDGE) IS
APPROXIMATELY 4 FEET ABOVE LOW CHORD.
THEREFORE, HEADWATER IN TERMS OF DEPTH
BEFORE ROADWAY IS OVERTOPPED IS $1.4 = (9+4)/9$.
CAPACITY OF STRUCTURE BEFORE ROADWAY IS
OVERTOPPED IS ROUGHLY 2640 CFS (22' WIDE
TIMES 120 CFS PER FOOT OF WIDTH); SEE PAGE 15.

TO DETERMINE IMPACT OF BREACH, MUST
DEVELOP STAGE-DISCHARGE CURVE FOR
STRUCTURE TO GET DEPTH OF FLOODING.
REQUIRES ESTIMATION OF WEIR SHAPE OF
THE ROADWAY; MUST ESTIMATE EFFECTIVE
FLOW LIMIT ON RIGHT (SOUTHEAST) ROADWAY
OF RT. 110 AS IT SLOPES CONTINUOUSLY DOWNHILL
TO CITY OF BERLIN. AN ESTIMATE OF 0.01 SLOPE
FOR THE RIGHT ROADWAY WILL SUFFICE FOR
ESTIMATING WEIR FLOW; LEFT ROADWAY
HAS A 0.04 SLOPE.


CALCULATE WEIR FLOW; ASSUME WEIR $C = 2.6$, AND
TRY DIFFERENT FLOOD DEPTHS TO GET RATING CURVE

USE STANDARD WEIR EQUATION:

$$Q = CLH^{3/2}$$

3-13-11

RATING CURVE (DEAD RIVER) ^{9 CF 18} CROSS-SECTION AT CONVERSE BUILDING ^{RH 10CS}



D-12

JOB NO. 3273-11SQUARES
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39

$$\text{STAGE} = 2' : \quad Q = \frac{1.486 (15) (1)^{2/3} (0.002)^{1/2}}{0.04} = 25 \text{ CFS}$$

$$\text{STAGE} = 4' : \quad Q = \frac{1.486 (245) (1.19)^{2/3} (0.002)^{1/2}}{0.04} = 444 \text{ CFS}$$

$$\text{STAGE} = 6' : \quad Q = \frac{1.486 (875) (1.07)^{2/3} (0.002)^{1/2}}{0.04} = 1520 \text{ CFS}$$

$$\text{STAGE} = 8' : \quad Q = \frac{1.486 (1705) (2.09)^{2/3} (0.002)^{1/2}}{0.04} = 4631 \text{ CFS}$$

$$\text{STAGE} = 10' : \quad Q = \frac{1.486 (2535) (3.11)^{2/3} (0.002)^{1/2}}{0.04} = 8977 \text{ CFS}$$

$$\text{STAGE} = 12' : \quad Q = \frac{1.486 (3365) (4.12)^{2/3} (0.002)^{1/2}}{0.04} = 14367 \text{ CFS}$$

$$\text{STAGE} = 14' : \quad Q = \frac{1.486 (4195) (5.12)^{2/3} (0.002)^{1/2}}{0.04} = 20705 \text{ CFS}$$

$$\text{STAGE} = 16' : \quad Q = \frac{1.486 (5025) (6.12)^{2/3} (0.002)^{1/2}}{0.04} = 27934 \text{ CFS}$$

END

FILMED

8-85

DTIC